

PSP Detailed Report

Federal Motor Carrier Safety Administration

Driver Information													
Last Name	First Name	License #	State										
HERRERAARMENTEROS	AMAURY	H666000764520	FL										
HERRERA	AMAURY	H666000764520	FL										
Crash Activity													
Crash Summary (Crashes listed represent a driver's involvement in FMCSA-reportable crashes, without any determination as to responsibility.)													
# of Crashes:		0	# of Crashes with Fatalities:		0	# of Crashes with Injuries:		0	# of Towaways:		0		
# Not preventable:		0	# of Fatalities:		0	# of Injuries:		0	# of Hazmat Releases:		0		
Crash Details (Crashes listed represent a driver's involvement in FMCSA-reportable crashes, without any determination as to responsibility.)													
	Date	DOT #	Carrier Name	Driver Name	Driver Lic	State	Driver DOB	Rpt St	Report Number	Location	# Fatalities	# of Injuries	
Inspection Activity (3 year history from MCMIS snapshot date)													
Inspection Summary													
Driver Summary				Vehicle Summary				Hazmat Summary					
Driver Inspections:		3		Vehicle Inspections:		1		Hazmat Inspections				0	
Driver Out-of-service Inspections:		0		Vehicle Out-of-service Inspections:		0		Hazmat Out-of-service Inspections:				0	
Driver Out-of-service Rate:		0%		Vehicle Out-of-service Rate:		0%		Hazmat Out-of-service Rate:				0%	
Inspection Details													
Carrier Info				Driver Info				Inspection Info					
	Date	DOT #	Carrier Name	Driver Name	Driver Lic	State	Driver DOB	Rpt St	Report Number	Hazmat Insp	Insp Level	# of Viol	
1	03/31/2022	3080754	MARKO POLO EXPRESS LLC	HERRERA ARMENTEROS, AMAURY	H666000764520	FL	12/12/1976	MS	1008011037	N	2	0	

Report executed at: 12/19/2024 12:05:36 PM

MCMIS snapshot date: 11/29/2024

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.

For an explanation of FMCSA-reportable crashes see: <https://www.psp.fmcsa.dot.gov/psp/?redirectUrl=FAQ>

2	09/03/2022	2588617	TOP LINE TRUCKING INC	HERRERA ARMENTEROS, AMAURY	H666000764520	FL	12/12/1976	AR	766C000249	N	3	0
3	04/11/2023	2819873	ALLAN TRUCKING LLC	HERRERA ARMENTEROS, AMAURY	H666000764520	FL	12/12/1976	FL	3414007158	N	3	3
<div>Vehicle Violation: 392.2 Violation of Local Laws - Explain NON-OOS</div> <div>Vehicle Violation: 395.22(h)(1) Driver failing to maintain ELD user's manual NON-OOS</div> <div>Vehicle Violation: 395.22(h)(3) Driver failed to maintain instruction sheet for ELD malfunction reporting requirements NON-OOS</div>												
Violation Summary												
Violation #	Description								# of Violations	# of Out-of-service Violations		
392.2	Violation of Local Laws - Explain								1	0		
395.22(h)(1)	Driver failing to maintain ELD user's manual								1	0		
395.22(h)(3)	Driver failed to maintain instruction sheet for ELD malfunction reporting requirements								1	0		

The summary counts and rates only include violations that were attributable to HERRERAARMENTEROS, AMAURY.

Report executed at: 12/19/2024 12:05:36 PM

MCMIS snapshot date: 11/29/2024

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.

For an explanation of FMCSA-reportable crashes see: <https://www.psp.fmcsa.dot.gov/psp/?redirectUrl=FAQ>