

PSP Detailed Report

Federal Motor Carrier Safety Administration

Driver Information															
Last Name		First Name		License #			State								
ACOSTA		PETER		49228250			TX								
Crash Activity															
Crash Summary (Crashes listed represent a driver's involvement in FMCSA-reportable crashes, without any determination as to responsibility.)															
# of Crashes:		0		# of Crashes with Fatalities:		0		# of Crashes with Injuries:		0		# of Towaways:		0	
# Not preventable:		0		# of Fatalities:		0		# of Injuries:		0		# of Hazmat Releases:		0	
Crash Details (Crashes listed represent a driver's involvement in FMCSA-reportable crashes, without any determination as to responsibility.)															
	Date	DOT #	Carrier Name	Driver Name	Driver Lic	State	Driver DOB	Rpt St	Report Number	Location	# Fatalities	# of Injuries			
Inspection Activity (3 year history from MCMIS snapshot date)															
Inspection Summary															
Driver Summary				Vehicle Summary				Hazmat Summary							
Driver Inspections:		2		Vehicle Inspections:		1		Hazmat Inspections				0			
Driver Out-of-service Inspections:		1		Vehicle Out-of-service Inspections:		1		Hazmat Out-of-service Inspections:				0			
Driver Out-of-service Rate:		50%		Vehicle Out-of-service Rate:		100%		Hazmat Out-of-service Rate:				0%			

Report executed at: 7/14/2023 2:10:54 PM

MCMIS snapshot date: 06/30/2023

For an explanation of FMCSA-reportable crashes see: <https://www.psp.fmcsa.dot.gov/psp/?redirectUrl=FAQ>

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.

Inspection Details												
Carrier Info				Driver Info				Inspection Info				
	Date	DOT #	Carrier Name	Driver Name	Driver Lic	State	Driver DOB	Rpt St	Report Number	Hazmat Insp	Insp Level	# of Viol
1	06/01/2023	3027671	MARSHA ENTERPRISE LLC	ACOSTA, PETER	49228250	TX	03/04/1991	TX	V231031143	N	2	7
Vehicle Violation: 393.209(d) Steering system components worn, welded, or missing OOS Vehicle Violation: 393.55(d)(3) No or Defective ABS Malfunction Indicator for towed vehicles on vehicles manufactured after February 2001 NON-OOS Vehicle Violation: 393.78 Windshield wipers inoperative/defective NON-OOS Vehicle Violation: 393.9(a) Inoperable head lamps NON-OOS Vehicle Violation: 393.9(a) Inoperable Required Lamp NON-OOS Driver Violation: 395.8(e)(1) False Record of Duty Status - Improper use of Personal Conveyance Exception OOS Vehicle Violation: 396.3(a)(1) Brake system pressure loss OOS												
2	06/15/2023	3027671	MARSHA ENTERPRISE LLC	ACOSTA, PETER JACK (co-driver)	49228250	TX	03/04/1991	AZ	0Y3F001726	N	3	1
Driver Violation: 392.2 Lane Restriction violation NON-OOS - This violation does NOT apply to ACOSTA, PETER JACK.												
Violation Summary												
Violation #	Description								# of Violations	# of Out-of-service Violations		
393.209(d)	Steering system components worn, welded, or missing								1	1		
393.55(d)(3)	No or Defective ABS Malfunction Indicator for towed vehicles on vehicles manufactured after February 2001								1	0		
393.78	Windshield wipers inoperative/defective								1	0		
393.9(a)	Inoperable head lamps								2	0		
395.8(e)(1)	False Record of Duty Status - Improper use of Personal Conveyance Exception								1	1		
396.3(a)(1)	Brake system pressure loss								1	1		

The summary counts and rates only include violations that were attributable to ACOSTA, PETER.

Report executed at: 7/14/2023 2:10:54 PM

MCMIS snapshot date: 06/30/2023

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.

For an explanation of FMCSA-reportable crashes see: <https://www.psp.fmcsa.dot.gov/psp/?redirectUrl=FAQ>