

DOGGETT - LITTLE ROCK
11700 VALENTINE RD,
NORTH LITTLE ROCK, AR 72117
(501) 955-3200
Fax-(501) 955-3208



Arkansas :

North Little Rock, Springdale, Van Buren

Page 1 of 2

SERVICE ORDER

*** E-CUS - DO NOT MAIL ***

Bill-To Customer CASHLR

Owner CASHLR

SERVICE ORDER

ROYAL 3 INC

ROYAL 3 INC

R301152473

11700 VALENTINE ROAD
NORTH LITTLE ROCK, AR 72117

11700 VALENTINE ROAD
NORTH LITTLE ROCK, AR 72117

P.O. Number / Auth#

V.I.N **3AKJHHDR1MSMZ5508**

Customer Fleet ID 726

Pinnacle / Fleetpack#

Year 2021

Invoice Date

Vehicle Unit ID # 564863

Make FTL

Model PT126SLP

Date In	Mileage	Billing	Terms	Writer	Reviewer	Date In Service	Phone#
02/14/2025	492,417	SR	CASH	300453	300124	3/22/21	(630) 485-7370

Sold Operations

Job#1 E101038

Monthly Service Special

Claim Number

Condition **COOLANT LEAK**

Cause

Correction

LOCATED UNIT AT END OF WORKLINE. FOUND DRIVELINE IS INSTALLED. PULLED UNIT INTO SHOP, CONNECTED UNIT TO DL8 PRO AND PRINTED FAULT CODES. FOUND ACTIVE 111/4 COOLANT LEVEL CIRCUIT FAILED LOW OR OPEN. RAISED HOOD, COOLANT LEVEL SENSOR IS DISCONNECTED. FOUND WATERPUMP FAILED AND IS LEAKING COOLANT. UNIT NEEDS WATERPUMP REPLACED AND COOLANT SYSTEM FILLED.

LOCATED UNIT ON WORK LINE AND PULLED INTO SHOP. CHOCKED WHEELS AND OPENED HOOD. DRAINED COOLANT OUT OF SYSTEM. TOOK CAC INTAKE OFF. TOOK BELT LOOSE. FOUND BELT MELTED FROM WATER PUMP BEARINGS GOING OUT. TOOK BOLTS OUT OF WATER PUMP ALSO FOUND COOLANT LEVEL SENSOR BROKEN AS WELL. REPLACED BELT AND SENSOR. TOOK OLD WATER PUMP OUT AND INSTALLED NEW ONE. PLUGGED IN AND BOLTED IN. TORQED BOLTS TO SPEC AND INSTALLED BELT ONTO WATER PUMP. INSTALLED CAC INLET BACK ON. PUT NEW COOLANT INTO SYSTEM. STARTED UNIT AND FOUND NO CODES AND ALL PULLY WORKING PROPERLY. TOOK TO WASH BAY AND STEAM CLEANED. PARKED ON DONE LINE.

****WATER PUMP, PART ONLY, COVERED BY WARRANTY****

Qty	Item	Description	Price	Extended
		LABOR TO PERFORM REPAIRS		979.90
1	301F/06-96622-000	SENSOR-COOLANT LEVEL,POTTED	37.31	37.31
1	301F/DDE A4729933496	POLY V BELT, ACCESSORY, VARIAB	54.28	54.28
6	301D/OWI 23519397	ANTFRZ-DDC PWRCOL ELC OAT1 GAL	14.27	85.62
1	TECH	TECHNOLOGY FEE	35.00	35.00
Total Labor		979.90	Total Parts/Other	212.21
			Operation Total	1,192.11

DOGGETT - LITTLE ROCK
11700 VALENTINE RD,
NORTH LITTLE ROCK, AR 72117
(501) 955-3200
Fax-(501) 955-3208



Arkansas :

North Little Rock, Springdale, Van Buren

Page 2 of 2

SERVICE ORDER

*** E-CUS - DO NOT MAIL ***

Bill-To Customer CASHLR

ROYAL 3 INC

11700 VALENTINE ROAD
NORTH LITTLE ROCK, AR 72117

Owner CASHLR

ROYAL 3 INC

11700 VALENTINE ROAD
NORTH LITTLE ROCK, AR 72117

SERVICE ORDER

R301152473

P.O. Number / Auth#

Pinnacle / Fleetpack#

Vehicle Unit ID # 564863

V.I.N **3AKJHHDR1MSMZ5508**

Customer Fleet ID 726

Year 2021

Make FTL

Model PT126SLP

Invoice Date

Date In	Mileage	Billing	Terms	Writer	Reviewer	Date In Service	Phone#
02/14/2025	492,417	SR	CASH	300453	300124	3/22/21	(630) 485-7370

Sold Operations (Cont.)

Job#2 A101000

Generic Repair

Claim Number

Condition WATER PUMP, PART ONLY, COVERED BY WARRANTY

NORTH LITTLE ROCK, AR 72117
501-955-3200

TERMS AND CONDITIONS OF SALE AND DISCLAIMER OF WARRANTIES

- Disclaimer for Labor. Seller disclaims all warranties, either express or implied, for labor performed in the repair of Owner's vehicle; however, notwithstanding the foregoing, Seller shall warranty its labor for a period of ninety (90) days next following the date of such repair.
- Disclaimer for Parts and Equipment. Parts and Equipment are covered only by warranties, if any, made by the manufacturer. Seller disclaims all warranties, express, implied, or statutory, including without limitation any implied warranty of merchantability or fitness for a particular purpose, and Seller neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of the parts.
- Parts Return Policy. Special order parts may require a deposit and are not returnable. All returnable parts must be in marketable condition and are subject to the manufacturer's warranty conditions and a fifteen percent (15%) restocking charge. All claims for returned parts must be accompanied by the purchase invoice. No refund after 30 days. Seller is not responsible for labor on parts not installed by Seller's shop.
- Terms. Strictly cash unless arrangements made.
- Mechanic's Lien Notice. Failure to pay invoice places any vehicles worked on subject to provisions of Title 18, Chapter 45 Arkansas Code.

Parts	177.21
Labor:	979.90
Sublet:	0.00
Freight:	0.00
Miscellaneous:	35.00
SubTotal:	1,192.11
Shop Environmental Fee:	175.98
Taxes:	130.00
Total:	1,498.09

Customer Signature: _____

Print: _____