



TOTAL TRUCK CARE

LOVE'S
0476 Davenport, IA TRUCKCARE
8255 Northwest Blvd Davenport , IA 52806
(563) 386-3466

WORK ORDER # : 4006353944
WORK ORDER DATE : 03/28/2025
CLOSE DATE :
SERVICE TYPE : In Shop

SHIP TO : Royal3 Inc(6109240)
6850 W 63Rd Street
Chicago , IL 60638

SOLD TO : Royal3 Inc(6109240)
6850 W 63Rd Street
Chicago , IL 60638

BILL TO : CHECK CUSTOMER(3602102)
10601 N PENNSYLVANIA AVE
OKLAHOMA CITY , OK 73120-4108

<input checked="" type="checkbox"/> TRACTOR #	VIN #	YEAR	MAKE	MILEAGE	PLATE#/STATE	ENGINE
712	1FUJHHDR7MLMP3394	2021	FREIGHTLINER	674148	P1070310/IL	DETROIT
<input type="checkbox"/> TRAILER #	VIN #	YEAR	MAKE	HUBOMETER	PLATE#/STATE	REEFER #
APU# / HOURS	ADDITIONAL UNIT	START TIME	END TIME	DRIVER NAME	DRIVER CONTACT	
		03/28/2025 090336	03/28/2025 105344	neal	9082668907	
Authorization #	AUTHORIZATION NAME	PAY TYPE	PO#	PO ISSUED BY	DR#	
	JOSH	Check				

COMPLAINT :
Complaint #1 Tractor/Other- Brake System- c/a brake.\\RMUNN\\2025-03-28\\07:40`
6305661257\\RMUNN\\2025-03-28\\07:41`
6305660552 josh \\RMUNN\\2025-03-28\\08:55`
maintenance@royal3inc.com\\RMUNN\\2025-03-28\\10:59`

DESCRIPTION	MECHANIC	UOM	QUANTITY	LIST PRICE	PRODUCT	LABOR	EXTENSION
diag brake issues	Jamie Stockton	EA	1.00	142.99	0.00	142.99	142.99
Check Fuses	Jamie Stockton	EA	0.50	143.00	0.00	143.00	71.50
Shop Supplies							10.72
						Parts	0.00
						Labor	214.49
						Tires	0.00
						Fees	10.72
						Customer Discount*	0.00
						Site Discount	0.00
						Tax	15.02
						Total	240.23

* Customer Discount may include coupons, MLR rewards, and applicable discounts

SERVICE COMMENTS: Unit came in for when applying brake it feels like the truck "nose dives". Checked all brake thickness and all are well within specs and so are the strokes. Checked the front leaf springs and seen no fractures or cracks. Found front shocks are starting to leak and recommending front shock replacement and cab shock replacement as the shocks are worn. Removed the shock and pressed down, the shock did not extend back up. Found the rear wheel seals are starting to leaks and the cabin air filter door and cabin filter is missing. Advised to company and company would like to take care back at their shop. \\RBRINGOLF\\03/28/2025\\11:28` Driver also stated the microwave did not work. Reset the inverter as was tripped. Also replaced a fuse in the fuse panel as it was blown\\RBRINGOLF\\03/28/2025\\11:29`

*****This is an Estimate*****



TOTAL TRUCK CARE

LOVE'S
0476 Davenport, IA TRUCKCARE
8255 Northwest Blvd Davenport , IA 52806
(563) 386-3466

WORK ORDER # : 4006353944
WORK ORDER DATE : 03/28/2025
CLOSE DATE :
SERVICE TYPE : In Shop

SHIP TO : Royal3 Inc(6109240)
6850 W 63Rd Street
Chicago , IL 60638

SOLD TO : Royal3 Inc(6109240)
6850 W 63Rd Street
Chicago , IL 60638

BILL TO : CHECK CUSTOMER(3602102)
10601 N PENNSYLVANIA AVE
OKLAHOMA CITY , OK 73120-4108

Driver Signature :

DID YOU LOVE IT?

Please take a short survey about your experience today:
Visit Loves.com/survey

Or Scan the QR Code below:

