

TA TRUCK SERVICE

Priced Work Order Work Order #018 296552

102 NW 4TH ST. I-70 AND HWY 23 Page 1
PO BOX 787
CONCORDIA, MO 64020- (660) 463-2001
SAMANTHA E WILLIS 660-463-2001

PRICED WORK ORDER
For Purchase Order APPROVAL ONLY
For Questions or Concerns:

MORE: BAYS. EXPERTISE. SOLUTIONS.
THANK YOU AND STAY SAFE!
Service Dept Manager:

Company Name CR ENGLAND & SONS INC (2474840)		Driver's Name DRIVER CELL# 7868658573		ID	License		# P 018 296552
Address 1325 S 4700 W		SIMON TRIP#		PO #	Authorized by		DR#
City SALT LAKE CITY		State UT		Zip 84104		Tax Exempt #	
Tractor # 727		Year 21		Make/Model FTL CASCADIA		License # P1095157 IL	
Trailer # W94925		Year 21		Make/Model GREAT DANE		License # 451977Z ME	
Work Requested UNIT SVCD: TRAILER		SIMON REQUESTS: LACED WITH LP22.5 GY RECAP. REPLACE THE LR MUDFLAP AND BRACKET ON THE TRAILER.		C/A LFI TRAILER TIRE IS FLAT SPOTTED AND NEEDS REP			

SERVICE	PLU #	PART NUMBER	DESCRIPTION	UOM	REG. PRICE	PRICE	QTY	EXTENDED AMOUNT
NTN	717 317	013427, SAP #0001606613	295/75R22.5 B123 TRAILER RECAP	EA	0.00	0.00	1.00	see NTA invoice
NTN	717 602	013427 OLD DOT# 2CBT3UA1514	NEW DOT# CRX4623 LFI	EA	0.00	0.00	1.00	see NTA invoice
TT	994 699	YY892379, SAP #0001608216	295/75R22.5 CASING	EA	12.00	12.00	1.00	12.00
		YY892416OLD DOT#	NEW DOT#	EA			1.00	see NTA invoice
		SAP # 0001605120	DRIVER REFUSED TIRE					
		YY197100	NAB INSIDE TIRE MOUNT					
		USE FOR BRIDGESTONE NATIONAL ACCOUNT TIRE MOUNT - INSIDE WHEEL						
		CHECK NUT TORQUE BETWEEN 50-100 MILES OF OPERATION AFTER WHEEL						
		SERVICE AS RECOMMENDED BY ATA-TMC, NWRA, AND TRUCK OE MANUFACTURERS.						
	998 002	777777, SAP #0001606876	STANDARD SERVICE LABOR	HR			.80	
	998 011	SAP # 0001606883	INSIDE TIRE ADDL	HR			.20	
		R&R MUD FLAP					1.00	42.99
		R&R MUD FLAP SIMPLE INSTALL.	ADDITIONAL WORK BILLED HOURLY LABOR.					
		LABOR ONLY						
	998 002	777777, SAP #0001606876	STANDARD SERVICE LABOR	HR			.35	
SL	409 021	IMXGT-2430PSB, SAP #000112269	24 X 30 BLACK PLASTIC MUDFLAP	EA	25.56	25.56	1.00	25.56
SL	409 028	BTS B516P, SAP #0001602601	MFBK 16 MUD FLAP BOLT ASSORT	EA	6.25	6.25	1.00	6.25
SL	587 699	0, SAP #0001602048	CUSTOMER REFUSED VALVE STEM	EA	0.00	0.00	1.00	0.00
SL	410 014	4405-2866, SAP #0001122702	MUDFLAP ANGLE IRON SLOTTED	EA	22.34	22.34	1.00	22.34
SL	998 004	LABOR, SAP #0001606877	RPR MUDFLAP BRACKET	HR	138.99	138.99	.50	69.50

Please come again! Your feedback matters. Tell us about your visit at www.tafeedback.com.

Customer agrees the only service work being requested by Customer from TA at this time is the work specifically listed in this work order. Customer understands TA offers additional services upon request; however, Customer declines any additional services not specifically listed on this work order. Customer hereby releases TA from any claims or liability related to service work, conditions and/or issues on Customer's vehicle/trailer which is not specifically listed in the work order, including, but not limited to any inspection, evaluation or recommendation related to tires, component parts or other items not specifically identified in this work order.

Have wheel torque checked after
50-100 miles of operation
as recommended by TMC, TIA
and OE manufacturers
Wheels torqued to 475 ft lbs

Customer Initials SL
TSA Initials BW

Parts :	0.00	New Tires :	0.00	Total :	0.00	Non-taxable :	0.00	ENV/WST Tax:	0.00
Labor :	0.00	Used Tires :	0.00	Discount :	0.00	Taxable :	0.00	TOTAL ► \$	0.00
Oil :	0.00	Trade-In :	0.00	Net :	0.00	Tax :	0.00	* * PRICED WORK ORDER * *	

Trade-In	0.00	Net	0.00	Tax
TORQUED LUGS TO 475FT LBS ON LEFT FRONT TRAILER AXLE. PLEASE RETORQUE LUGS AFTER 50-100MILES. DRIVE				
ER AND AUSTIN WITNESSED TORQUE. CLEANED/OILED LUGS STUDS, PILOT PADS, AND WHEELS. AIRED TIRE TO 100PS				
I. WE KEEP OLD TIRE. FOUND LEFT MUDFLAP BRACKET WAS MISSING. WELDED A NEW ONE ON AND REPLACED THE MI				
SSING MUDFLAP WITH NEW HARDWARE.				
THANKS.... TYLER				

★ ★ ★ DO NOT PAY ★ ★ ★

* * * * PRICED WORK ORDER - FOR PURCHASE ORDER ISSUANCE ONLY * * * *

In the event that you, the customer, authorize commencement but do not authorize completion of a repair or service, a charge will be imposed for disassembly, reassembly or partially completed work. Such charges will be directly related to the actual amount of labor or parts involved in the inspection, repair or service.

*** NO SIGNATURE ON FILE ***

LIMITED WARRANTY

WHAT IS WARRANTED AND FOR HOW LONG? Subject to the terms hereof, including the exclusions and other limitations listed below, parts purchased at any TravelCenters of America or Petro Stopping Centers location (each, a "TA or Petro Location") will be, at our sole option, repaired or replaced without additional charge if they fail due to a defect for a period of one (1) year from the date of purchase. Service work (labor) performed at a TA or Petro Location is warranted to be free from defect in workmanship for 120 days from the date of service. If you purchase a used tire at a TA or Petro Location and the tire fails due to a defect within seven (7) days of purchase, we will, at our sole option, repair or replace the used tire. These limited warranties do not apply to products or vehicles used for racing or off-road purposes, or to damage caused by abuse, accident or neglect. New tires are warranted separately by the manufacturer and not included in this warranty.

EXCLUSIONS: Consumable materials and parts (such as antifreeze, oil, filters) are not included in this warranty.

FEES AND TAXES NOT INCLUDED. Fees, including, without limitation, waste disposal fees, are not included in this warranty and must be paid by you. In addition, Florida law requires us to collect a \$1.00 fee for each new tire sold and \$1.50 for each new or remanufactured battery sold in the state. This fee is not covered by the warranty and must be paid by you. Some states and/or local governments may require a tax on a portion of warranty repairs. Where applicable law allows, the tax must be paid by you.

ADDITIONAL EXCLUSIONS FOR REFRIGERATION SYSTEMS: TA and Petro's scope of services for refrigeration system tractors and trailers covers only external component repairs and specifically excludes the refrigeration system itself. Maintenance items that will not be serviced include, but are not limited to, any internal component of the refrigeration system, the freon filter, the upper belts that require fan replacement and condensers. TA and Petro specifically disclaim any responsibility for the refrigeration system, loss of use of the refrigeration system, damage, loss or spoliation of the contents of the refrigerated trailer, lost time, inconvenience, loss of use of the tractor/trailer or any other incidental or consequential damage or loss.

HOW CAN A CLAIM BE MADE UNDER THE LIMITED WARRANTY? No warranty will be honored without strict adherence to the following procedure: You must notify us immediately of any part or service failure by visiting the TA or Petro Location that sold the warranted parts and/or performed the warranted service work or by calling us at 1-800-632-9240. If the original TA or Petro Location is not convenient for you, please telephone us at 1-800-632-9240 and we will direct you to an alternative TA or Petro Location. The owner/driver is responsible for presenting the vehicle to the TA or Petro Location as specified above. **The original invoice from the TA or Petro Location at which the part was purchased and/or the work was performed MUST be presented in order to get the benefit of the limited warranty.**

WARRANTY LIMITED. THE OBLIGATIONS UNDERTAKEN IN THESE LIMITED WARRANTIES ARE OFFERED ONLY ON THE ABOVE ITEMS AND UNDER THE EXPRESS CONDITIONS SET FORTH, AND MAY NOT BE ENLARGED OR ALTERED BY ANYONE. NO WARRANTIES ARE MADE, EITHER EXPRESS OR IMPLIED, AS TO ANY MATTER WHATSOEVER, INCLUDING WITHOUT LIMITATION, THE CONDITION OF THE PARTS, MERCHANTABILITY OR FITNESS FOR ANY PARTICULAR PURPOSE, EXCEPT AS SPECIFICALLY PROVIDED HEREIN OR AS OTHERWISE PROVIDED BY LAW.

NO COVERAGE FOR INCIDENTAL AND CONSEQUENTIAL DAMAGES. THE ONLY REMEDIES THE PURCHASER HAS IN CONNECTION WITH THE PURCHASE OF PRODUCTS OR SERVICES FROM TA AND PETRO ARE THOSE SET FORTH ABOVE. IN NO EVENT WILL TA OPERATING LLC, ANY COMPANY AFFILIATED WITH TA OPERATING LLC, OR ANY FRANCHISEE OF TA OPERATING LLC (OR ITS AFFILIATES) BE LIABLE FOR BUSINESS INTERRUPTIONS, LOSS OF SALES AND/OR PROFITS, RENTAL OR SUBSTITUTE EQUIPMENT, COSTS OF DELAY OR FOR ANY OTHER SPECIAL, INCIDENTAL OR CONSEQUENTIAL LOSSES, COSTS OR DAMAGES. PURCHASER ASSUMES ALL LIABILITY FOR ALL PERSONAL INJURY AND PROPERTY DAMAGE RESULTING FROM THE HANDLING, POSSESSION OR USE OF THE PRODUCTS BY THE PURCHASER.

CONSUMER RIGHTS: This limited warranty gives you specific legal rights; you may also have other rights which vary from state to state.

YOUR SATISFACTION is important to us. If for any reason you are not satisfied with the service you receive, contact the Truck Services manager of the TA or Petro Location where service was provided. If the problem has not been handled to your complete satisfaction, please call 1-800-632-9240.

GIVEN BY: TA Operating LLC, d/b/a TravelCenters of America and Petro Stopping Centers, 24601 Center Ridge Road, Suite 200, Westlake, Ohio 44145.