



TOTAL TRUCK CARE

LOVE'S
0481 Deer Park, TX TRUCKCARE
7005 Hwy 225 Deer Park, TX 77536
(281) 479-3430

WORK ORDER #: 4000842214
WORK ORDER DATE: 06/05/2023
CLOSE DATE:
SERVICE TYPE: In Shop

SHIP TO: England Carrier Services(3408710)
PO BOX 27566
Salt Lake City, UT 84127-0566
(801) 974-3520

SOLD TO: England Carrier Services(34087
PO BOX 27566
Salt Lake City, UT 84127-0566

BILL TO: ENGLAND CARRIER SERVICES (STK/
4701 W 2100 S
SALT LAKE CITY, UT 84120
ACCOUNT #: 1268394


<input checked="" type="checkbox"/> TRACTOR #	VIN #	YEAR	MAKE	MILEAGE	PLATE#/STATE	ENGINE
820	1M1AN4GY6LM017942	2020	MACK	123456	P1151470/IL	MACK
<input type="checkbox"/> TRAILER #	VIN #	YEAR	MAKE	HUBOMETER	PLATE#/STATE	REEFER #
APU# / HOURS	ADDITIONAL UNIT	START TIME	END TIME	DRIVER NAME	DRIVER CONTACT	
				Huventino Hernandez	7867440598	
Authorization #	AUTHORIZATION NAME	PAY TYPE	PO#	PO ISSUED BY	DR#	
086875/Amy	Amy Christensen	NAB Michelin			DR0062134	

COMPLAINT:
I authorize 1- 66205 Michelin:XLEZ Size:275/80R22.5 Ply:16 due to reginal tire will not work for the long haul this carrier does :) All labor included :) Please correct all VIN and Plate info :) Any questions call Amy @ 801.656.2885 Thank you Sunshine!

DESCRIPTION	MECHANIC	UOM	QUANTITY	LIST PRICE	PRODUCT	LABOR	EXTENSION
Tire Replacement		EA	1.00	0.00	0.00	0.00	0.00
M66205 275/80R22.5H X LINE ENERGY Z		EA	1.00	0.00	0.00	0.00	0.00
FET							0.00
VALVE STEM STANDARD		EA	1.00	0.00	0.00	0.00	0.00
TIRE DISPOSAL		EA	1.00	0.00	0.00	0.00	0.00
DISMOUNT AND MOUNT MED TRUCK TIRE		EA	1.00	0.00	0.00	0.00	0.00

Unit :TRACTOR Old Brand :BRIDGESTONE Position :LS Failure Reason :Puncture too Large Old Tread Depth :2 Old DOT# :1B6EJ014X1423 New DOT# :1B6EJ014X1423

Parts	0.00
Labor	0.00
Tires	0.00
Fees	0.00
Customer Discount*	0.00
Site Discount	0.00



TOTAL TRUCK CARE

LOVE'S
0481 Deer Park, TX TRUCKCARE
7005 Hwy 225 Deer Park, TX 77536
(281) 479-3430

WORK ORDER #: 4000842214
WORK ORDER DATE: 06/05/2023
CLOSE DATE:
SERVICE TYPE: In Shop

SHIP TO: England Carrier Services(3408710)
PO BOX 27566
Salt Lake City, UT 84127-0566
(801) 974-3520

SOLD TO: England Carrier Services(34087
PO BOX 27566
Salt Lake City, UT 84127-0566

BILL TO: ENGLAND CARRIER SERVICES (STK/
4701 W 2100 S
SALT LAKE CITY, UT 84120
ACCOUNT #: 1268394

Tax	0.00
-----	------

Total	0.00
-------	------

* Customer Discount may include coupons, MLR rewards, and applicable discounts

SERVICE COMMENTS: C: RF HAD PUNCTURE C: ROAD HAZARD C: REPLACED RF \DSAVAGE\06/05/2023\18:43

*****This is an Estimate*****

Driver Signature:

#820

Southern Tire Mart
at **Pilot FLYING**

INVOICE #: 2290005627

STMP MEBANE, NC
1352 TROLLINGWOOD HAWFIELDS RD

PAGE: 1

MEBANE, NC 27302

984/983-0161

CUSTOMER: RIKI TRANSPORTATION INC
0110229 8225 LECLAIRE AVE
BURBANK, IL 60459

SALESMAN: 22901 VEHICLE: 2020 MAC TRUCK
LICENSE: P1151470 IL MILEAGE: 370142
COLOR: RED ENGINE: PACCAR
VIN: 1M1AN4GY6LM017942
Fleet ID 820
INVOICE DATE: 06/11/23 DUE: 06/11/23

PRODUCT	MECHANIC	QUANTITY	PRICE	F.E.T.	EXTENSION
MANDATORY CONCERN: LRI DRIVE TIRE FLAT INFO CAUSE: NAIL IN TIRE CURE: PERFORMED ALL RIST PROCEDURES TO TIA SPEC, TORQUED LUGN UTS TO 475 FT LBS, DRIVER VERIFIED TORQUE, REPAIRED TIRE AND AIRED TO 105 PSI. FOUND NO LEAKS.					
TRUCK TIRE FLAT REPAIR LABOR 100	1113	1	54.99		54.99
TMC recommends lug nuts be rechecked between 50/100 miles after service. TMC recommends lug nuts be torqued to 450-500 FT LBS. Driver Witnessed Torque. Driver Signature: _____					
TIRE PATCH 200		1	3.99		3.99
SERVICE SUPPLIES 240			5.50		5.50
				MERCHANDISE:	9.49
				LABOR:	54.99
				SALES TAX:	4.35
				INVOICE TOTAL:	68.83
*****THIS IS A REPRINTED INVOICE*****					
CHECK					68.83
				Check Verification #:	50604
Thank you, for visiting Southern Tire Mart #229. We appreciate your business!					

PLEASE REMIT To:

Dept. 6412
P.O. Box 11407
Birmingham, AL 35246-6412

PRINTED NAME/CUSTOMER SIGNATURE: