



925 STAGECOACH DRIVE  
ROCK SPRINGS, WY 82901  
P: (307) 382-4646  
F: (307) 382-4645  
Dealer Code: DKGD



BILL TO  
BRZ TRANSPORTATION LLC - 69062  
8225 LECLAIRE AVE  
BURBANK IL 60459  
P: (630) 485-7370  
F:

DELIVER TO  
BRZ TRANSPORTATION LLC - 69062  
8225 LECLAIRE AVE  
BURBANK IL 60459  
P: (630) 485-7370  
F:

### SERVICE ORDER: R303008978

| DATE ARRIVED       |      | DATE INVOICE | SALES TYPE        | ADVISOR         | TERMS        | CUSTOMER REFERENCE |                    |          |
|--------------------|------|--------------|-------------------|-----------------|--------------|--------------------|--------------------|----------|
| 1/9/2025 9:36:19AM |      |              | SRET              | LINSEYL         | CASH         |                    |                    |          |
| YEAR               | MAKE | MODEL        | VIN               | CUSTOMER UNIT # | ENGINE HOURS | IN SERVICE         | Component Serial # | ODOMETER |
| 2023               | FTL  | PT126SLP     | 3AKJHHDR6PSUA1588 | 604             | 0            | 10/21/2022         | 472912S0970779     | 345066   |

#### Sold Operations

#### JOB #1 EA EXPRESS ASSESSMENT

COMPLAINT CAUSE CORRECTION  
EXPRESS ASSESSMENT \*\* WATER PUMP FAILURE, BROKEN BELTS  
WATER PUMP  
TOWED UNIT FROM REAR INTO BAY 10. INSPECT WATER PUMP, FOUND WATER PUMP MELTED AND BELT DAMAGED, DRAINED COOLANT, REMOVED CAC COLD PIPE, DISCONNECT ELECTRICAL FROM WATER PUMP, REMOVED WATER PUMP, INSPECT COOLANT MODULE FOR DAMAGE, NONE FOUND, WATER PUMP WILL NEED REPLACED. INSTALLED NEW WATER PUMP AND DRIVE BELT, FILLED SYSTEM TO SPEC, RAN ENGINE TO OPERATING TEMP AND CHECKED FOR LEAKS=OK.

#### PARTIAL TECH NOTE ON JOB 2

| QTY | ITEM                       | DESCRIPTION                 | UNIT PRICE | EXTD PRICE |
|-----|----------------------------|-----------------------------|------------|------------|
|     | LABOR 20                   | ENGINE COOLING SYSTEM       |            |            |
|     | LABOR 41                   | DRIVELINE                   |            |            |
|     | LABOR EA                   | EXPRESS ASSESSMENT          |            |            |
| 1   | 303D/DDE EA4722002701      | LU COOLANT PUMP             |            |            |
| 1   | 303D/DDE EA4722002701-CORE | LU COOLANT PUMP CORE        |            |            |
| 6   | 303D/OWI 23519397          | GAL/JUG DDC ELC CONCENTRATE |            |            |
| 1   | 303D/DDE A4729933496       | SERP BELT - 8PK2691         |            |            |
| -1  | 303D/DDE EA4722002701-CORE | LU COOLANT PUMP CORE        |            |            |

#### JOB #2 41 DRIVELINE

COMPLAINT CAUSE CORRECTION  
DRIVE LINE \*\* TOWED: CHECK/INSTALL DRIVELINE AND AXELS  
DRIVELINE  
WALKED OUT TO UNIT, FOUND DRIVE LINE IS INSTALLED. VERIFIED TORQUED TO 135FTLBS.

| QTY | ITEM       | DESCRIPTION                                | UNIT PRICE | EXTD PRICE |
|-----|------------|--------------------------------------------|------------|------------|
| 1   | J3603      | FIVE STAR TOWING                           | 1,181.25   | 1,181.25   |
| -1  | Deductible | Application of Customer Deductible Payment | 550.00     | -550.00    |

Prepay: \$-550.00 Parts: \$0 Labor: \$0 Misc: \$0 Sublet: \$1,181.25 \$631.25

#### JOB #3 QC QUALITY INSPECTIONS

COMPLAINT QUALITY INSPECTIONS \*\*



SERVICE ORDER: R303008978

ESTIMATE: E303008177

**Sold Operations (Cont.)**

CAUSE QUALITY INSPECTION  
CORRECTION VERIFIED WATER PUMP BOLTS TORQUED TO SPEC, AND BELT ROUTED PROPERLY, ALL FLUIDS FULL. REPAIR IS COMPLETE.

| QTY                                                     | ITEM     | DESCRIPTION        | UNIT PRICE | EXTD PRICE |
|---------------------------------------------------------|----------|--------------------|------------|------------|
|                                                         | LABOR QC | QUALITY INSPECTION |            | 0.00       |
| Prepay: \$0 Parts: \$0 Labor: \$0 Misc: \$0 Sublet: \$0 |          |                    |            | \$0.00     |

**JOB #4 41 DRIVELINE**

COMPLAINT Deductible payment from Customer  
CAUSE EXTENDED TOW COVERAGE  
CORRECTION EXTENDED TOW COVERAGE COVERS UP TO \$550 OF THE TOW BILL.

| QTY | ITEM       | DESCRIPTION                 | UNIT PRICE | EXTD PRICE |
|-----|------------|-----------------------------|------------|------------|
| 1   | Deductible | Customer Deductible Payment |            |            |

**Factory Warranty.** We do not guarantee that any repairs you request will be covered by your manufacturer warranty. We do not issue your warranty; we are merely a factory-authorized warranty repair facility. We will do our best to determine your warranty coverage prior to the repair, and we will submit to the manufacturer repairs that we believe qualify for manufacturer warranty coverage. But the manufacturer may deny your claim. In the event the manufacturer denies your claim, you are fully responsible for all charges incurred.

**Workmanship Warranty Disclaimer.** We warranty labor and/or workmanship for 30 days following the completion of repair. No claim will be honored past the stated 30-day period. We expressly disclaim all other warranties, either express or implied, including any implied warranties of merchantability or fitness for a particular purpose. We do not assume nor authorize any other person to assume for it any liability in connection with the sale of the parts or repair. In no event are we liable to you or any third-party for any indirect, special, punitive, incidental, or consequential damage connected to, or arising out of, our work on your vehicle whether the damage arises from breach of contract or tort or whether we have been previously advised of the possibility of such damage. If we are found liable to you for any damage, our damages are limited to the replacement of parts and/or the labor cost of repeating the service.

**Acts of God.** We are not responsible for damage to your vehicle due to acts of God that occur while your vehicle is in our possession. Acts of God include but are not limited to wind, hail, fire, and flood.

**Payment.** All charges for repairs, including labor and materials, are due at or before the time we tender the vehicle to you. We may tender the vehicle to you through a phone call, mail, email, or any other means of communication that shows, upon payment, we are returning the vehicle to your custody. If any charges remain unpaid for 30 days past due, we may hire attorneys to help with collection, and you are responsible for paying those attorney's fees. Further, we will charge you interest monthly on all past due amounts at a rate of 16% per annum.

**Storage Charge.** If you do not take custody of the vehicle within three days after we tender the vehicle to you, we will charge you a storage fee of \$25.00 per day.

**Credit Card Surcharge.** Our credit card processor will impose a surcharge on credit cards that will not be greater than our cost of acceptance. This surcharge will not reflect on this invoice but will reflect on credit card receipt.

|                 |                 |
|-----------------|-----------------|
| LABOR           | \$0.00          |
| PARTS           | \$0.00          |
| MISC            | \$-550.00       |
| SUBLET          | \$1,181.25      |
| PREPAY          | \$-550.00       |
| <b>SUBTOTAL</b> | <b>\$631.25</b> |
| SHOP SUPPLIES   | \$0.00          |
| MISC SUPPLIES   | \$0.00          |
| TAX             | \$70.88         |
| <b>TOTAL</b>    | <b>\$702.13</b> |

Please Remit Payment to:  
FLOYD'S TRUCK CENTER  
PO BOX 1628  
GILLETTE, WY 82717

Scan to leave a Google Review



AUTHORIZED BY \_\_\_\_\_ DATE \_\_\_\_\_