



INVOICE

BILL TO:
TONE BROKERAGE
55375SAVAGE RD.
MARCELLUS, MI 49067

INVOICE DATE: 01/27/2025
INVOICE #: R74254
TERMS: NET 30
DUE DATE: 02/27/2025

DATE	CUSTOMER REF#	ORIGIN - DESTINATION	QUANTITY	RATE	AMOUNT
01/23/2025		425 East Heber Road, Heber, CA 92249 - 58288 Ventura Drive, Elkhart, IN 46517			
		Freight Income	1	\$4,100.00	\$4,100.00

TOTAL
\$4,100.00

PLEASE NOTE

The right to payment under this invoice has been assigned to Compass payment Solutions LLC (CFS) and all payments hereunder are to be directed to the assignee at the address noted below.

Remittances to other than CFS do not constitute payment of this invoice. CFS must be given notification of any claims, agreements or merchandise returns which would affect the payment of all or part of this Invoice on the due date.

COMPASS FUNDING SOLUTIONS LLC

P.O.BOX 205154

DALLAS, TX 75320-5154

Tel: 844-899-8092

Load #L-01060

Please have driver
call for dispatch.
(269) 646-9072

Tone Brokerage
15390 Dutch Settlement St
Marcellus, MI 49067
MC# 598306

LOAD CONFIRMATION AND PAYMENT AGREEMENT
PLEASE SIGN ASAP

Heber, CA → Elkhart, IN

Carrier: ROYAL3 INC (630) 485-7370
MC#: 944686
Dispatch: Phil (630) 485-7370
phil@royal3inc.com
Driver: Fernando (786) 868-7851
Pay Day: 30

Broker: Jeff Tone
Email: dispatch@tonestrucking.com

Load Details

Equipment Type: Power Only
Value of Load: \$100,000.00

Rate Details

Detail	Rate
Flat Rate	\$4,100.00
Total:	\$4,100.00

Total Items

Product	Handling	Pkg	Weight
Trailer	1		35,000
Total:	1	0	35,000

Origin

Date: 01/23/2025 Thursday
Time: 07:00 - 15:00
From: Heber Yard
425 East Heber Road
Heber, CA 92249

Contact:
Phone:
Cell:

Destination


Date: 01/26/2025 Sunday
Time: 07:00 - 15:00
From: Truck Group
58288 Ventura Drive
Elkhart, IN 46517

Contact:
Phone:
Cell:

Carrier Rate Confirmation Terms

Unless otherwise noted, Carrier is responsible for making sure equipment/commodity is loaded correctly by shipper and within legal dimensions and weight for specific trailer type being used. If the shipper refuses to load your trailer due to the condition of your equipment, then we will not pay a Truck Order Not Used. Once carrier leaves the shipper's yard, they assume any and all responsibility for damage incurred from improperly loaded machinery. In the event you do not fulfill the terms of this agreement, you will be subject to any and all fines associated with the service failure beginning with \$250 per day that you are late. We will not provide fuel advances OR quick pays for loads 1000 miles or further. THIS RATE CONFIRMATION IS NOT AN ACCEPTABLE FORM OF A PROOF OF DELIVERY AND DOING SO COULD RESULT IN A FINE.

Signature



Broker Signature

Jeff Tone

IP:192.82.16.68

1/22/2025 2:02:56 PM -05:00



Confirmation Signature

Phil

IP:50.76.79.115

1/22/2025 1:04:26 PM -06:00

A POD & Invoice Request will be emailed to you upon the delivery of this load. Please use the link sent to submit POD(s), Invoice and any other relative document via our carrier portal link.



MOBILE MAINTENANCE & TRAILER FLEET SERVICE

Trailer PM & Inspection List

Unit # 3650 Hub

Vin # 5NPAU52W791138 Manufacturer UNION Year 18
Lic # 495088 State/Prov TX

OK/Defect

- All defects should be recorded on a work order. Miscellaneous and additional notes may be recorded on the back of this form.
- ☒ ☐ Front
- ☒ ☐ 1. Pre-Inspection walk around, Registration/Decals/7-Way/Gladhands (Damage, Missing, Operation)
- ☒ ☐ 2. Front Panels/Bulkhead/Lights (Damage, Seals, Operation)
- ☒ ☐ Landing Gear/Coupler
- ☒ ☐ 3. Landing Legs/Brackets/Braces (Operation, Mounting, Damage) - Lubricate
- ☒ ☐ 4. Coupler/Kingpin (Damage, Wear)
- ☒ ☐ Left Side (LS)
- ☒ ☐ 5. LS Slider Rails/Pins/Release Mechanism/Decals (Damage, Engagement, Missing, Operation)
- ☒ ☐ 6. LS Panels/Rails/Crossmembers/Winch/Lights/Reflectors/Wires (Damage, Seals, Fasteners, Operation, Repairs)
- ☒ ☐ 7. LS Tires and Wheels (Clearance, Tread, Air Pressure, Nut Tightness, Damage, Hubcap/Lubricant condition and levels) - Inflate
- ☒ ☐ Rear
- ☒ ☐ 8. Rear Bumper/Frame/License Plate/Flaps/Brackets/Pintle Hook (Damage, Missing, Welds, Wear, Operation)
- ☒ ☐ 9. Rear Lights - STT/Rear Markers/License Plate/Side Markers (Damage, Operation)
- ☒ ☐ 10. Rear Doors/Hardware (Damage, Seals, Binding, Tension, Fasteners)
- ☐ ☐ Inside
- ☐ ☐ 11. Inside Inspection (Roll Door Mechanisms, Plyliner, Schuff-liner, Floor Damage, Roof Damage)
- ☒ ☐ Right Side (RS)
- ☒ ☐ 12. RS Tires and Wheels (Clearance, Tread, Air Pressure, Nut Tightness, Damage, Hubcap/Lubricant condition and levels) - Inflate
- ☒ ☐ 13. RS Slider Rails/Pins (Damage, Engagement)
- ☒ ☐ 14. RS Panels/Rails/Crossmembers/Winch/Lights/Reflectors/Wires (Damage, Seals, Fasteners, Operation, Repairs)
- ☐ ☐ Underneath
- ☐ ☐ 15. Spring Suspension - Springs/U-bolts/Hangers/Equalizers/Radius Rods (Damage, Looseness, Wear)
- ☐ ☐ 16. Air Ride Suspension - Bags/Arms/Brackets/Shocks/Bushings/Valves/Lines (Damage Looseness, Height, Wear)
- ☒ ☐ 17. Brakes - Linings/Drums/S-cams/Shocks/Clevis Pins/Chambers/ABS (Adjustment, Mounting, Damage, Wear) - Lubricate
- ☒ ☐ 18. Slider Assembly/Axles (Damage, Welds)
- ☒ ☐ 19. Air System - Air Lines/Reservoirs/Valves (Mounting, Operation, Rubbing, Dry Rot)
- ☒ ☐ Finishing up
- ☒ ☐ 20. Check Applied Brake Stroke/Air leaks - If Needed Check Trailer Top / Engagement of Anti-Dock Walk
- ☒ ☐ 21. Converter Gear 5th Wheel (Fasteners, Shear Blocks, Proper Latching)
- ☒ ☐ 22. Converter Gear Drawbar and Drawbar Eye (Fasteners, Welds, Safety Chains, Cables, Hooks and Hinges)
- ☒ ☐ 23. Misc. Equipment (Lift-gate, Roller Floor, Extension System, Curtain, etc.)
- ☒ ☐ 24. Annual inspection decal applied to trailer, "Defect" check box indicates a "Failed to pass" status.
- ☒ ☐ 25. PM or BIT inspection only.

Tire Tread Depth (Measured in 1/32nds)

Axle	Position	Tread Depth	Type/Brand	PSI	Tire Size	Position	Tread Depth	Type/Brand	PSI
1	L.O.	7	Mich	65	295/70R22.5	R.O.	7	Mich	65
2	L.O.	15	Mich	65		R.O.	15	Mich	65
3	L.O.					R.O.			
	L.I.					R.I.			
	L.I.					R.I.			

Record lowest brake lining thickness (Measured in 1/32nds)

Axle 1 16 32

Axle 2 17 32

Axle 3 32

Inspector Enriquez, Enche

printed name and employee number

signature

Date

12/30/24

Inspecting Company

Name

Address

street

Tel #

State

zip code

As Required, Customer Name

Remarks/Parts Used

Left Par used O/K

Signature

KSW MOBILE MAINTENANCE & TRAILER FLEET SERVICE
35 E. CRUICKSHANK RD. EL CENTRO CA. 92243

This vehicle was licensed in accordance with the requirements contained in Appendix G to subchapter 5 of C.T. rule 49 C.F.R. part 396 on the above listed date. The inspector is qualified per these requirements.

(49 CFR 39.7-2)

10/11/23
D8853795

REPORT OF CONDITION (For Detailed Information on Inspection Procedures see FWCIS Part 366, Appendix A)

РЕЗЮМЕ

QUALIFIED INSPECTOR'S SIGNATURE

DATE 10/11/23

AN INDELIBLE INK MARKER IS RECOMMENDED FOR USE WHEN FILLING OUT THE LABEL. INDELIBLE INK IS PERMANENT AND WILL NOT WASH OFF, BUT MAY FADE DUE TO EXPOSURE TO ULTRAVIOLET LIGHT OVER TIME. CAREFUL DISCRETION IS ADVISED REGARDING APPLICATION OF LABEL TO AN AREA NOT EXPOSED TO EXCESSIVE ULTRAVIOLET LIGHT AND/OR ELEMENTS AND IT IS RECOMMENDED THAT THE READABILITY OF THE LABEL BE CHECKED PERIODICALLY.

Copyright © 2021 J. J. Keller & Associates, Inc.
Neenah, WI - JJKeller.com - (800) 368-5899
Printed in the USA

1935
(Feb. 1935)

Escaneado con CamScanner