## **PSP Detailed Report**

**Federal Motor Carrier Safety Administration** 

						Driv	ver Inf	forma	ation										
Last Name First Name					Name License #					Sta				State					
PESTANALLANES ARMANDO					P235000832500					FL									
Crash Activity																			
Crash	Summary (C	rashes liste	d represent a	driver's invo	lvemer	nt in FMCSA-reportable	e crasi	hes, v	vithout any	/ deter	rminat	ion as t	o respo	onsibili	ity.)				
# of Crashes: 0						# of Crashes with Fatalities:				# of Crashes with Injurie					0	# of Towaways			rays: 0
		# Not	preventable:	0	# of Fataliti			0			# of Injuries: 0 # of Hazmat F					mat Relea	ises: 0		
Crash Details (Crashes listed represent a driver's involvement in FMCSA-reportable crashes, without any determination as to responsibility.)										•									
	Date	DOT#	<u> </u>	er Name		Driver Name		Driver Lic State								er Location #Fatalities		lities #	of Injuries
Date DOT# Carrie				2,110, 1,4,110					2		Apr or Rope		Localio		.		,		
	Inspection Activity (3 year history from MCMIS snapshot date)																		
Inspec	tion Summa	ry																	
	Driver Summary Vehicle Summary Hazmat Summary																		
Driver Inspections:					3	3 Vehicle Inspections:					3 Hazmat Inspections 0								
Driver Out-of-service Inspections:					0	0 Vehicle Out-of-service Inspections:					0 Hazmat Out-of-service Inspections:								0
Driver Out-of-service Rate:					0%	% Vehicle Out-of-service Rate:					0% Hazmat Out-of-service Rate: 0%								
Inspec	tion Details																		
Carrier Info Driver Info										- In	nspect	ion Info							
	Date	DOT#	Carri	r Name		Driver Name			Driver Lic		State	Driver		Rpt St	Report	Number	Hazmat	Insp Lev	el # of
															·		Insp		Viol
1	11/22/2020	3121089		(ING OF PALM CH LLC	PESTANA LLANES, ARMANDO			P235000832500		00	FL	07/10/1	1983	FL	23220	02700	N	2	2
Vehicle Violation: 390.21T(b) Carrier name and/or USDOT Number not displayed as require						required		NON-C	oos							•			
Vehicle Violation: 393.11				nicle Violation: 393.11 No or defective lighting devices or reflective material as required							NON-OOS								

Report executed at: 11/20/2023 8:55:50 AM

MCMIS snapshot date: 10/27/2023

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.

2	11/22/2020	2792170	M & D AUTO TRANSPORT PESTANA LLANES, ARMANDO INC		P235000832500	FL	07/10/1983	FL	2322002701	N	2	0
							<u> </u>	<u> </u>		<u> </u>		
3	01/17/2023	3121089	A & L TRUCKING OF PALM BEACH LLC	PESTANA LLANES, ARMANDO	P235000832500	FL	07/10/1983	FL	3198013007	N	2	2
	Vehicle Violation: 392.2 State vehicle registration or License Plate violation NON-OOS											
	Vehicle Violation: 392.2 State vehicle registration or License Plate violation NON-OOS											
Violation Summary												
Violation # Description									# of Violations		# of Out-of-service Violations	
390.21	Γ(b)	Carrier name	and/or USDOT Number not disp		1		0					
393.11		No or defective	ve lighting devices or reflective m		1		0					
392.2 State vehicle registration or License Plate violation										2		0

The summary counts and rates only include violations that were attributable to PESTANALLANES, ARMANDO.

Report executed at: 11/20/2023 8:55:50 AM

MCMIS snapshot date: 10/27/2023

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.