

PSP Detailed Report

Federal Motor Carrier Safety Administration

Driver Information															
Last Name		First Name		License #			State								
DIAZCARABALLO		VICTOR		D261870893740			FL								
DIAZ		VICTOR		47739421			TX								
Crash Activity															
Crash Summary (Crashes listed represent a driver's involvement in FMCSA-reportable crashes, without any determination as to responsibility.)															
# of Crashes:		1		# of Crashes with Fatalities:		0		# of Crashes with Injuries:		1		# of Towaways:		1	
# Not preventable:		0		# of Fatalities:		0		# of Injuries:		3		# of Hazmat Releases:		0	
Crash Details (Crashes listed represent a driver's involvement in FMCSA-reportable crashes, without any determination as to responsibility.)															
	Date	DOT #	Carrier Name	Driver Name	Driver Lic	State	Driver DOB	Rpt St	Report Number	Location	# Fatalities	# of Injuries			
1	12/04/2020			DIAZ-CARABALLO, VICTOR	D261870893740	FL	10/14/1989	FL	FL8944219200	I4 E (SR 400)	0	3			
Inspection Activity (3 year history from MCMIS snapshot date)															
Inspection Summary															
Driver Summary				Vehicle Summary				Hazmat Summary							
Driver Inspections:		9		Vehicle Inspections:		8		Hazmat Inspections				0			
Driver Out-of-service Inspections:		2		Vehicle Out-of-service Inspections:		5		Hazmat Out-of-service Inspections:				0			
Driver Out-of-service Rate:		22%		Vehicle Out-of-service Rate:		62%		Hazmat Out-of-service Rate:				0%			

Report executed at: 11/29/2023 1:15:03 PM

MCMIS snapshot date: 10/27/2023

For an explanation of FMCSA-reportable crashes see: <https://www.psp.fmcsa.dot.gov/psp/?redirectUrl=FAQ>

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.

Inspection Details												
Carrier Info				Driver Info				Inspection Info				
	Date	DOT #	Carrier Name	Driver Name	Driver Lic	State	Driver DOB	Rpt St	Report Number	Hazmat Insp	Insp Level	# of Viol
1	11/04/2020	3451173	BAJA MAR AUTO TRANSPORT LLC	DIAZ CARABALLO, VICTOR	D261870893740	FL	10/14/1989	TN	TEYY001859	N	2	2
Vehicle Violation: 392.2				State/Local Laws - Excessive weight - More than 5000 lbs over on allowable gross weight.			NON-OOS					
Vehicle Violation: 392.9(a)				Failing to secure load			OOS					
2	02/20/2022	3788046	JOLKADOT TRANSPORT LLC	DIAZ-CARABALLO, VICTOR	D261870893740	FL	10/14/1989	AL	RPFA005658	N	3	0
3	06/30/2022	3788046	JOLKADOT TRANSPORT LLC	DIAZ, VICTOR	47739421	TX	10/14/1989	LA	LADR007057	N	2	1
Vehicle Violation: 392.2				Dimension Violation (Width / Height / Length)			NON-OOS					
4	09/01/2022	3788046	JOLKADOT TRANSPORT LLC	DIAZ, VICTOR	47739421	TX	10/14/1989	WY	WSDD000259	N	2	4
Driver Violation: 392.2				Failure to obey traffic control device			NON-OOS					
Vehicle Violation: 392.2				Dimension Violation (Width / Height / Length)			NON-OOS					
Vehicle Violation: 393.45(b)(2)				Brake Hose or Tubing Chafing and/or Kinking - Connection to Power Unit			NON-OOS					
Vehicle Violation: 393.205(c)				Wheel fasteners loose and/or missing			NON-OOS					
5	09/03/2022	3788046	JOLKADOT TRANSPORT LLC	DIAZ, VICTOR	47739421	TX	10/14/1989	IN	7301003088	N	2	5
Vehicle Violation: 393.9(a)				Inoperative turn signal			OOS					
Vehicle Violation: 393.25(f)				Stop lamp violations			NON-OOS					
Vehicle Violation: 392.2				Dimension Violation (Width / Height / Length)			NON-OOS					
Vehicle Violation: 392.2				Dimension Violation (Width / Height / Length)			NON-OOS					
Vehicle Violation: 392.2				IRP Apportioned Tag or Registration Violation			NON-OOS					
6	09/04/2022	3788046	JOLKADOT TRANSPORT LLC	DIAZ, VICTOR	47739421	TX	10/14/1989	IN	7306003662	N	2	13

Report executed at: 11/29/2023 1:15:03 PM

MCMIS snapshot date: 10/27/2023

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.

	Driver Violation:	395.22(h)(2)	Driver failing to maintain ELD instruction sheet	NON-OOS									
	Driver Violation:	395.22(h)(3)	Driver failed to maintain instruction sheet for ELD malfunction reporting requirements	NON-OOS									
	Vehicle Violation:	392.2	IRP Apportioned Tag or Registration Violation	NON-OOS									
	Vehicle Violation:	393.11	Truck-Tractor upper body corner requirements for retroreflective sheeting or reflex reflective material for vehicles manufactured after July 1997	NON-OOS									
	Vehicle Violation:	393.11	Truck-Tractor lower rear mud flaps retroreflective sheeting / reflex reflective material requirements for vehicles manufactured after July 1997	NON-OOS									
	Vehicle Violation:	393.205(c)	Wheel fasteners loose and/or missing	NON-OOS									
	Vehicle Violation:	393.75(a)(3)	Tire-flat and/or audible air leak	OOS									
	Vehicle Violation:	392.2	Dimension Violation (Width / Height / Length)	NON-OOS									
	Vehicle Violation:	392.2	Dimension Violation (Width / Height / Length)	NON-OOS									
	Vehicle Violation:	392.2	Dimension Violation (Width / Height / Length)	NON-OOS									
	Vehicle Violation:	393.9(a)	Inoperable Required Lamp	NON-OOS									
	Vehicle Violation:	392.2	IRP Apportioned Tag or Registration Violation	NON-OOS									
	Vehicle Violation:	392.2	State or International Fuel Tax (IFTA) Violation	NON-OOS									
7	10/04/2022	3788046	JOLKADOT TRANSPORT LLC	DIAZ, VICTOR	47739421	TX	10/14/1989	WA	W318005548	N	2	10	
	Driver Violation:	395.8(e)(1)	False report of drivers record of duty status	OOS									
	Driver Violation:	395.22(g)	Portable ELD not mounted in a fixed position and visible to driver	NON-OOS									
	Driver Violation:	392.2	Dimension Violation (Width / Height / Length)	NON-OOS									
	Driver Violation:	392.2	State/Local Laws - Excessive weight - 2501-5000 lbs over on an axle/axle groups.	NON-OOS									
	Vehicle Violation:	392.2	Violation of Local Laws - Explain:	NON-OOS									
	Vehicle Violation:	393.100(b)	Leaking/spilling/blowing/falling cargo	OOS									
	Vehicle Violation:	393.207(f)	Air suspension pressure loss	OOS									
	Vehicle Violation:	393.75(g)	Weight carried exceeds tire load limit	OOS									
	Vehicle Violation:	393.75(a)(1)	Tire-ply or belt material exposed	OOS									
	Vehicle Violation:	393.106(d)	Insufficient aggregate working load limit	OOS									
8	10/26/2022	3788046	JOLKADOT TRANSPORT LLC	DIAZ, VICTOR	47739421	TX	10/14/1989	UT	23HK000023	N	2	4	
	Vehicle Violation:	393.9(a)	Inoperable tail lamp	NON-OOS									
	Vehicle Violation:	393.9(a)	Inoperable Required Lamp	NON-OOS									
	Driver Violation:	395.34(a)(1)	Failing to note malfunction that requires use of paper log	NON-OOS									
	Driver Violation:	395.8(e)(1)	False report of drivers record of duty status	OOS									

Report executed at: 11/29/2023 1:15:03 PM

MCMIS snapshot date: 10/27/2023

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.

9	11/01/2022	3788046	JOLKADOT TRANSPORT LLC	DIAZ, VICTOR	47739421	TX	10/14/1989	TX	6FO89DMPRX	N	2	13
Vehicle Violation:	393.104(b)	Damaged securement system/tiedowns	NON-OOS									
Vehicle Violation:	393.55(e)	No or Defective ABS Malfunction Indicator Lamp for trailer manufactured after 03/01/1998	NON-OOS									
Driver Violation:	395.3(a)(3)(ii)	Driving beyond 8 hour driving limit since the end of the last on duty, off duty, or sleeper period of at least 30 minutes	NON-OOS									
Vehicle Violation:	393.9(a)	Inoperative Brake Lamps	NON-OOS									
Vehicle Violation:	393.9(a)	Inoperative turn signal	NON-OOS									
Vehicle Violation:	393.19	Inoperative/Defective Hazard Warning Lamp	NON-OOS									
Vehicle Violation:	393.9(a)	Inoperable Required Lamp	NON-OOS									
Vehicle Violation:	393.9(a)	Inoperable Required Lamp	NON-OOS									
Vehicle Violation:	393.11	Truck-Tractor lower rear mud flaps retroreflective sheeting / reflex reflective material requirements for vehicles manufactured after July 1997	NON-OOS									
Vehicle Violation:	393.11	Truck-Tractor upper body corner requirements for retroreflective sheeting or reflex reflective material for vehicles manufactured after July 1997	NON-OOS									
Driver Violation:	999.	Speeding	NON-OOS									
Vehicle Violation:	393.106(c)(1)	No means to prevent cargo from rolling	OOS									
Vehicle Violation:	393.45(a)	Air Brake tubing improperly joined or spliced	OOS									

Violation Summary

Violation #	Description	# of Violations	# of Out-of-service Violations
393.104(b)	Damaged securement system/tiedowns	1	0
393.55(e)	No or Defective ABS Malfunction Indicator Lamp for trailer manufactured after 03/01/1998	1	0
395.3(a)(3)(ii)	Driving beyond 8 hour driving limit since the end of the last on duty, off duty, or sleeper period of at least 30 minutes	1	0
393.9(a)	Inoperative Brake Lamps	8	1
393.19	Inoperative/Defective Hazard Warning Lamp	1	0
393.11	Truck-Tractor lower rear mud flaps retroreflective sheeting / reflex reflective material requirements for vehicles manufactured after July 1997	4	0
999.	Speeding	1	0
393.106(c)(1)	No means to prevent cargo from rolling	1	1
393.45(a)	Air Brake tubing improperly joined or spliced	1	1
395.8(e)(1)	False report of drivers record of duty status	2	2
395.22(g)	Portable ELD not mounted in a fixed position and visible to driver	1	0
392.2	Dimension Violation (Width / Height / Length)	16	0

Report executed at: 11/29/2023 1:15:03 PM

MCMIS snapshot date: 10/27/2023

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.

393.100(b)	Leaking/spilling/blowing/falling cargo	1	1
393.207(f)	Air suspension pressure loss	1	1
393.75(g)	Weight carried exceeds tire load limit	1	1
393.75(a)(1)	Tire-ply or belt material exposed	1	1
393.106(d)	Insufficient aggregate working load limit	1	1
393.25(f)	Stop lamp violations	1	0
395.34(a)(1)	Failing to note malfunction that requires use of paper log	1	0
395.22(h)(2)	Driver failing to maintain ELD instruction sheet	1	0
395.22(h)(3)	Driver failed to maintain instruction sheet for ELD malfunction reporting requirements	1	0
393.205(c)	Wheel fasteners loose and/or missing	2	0
393.75(a)(3)	Tire-flat and/or audible air leak	1	1
393.45(b)(2)	Brake Hose or Tubing Chafing and/or Kinking - Connection to Power Unit	1	0
392.9(a)	Failing to secure load	1	1

The summary counts and rates only include violations that were attributable to DIAZCARABALLO, VICTOR.

Report executed at: 11/29/2023 1:15:03 PM

MCMIS snapshot date: 10/27/2023

For an explanation of FMCSA-reportable crashes see: <https://www.psp.fmcsa.dot.gov/psp/?redirectUrl=FAQ>

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.