

# PSP Detailed Report

Federal Motor Carrier Safety Administration

Driver Information													
Last Name	First Name	License #	State										
GARCIA	PABLO	G620660652900	FL										
Crash Activity													
Crash Summary (Crashes listed represent a driver's involvement in FMCSA-reportable crashes, without any determination as to responsibility.)													
# of Crashes:	1	# of Crashes with Fatalities:	0	# of Crashes with Injuries:	0	# of Towaways:	1						
# Not preventable:	0	# of Fatalities:	0	# of Injuries:	0	# of Hazmat Releases:	0						
Crash Details (Crashes listed represent a driver's involvement in FMCSA-reportable crashes, without any determination as to responsibility.)													
	Date	DOT #	Carrier Name	Driver Name	Driver Lic	State	Driver DOB	Rpt St	Report Number	Location	# Fatalities	# of Injuries	
1	02/15/2021	3179130	OSARGO TRANSPORT LLC	GARCIA, PABLO	G620660652900	FL	08/10/1965	AR	AR2021508508	I49	0	0	
Inspection Activity (3 year history from MCMIS snapshot date)													
Inspection Summary													
Driver Summary				Vehicle Summary				Hazmat Summary					
Driver Inspections:	2			Vehicle Inspections:	1			Hazmat Inspections			0		
Driver Out-of-service Inspections:	0			Vehicle Out-of-service Inspections:	1			Hazmat Out-of-service Inspections:			0		
Driver Out-of-service Rate:	0%			Vehicle Out-of-service Rate:	100%			Hazmat Out-of-service Rate:			0%		

Report executed at: 12/1/2023 9:34:30 AM

MCMIS snapshot date: 11/24/2023

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.

For an explanation of FMCSA-reportable crashes see: <https://www.psp.fmcsa.dot.gov/psp/?redirectUrl=FAQ>

Inspection Details												
Carrier Info				Driver Info				Inspection Info				
	Date	DOT #	Carrier Name	Driver Name	Driver Lic	State	Driver DOB	Rpt St	Report Number	Hazmat Insp	Insp Level	# of Viol
1	03/16/2021	3509574	JHL EXPRESS INC	GARCIA, PABLO	G620660652900	FL	08/10/1965	WA	W217003919	N	2	6
Vehicle Violation:		393.9(a)	Inoperative turn signal			OOS						
Vehicle Violation:		393.45	Brake tubing and hose adequacy			OOS						
Driver Violation:		395.8	Record of Duty Status violation (general/form and manner)			NON-OOS						
Driver Violation:		395.8(e)(1)	False report of drivers record of duty status			NON-OOS						
Driver Violation:		395.3(a)(2)	Driving beyond 14 hour duty period (Property carrying vehicle)			NON-OOS						
Driver Violation:		395.3(a)(3)(i)	Driving beyond 11 hour driving limit. (Property Carrying Vehicle)			NON-OOS						
2	04/25/2023	3731355	INTRANS XPRESS LLC	GARCIA, PABLO	G620660652900	FL	08/10/1965	IL	4181110059	N	3	0

### Violation Summary

Violation #	Description	# of Violations	# of Out-of-service Violations
393.9(a)	Inoperative turn signal	1	1
393.45	Brake tubing and hose adequacy	1	1
395.8	Record of Duty Status violation (general/form and manner)	1	0
395.8(e)(1)	False report of drivers record of duty status	1	0
395.3(a)(2)	Driving beyond 14 hour duty period (Property carrying vehicle)	1	0
395.3(a)(3)(i)	Driving beyond 11 hour driving limit. (Property Carrying Vehicle)	1	0

The summary counts and rates only include violations that were attributable to GARCIA, PABLO.

Report executed at: 12/1/2023 9:34:30 AM

MCMIS snapshot date: 11/24/2023

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.

For an explanation of FMCSA-reportable crashes see: <https://www.psp.fmcsa.dot.gov/psp/?redirectUrl=FAQ>