

PSP Detailed Report

Federal Motor Carrier Safety Administration

Driver Information															
Last Name		First Name		License #			State								
SANTIAGOVAZQUEZ		JUAN		S532423983210			FL								
Crash Activity															
Crash Summary (Crashes listed represent a driver's involvement in FMCSA-reportable crashes, without any determination as to responsibility.)															
# of Crashes:		0		# of Crashes with Fatalities:		0		# of Crashes with Injuries:		0		# of Towaways:		0	
# Not preventable:		0		# of Fatalities:		0		# of Injuries:		0		# of Hazmat Releases:		0	
Crash Details (Crashes listed represent a driver's involvement in FMCSA-reportable crashes, without any determination as to responsibility.)															
	Date	DOT #	Carrier Name	Driver Name	Driver Lic	State	Driver DOB	Rpt St	Report Number	Location	# Fatalities	# of Injuries			
Inspection Activity (3 year history from MCMIS snapshot date)															
Inspection Summary															
Driver Summary				Vehicle Summary				Hazmat Summary							
Driver Inspections:		3		Vehicle Inspections:		2		Hazmat Inspections				0			
Driver Out-of-service Inspections:		0		Vehicle Out-of-service Inspections:		0		Hazmat Out-of-service Inspections:				0			
Driver Out-of-service Rate:		0%		Vehicle Out-of-service Rate:		0%		Hazmat Out-of-service Rate:				0%			
Inspection Details															
Carrier Info				Driver Info				Inspection Info							
	Date	DOT #	Carrier Name	Driver Name	Driver Lic	State	Driver DOB	Rpt St	Report Number	Hazmat Insp	Insp Level	# of Viol			
1	12/21/2020	3171739	KIND TRANSPORT INC	SANTIAGO VAZQUEZ, JUAN	S532423983210	FL	09/01/1998	KY	CV43882476	N	2	0			

Report executed at: 11/30/2023 12:03:18 PM

MCMIS snapshot date: 10/27/2023

For an explanation of FMCSA-reportable crashes see: <https://www.psp.fmcsa.dot.gov/psp/?redirectUrl=FAQ>

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.

2	02/19/2021	3171739	KIND TRANSPORT INC	SANTIAGO VAZQUEZ, JUAN	S532423983210	FL	09/01/1998	TN	BBBA019615	N	1	5
Vehicle Violation:		393.95(a)	No/discharged/unsecured fire extinguisher			NON-OOS						
Vehicle Violation:		393.78	Windshield wipers inoperative/defective			NON-OOS						
Vehicle Violation:		392.2	State/Local Laws - Excessive weight - 1-2500 lbs over on an axle/axle groups.			NON-OOS						
Vehicle Violation:		393.47(e)	Clamp or Roto type brake out-of-adjustment			NON-OOS						
Vehicle Violation:		393.53(b)	CMV manufactured after 10/19/94 has an automatic airbrake adjustment system that fails to compensate for wear			NON-OOS						
3	06/30/2021	3171739	KIND TRANSPORT INC	SANTIAGO VAZQUEZ, JUA (co-driver)	S532423983210	FL	09/01/1998	SC	M321000384	N	3	0

Violation Summary

Violation #	Description	# of Violations	# of Out-of-service Violations
393.95(a)	No/discharged/unsecured fire extinguisher	1	0
393.78	Windshield wipers inoperative/defective	1	0
392.2	State/Local Laws - Excessive weight - 1-2500 lbs over on an axle/axle groups.	1	0
393.47(e)	Clamp or Roto type brake out-of-adjustment	1	0
393.53(b)	CMV manufactured after 10/19/94 has an automatic airbrake adjustment system that fails to compensate for wear	1	0

The summary counts and rates only include violations that were attributable to SANTIAGOVAZQUEZ, JUAN.

Report executed at: 11/30/2023 12:03:18 PM

MCMIS snapshot date: 10/27/2023

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.

For an explanation of FMCSA-reportable crashes see: <https://www.psp.fmcsa.dot.gov/psp/?redirectUrl=FAQ>