

PSP Detailed Report

Federal Motor Carrier Safety Administration

| Driver Information | | | | | | | | | | | | | | | |
|--|------------|--------------|-----------------------|-------------------------------------|------------|-------|------------|------------------------------------|---------------|-------------|--------------|-----------------------|--|---|--|
| Last Name | | First Name | | License # | | | State | | | | | | | | |
| PATLAN | | HERMENEGILDO | | 12173249 | | | TX | | | | | | | | |
| Crash Activity | | | | | | | | | | | | | | | |
| Crash Summary (Crashes listed represent a driver's involvement in FMCSA-reportable crashes, without any determination as to responsibility.) | | | | | | | | | | | | | | | |
| # of Crashes: | | 0 | | # of Crashes with Fatalities: | | 0 | | # of Crashes with Injuries: | | 0 | | # of Towaways: | | 0 | |
| # Not preventable: | | 0 | | # of Fatalities: | | 0 | | # of Injuries: | | 0 | | # of Hazmat Releases: | | 0 | |
| Crash Details (Crashes listed represent a driver's involvement in FMCSA-reportable crashes, without any determination as to responsibility.) | | | | | | | | | | | | | | | |
| | Date | DOT # | Carrier Name | Driver Name | Driver Lic | State | Driver DOB | Rpt St | Report Number | Location | # Fatalities | # of Injuries | | | |
| Inspection Activity (3 year history from MCMIS snapshot date) | | | | | | | | | | | | | | | |
| Inspection Summary | | | | | | | | | | | | | | | |
| Driver Summary | | | | Vehicle Summary | | | | Hazmat Summary | | | | | | | |
| Driver Inspections: | | 6 | | Vehicle Inspections: | | 6 | | Hazmat Inspections | | | | 0 | | | |
| Driver Out-of-service Inspections: | | 0 | | Vehicle Out-of-service Inspections: | | 1 | | Hazmat Out-of-service Inspections: | | | | 0 | | | |
| Driver Out-of-service Rate: | | 0% | | Vehicle Out-of-service Rate: | | 17% | | Hazmat Out-of-service Rate: | | | | 0% | | | |
| Inspection Details | | | | | | | | | | | | | | | |
| Carrier Info | | | | Driver Info | | | | Inspection Info | | | | | | | |
| | Date | DOT # | Carrier Name | Driver Name | Driver Lic | State | Driver DOB | Rpt St | Report Number | Hazmat Insp | Insp Level | # of Viol | | | |
| 1 | 01/27/2021 | 3406925 | REBLANK TRANSPORT INC | PATLAN, HERMENEGILDO | 12173249 | TX | 04/19/1966 | CO | PF11500585 | N | 2 | 0 | | | |

Report executed at: 12/18/2023 12:55:32 PM

MCMIS snapshot date: 11/24/2023

For an explanation of FMCSA-reportable crashes see: <https://www.psp.fmcsa.dot.gov/psp/?redirectUrl=FAQ>

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.

| | | | | | | | | | | | | |
|--------------------|------------|--------------|--|----------------------|----------|----|------------|----|------------|---|---|---|
| 2 | 11/10/2021 | 3053221 | TERESITA MENDOZA TREVINO | PATLAN, HERMENEGILDO | 12173249 | TX | 04/19/1966 | TX | 65SI0XIW66 | N | 2 | 2 |
| Vehicle Violation: | | 393.9(a) | Inoperable Required Lamp | NON-OOS | | | | | | | | |
| Vehicle Violation: | | 392.2 | State vehicle registration or License Plate violation | NON-OOS | | | | | | | | |
| 3 | 11/18/2021 | 3307859 | DOUBLE ACES LLC | PATLAN, HERMENEGILDO | 12173249 | TX | 04/19/1966 | TX | 66090XLC24 | N | 2 | 3 |
| Vehicle Violation: | | 393.9(a) | Inoperative turn signal | NON-OOS | | | | | | | | |
| Vehicle Violation: | | 393.30 | Improper battery installation | NON-OOS | | | | | | | | |
| Vehicle Violation: | | 393.9(a) | Inoperable Required Lamp | NON-OOS | | | | | | | | |
| 4 | 01/05/2023 | 3869555 | ABUELOS LOGISTICS LLC | PATLAN, HERMENEGILDO | 12173249 | TX | 04/19/1966 | TX | 6HHC0EFORK | N | 2 | 3 |
| Vehicle Violation: | | 393.203(c) | Hood not securely fastened | NON-OOS | | | | | | | | |
| Vehicle Violation: | | 393.9(a) | Inoperative turn signal | NON-OOS | | | | | | | | |
| Vehicle Violation: | | 393.9(a) | Inoperable Required Lamp | NON-OOS | | | | | | | | |
| 5 | 03/29/2023 | 2327057 | BZ EXPRESS INC | PATLAN, HERMENEGILDO | 12173249 | TX | 04/19/1966 | WI | 1769003629 | N | 1 | 3 |
| Driver Violation: | | 395.8(e)(1) | False report of drivers record of duty status | NON-OOS | | | | | | | | |
| Vehicle Violation: | | 393.11 | No or defective lighting devices or reflective material as required | NON-OOS | | | | | | | | |
| Vehicle Violation: | | 393.55(e) | No or Defective ABS Malfunction Indicator Lamp for trailer manufactured after 03/01/1998 | NON-OOS | | | | | | | | |
| 6 | 08/03/2023 | 2327057 | BZ EXPRESS INC | PATLAN, HERMENEGILDO | 12173249 | TX | 04/19/1966 | TX | 6NB70AKLET | N | 2 | 1 |
| Vehicle Violation: | | 393.75(a)(3) | Tire-flat and/or audible air leak | OOS | | | | | | | | |

Violation Summary

| Violation # | Description | # of Violations | # of Out-of-service Violations |
|--------------|--|-----------------|--------------------------------|
| 393.203(c) | Hood not securely fastened | 1 | 0 |
| 393.9(a) | Inoperative turn signal | 5 | 0 |
| 395.8(e)(1) | False report of drivers record of duty status | 1 | 0 |
| 393.11 | No or defective lighting devices or reflective material as required | 1 | 0 |
| 393.55(e) | No or Defective ABS Malfunction Indicator Lamp for trailer manufactured after 03/01/1998 | 1 | 0 |
| 393.75(a)(3) | Tire-flat and/or audible air leak | 1 | 1 |
| 393.30 | Improper battery installation | 1 | 0 |
| 392.2 | State vehicle registration or License Plate violation | 1 | 0 |

The summary counts and rates only include violations that were attributable to PATLAN, HERMENEGILDO.

Report executed at: 12/18/2023 12:55:32 PM

MCMIS snapshot date: 11/24/2023

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.

For an explanation of FMCSA-reportable crashes see: <https://www.psp.fmcsa.dot.gov/psp/?redirectUrl=FAQ>