

PSP Detailed Report

Federal Motor Carrier Safety Administration

Driver Information															
Last Name		First Name		License #			State								
FERRERAZELAYA		JUAN		F662426743300			FL								
Crash Activity															
Crash Summary (Crashes listed represent a driver's involvement in FMCSA-reportable crashes, without any determination as to responsibility.)															
# of Crashes:		0		# of Crashes with Fatalities:		0		# of Crashes with Injuries:		0		# of Towaways:		0	
# Not preventable:		0		# of Fatalities:		0		# of Injuries:		0		# of Hazmat Releases:		0	
Crash Details (Crashes listed represent a driver's involvement in FMCSA-reportable crashes, without any determination as to responsibility.)															
	Date	DOT #	Carrier Name	Driver Name	Driver Lic	State	Driver DOB	Rpt St	Report Number	Location	# Fatalities	# of Injuries			
Inspection Activity (3 year history from MCMIS snapshot date)															
Inspection Summary															
Driver Summary				Vehicle Summary				Hazmat Summary							
Driver Inspections:		1		Vehicle Inspections:		1		Hazmat Inspections				0			
Driver Out-of-service Inspections:		0		Vehicle Out-of-service Inspections:		1		Hazmat Out-of-service Inspections:				0			
Driver Out-of-service Rate:		0%		Vehicle Out-of-service Rate:		100%		Hazmat Out-of-service Rate:				0%			

Report executed at: 1/5/2024 2:24:33 PM

MCMIS snapshot date: 12/29/2023

For an explanation of FMCSA-reportable crashes see: <https://www.psp.fmcsa.dot.gov/psp/?redirectUrl=FAQ>

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.

Inspection Details												
Carrier Info				Driver Info				Inspection Info				
	Date	DOT #	Carrier Name	Driver Name	Driver Lic	State	Driver DOB	Rpt St	Report Number	Hazmat Insp	Insp Level	# of Viol
1	10/17/2023	3794409	DMS TRACK INC	FERRERA ZELAYA, JUAN	F662426743300	FL	09/10/1974	MD	3056005062	N	1	4
<div>Vehicle Violation: 396.3(a)(1) Inspection, repair and maintenance of parts & accessories NON-OOS</div> <div>Vehicle Violation: 393.45 Brake tubing and hose adequacy OOS</div> <div>Driver Violation: 395.8(e)(1) False report of drivers record of duty status NON-OOS</div> <div>Driver Violation: 395.8(e)(1) False report of drivers record of duty status NON-OOS</div>												
Violation Summary												
Violation #	Description								# of Violations	# of Out-of-service Violations		
396.3(a)(1)	Inspection, repair and maintenance of parts & accessories								1	0		
393.45	Brake tubing and hose adequacy								1	1		
395.8(e)(1)	False report of drivers record of duty status								2	0		

The summary counts and rates only include violations that were attributable to FERRERAZELAYA, JUAN.

Report executed at: 1/5/2024 2:24:33 PM

MCMIS snapshot date: 12/29/2023

For an explanation of FMCSA-reportable crashes see: <https://www.psp.fmcsa.dot.gov/psp/?redirectUrl=FAQ>

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.