

PSP Detailed Report

Federal Motor Carrier Safety Administration

Driver Information													
Last Name	First Name	License #	State										
BUCKNOR	IAN	B256411783370	FL										
Crash Activity													
Crash Summary (Crashes listed represent a driver's involvement in FMCSA-reportable crashes, without any determination as to responsibility.)													
# of Crashes:	0	# of Crashes with Fatalities:	0	# of Crashes with Injuries:	0	# of Towaways:	0						
# Not preventable:	0	# of Fatalities:	0	# of Injuries:	0	# of Hazmat Releases:	0						
Crash Details (Crashes listed represent a driver's involvement in FMCSA-reportable crashes, without any determination as to responsibility.)													
	Date	DOT #	Carrier Name	Driver Name	Driver Lic	State	Driver DOB	Rpt St	Report Number	Location	# Fatalities	# of Injuries	
Inspection Activity (3 year history from MCMIS snapshot date)													
Inspection Summary													
Driver Summary				Vehicle Summary				Hazmat Summary					
Driver Inspections:		2		Vehicle Inspections:		1		Hazmat Inspections				0	
Driver Out-of-service Inspections:		0		Vehicle Out-of-service Inspections:		1		Hazmat Out-of-service Inspections:				0	
Driver Out-of-service Rate:		0%		Vehicle Out-of-service Rate:		100%		Hazmat Out-of-service Rate:				0%	
Inspection Details													
Carrier Info				Driver Info					Inspection Info				
	Date	DOT #	Carrier Name	Driver Name	Driver Lic	State	Driver DOB	Rpt St	Report Number	Hazmat Insp	Insp Level	# of Viol	
1	08/12/2022	2578858	YANKEE FREIGHT SYSTEMS LLC	BUCKNOR, IAN	B256411783370	FL	09/17/1978	MO	W236007674	N	3	1	
Driver Violation:		392.2		State/Local Laws - Excessive weight - 1-2500 lbs over on an axle/axle groups				NON-OOS					

Report executed at: 12/2/2024 9:41:28 AM

MCMIS snapshot date: 10/25/2024

For an explanation of FMCSA-reportable crashes see: <https://www.psp.fmcsa.dot.gov/psp/?redirectUrl=FAQ>

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.

2	07/18/2024	3119062	RIKI TRANSPORTATION INC	BUCKNOR, IAN	B256411783370	FL	09/17/1978	SC	K395000238	N	2	2
Vehicle Violation:		393.9(a)	Inoperable Required Lamp		NON-OOS							
Vehicle Violation:		393.9(a)	Inoperable Required Lamp		OOS							
Violation Summary												
Violation #		Description							# of Violations		# of Out-of-service Violations	
392.2		State/Local Laws - Excessive weight - 1-2500 lbs over on an axle/axle groups							1		0	
393.9(a)		Inoperable Required Lamp							2		1	

The summary counts and rates only include violations that were attributable to BUCKNOR, IAN.

Report executed at: 12/2/2024 9:41:28 AM

MCMIS snapshot date: 10/25/2024

For an explanation of FMCSA-reportable crashes see: <https://www.psp.fmcsa.dot.gov/psp/?redirectUrl=FAQ>

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.