

PSP Detailed Report

Federal Motor Carrier Safety Administration

Driver Information															
Last Name		First Name		License #			State								
BALTODANO		GUSTAVO		19598792			TX								
Crash Activity															
Crash Summary (Crashes listed represent a driver's involvement in FMCSA-reportable crashes, without any determination as to responsibility.)															
# of Crashes:		0		# of Crashes with Fatalities:		0		# of Crashes with Injuries:		0		# of Towaways:		0	
# Not preventable:		0		# of Fatalities:		0		# of Injuries:		0		# of Hazmat Releases:		0	
Crash Details (Crashes listed represent a driver's involvement in FMCSA-reportable crashes, without any determination as to responsibility.)															
	Date	DOT #	Carrier Name	Driver Name	Driver Lic	State	Driver DOB	Rpt St	Report Number	Location	# Fatalities	# of Injuries			
Inspection Activity (3 year history from MCMIS snapshot date)															
Inspection Summary															
Driver Summary				Vehicle Summary				Hazmat Summary							
Driver Inspections:		2		Vehicle Inspections:		1		Hazmat Inspections				0			
Driver Out-of-service Inspections:		0		Vehicle Out-of-service Inspections:		1		Hazmat Out-of-service Inspections:				0			
Driver Out-of-service Rate:		0%		Vehicle Out-of-service Rate:		100%		Hazmat Out-of-service Rate:				0%			

Report executed at: 1/5/2024 11:58:22 AM

MCMIS snapshot date: 12/29/2023

For an explanation of FMCSA-reportable crashes see: <https://www.psp.fmcsa.dot.gov/psp/?redirectUrl=FAQ>

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.

Inspection Details												
Carrier Info				Driver Info				Inspection Info				
	Date	DOT #	Carrier Name	Driver Name	Driver Lic	State	Driver DOB	Rpt St	Report Number	Hazmat Insp	Insp Level	# of Viol
1	06/22/2023	3105463	VDV ROYAL TRANS INC	BALTODANO, GUSTAVO	19598792	TX	09/23/1971	CA	NDDN004244	N	1	4
Vehicle Violation: 396.3(a)(1) Inspection, repair and maintenance of parts & accessories NON-OOS Vehicle Violation: 396.5(b) Hubs - Wheel seal leaking - inner wheel OOS Vehicle Violation: 393.45 Brake tubing and hose adequacy OOS Vehicle Violation: 396.3(a)(1) Inspection, repair and maintenance of parts & accessories NON-OOS												
2	10/23/2023	3547441	MEETI INC	BALTODANO, GUSTAVO	19598792	TX	09/23/1971	CA	UDI1001664	N	3	4
Driver Violation: 392.2 Lane Restriction violation NON-OOS Driver Violation: 392.2 State/Local Laws - Speeding 11-14 miles per hour over the speed limit. NON-OOS Driver Violation: 392.60(a) Unauthorized passenger on board CMV NON-OOS Driver Violation: 395.30(b)(1) Driver failed to certify the accuracy of the information gathered by the ELD NON-OOS												
Violation Summary												
Violation #	Description								# of Violations	# of Out-of-service Violations		
392.2	Lane Restriction violation								2	0		
392.60(a)	Unauthorized passenger on board CMV								1	0		
395.30(b)(1)	Driver failed to certify the accuracy of the information gathered by the ELD								1	0		
396.3(a)(1)	Inspection, repair and maintenance of parts & accessories								2	0		
396.5(b)	Hubs - Wheel seal leaking - inner wheel								1	1		
393.45	Brake tubing and hose adequacy								1	1		

The summary counts and rates only include violations that were attributable to BALTODANO, GUSTAVO.

Report executed at: 1/5/2024 11:58:22 AM

MCMIS snapshot date: 12/29/2023

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.

For an explanation of FMCSA-reportable crashes see: <https://www.psp.fmcsa.dot.gov/psp/?redirectUrl=FAQ>