PSP Detailed Report

Federal Motor Carrier Safety Administration

Driver Information																		
Last Name				First Name			Lice	License #					State					
RODRIGUEZ					SIXTO CELES			E215783811490					FL					
ESPINALRODRIGUEZ				SIXTO			E21	E215783811490					FL					
ESPINAL					SIXTO CELES			E215783811490					FL					
	Crash Activity																	
Crash Summary (Crashes listed represent a driver's involvement in FMCSA-reportable crashes, without any determination as to responsibility.)																		
# of Crashes:				0		# of Crashes with Fatali					# of Cras	hes with l	njuries:	0	# of Towaways:			
# Not preventable:					# of Fatalit			0		# of I				0	# of Hazmat Releases:			
Cras	sh Details (C	rashes listed r	epresent a c	rive	r's involvement	in FMCSA-reportable cr	rashes	s, wit	hout any	determ	ination as t	o respon	sibility	_)			•	
	Date DOT# Carri			ier N	ame	Driver Name		Driver Lic		State	Driver DOE	Rpt St	Report Number		Location	# Fatalities	# of Injuries	
	Inspection Activity (3 year history from MCMIS snapshot date)																	
Insp	ection Sum	mary																
Driver Summary						Vehicle Summary						Hazmat Summary						
Driver Inspections:						Vehicle Inspections: 1					Hazmat Inspections 0							
Driver Out-of-service Inspections:						Vehicle Out-of-service Inspections:					0	Hazmat Out-of-service Inspections:						
Driver Out-of-service Rate:					09	Vehicle Out-of-service Rate:					0%	Hazmat Out-of-service Rate: 00					0%	

Report executed at: 2/15/2024 11:23:18 AM

MCMIS snapshot date: 01/26/2024

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.

Inspection Details														
Carrier Info				Driver Info					Inspection Info					
	Date	DOT#	Carrier Name	Driver Name	Driver Lic	State	Driver DOB	Rpt St	Report Number	Hazmat Insp	Insp Level	# of Viol		
1	09/20/2023	1430510	RAIN DOGS TRUCKING INC	ESPINAL RODRIGUEZ, SIXTO	E215783811490	FL	04/29/1981	TX	V231156493	N	2	1		
	Vehicle Violation: 393.55(d)(3) No or Defective ABS Malfunction Indicator for towed vehicles on vehicles manufactured after February 2001 NON-OOS													
Violati	on Summary													
Violation #				# of Violation	# of Violations		# of Out-of-service Violations							
393.55(d)(3)	No or Defective	ve ABS Malfunction Indicator for		1		0							

The summary counts and rates only include violations that were attributable to RODRIGUEZ, SIXTO CELES.

Report executed at: 2/15/2024 11:23:18 AM

MCMIS snapshot date: 01/26/2024

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.