

# PSP Detailed Report

Federal Motor Carrier Safety Administration

Driver Information													
Last Name	First Name	License #	State										
CUELLAR	HAROL	514416524	NM										
SANCHEZ	HAROL	514416524	NM										
CUELLARSANCHEZ	HAROL	514416524	NM										
SANCHEZCUELLAR	HAROL	514416524	NM										

Crash Activity													
Crash Summary (Crashes listed represent a driver's involvement in FMCSA-reportable crashes, without any determination as to responsibility.)													
# of Crashes:	0	# of Crashes with Fatalities:	0	# of Crashes with Injuries:	0	# of Towaways:	0						
# Not preventable:	0	# of Fatalities:	0	# of Injuries:	0	# of Hazmat Releases:	0						
Crash Details (Crashes listed represent a driver's involvement in FMCSA-reportable crashes, without any determination as to responsibility.)													
	Date	DOT #	Carrier Name	Driver Name	Driver Lic	State	Driver DOB	Rpt St	Report Number	Location	# Fatalities	# of Injuries	

Inspection Activity (3 year history from MCMIS snapshot date)													
Inspection Summary													
Driver Summary				Vehicle Summary				Hazmat Summary					
Driver Inspections:	8			Vehicle Inspections:	3			Hazmat Inspections				0	
Driver Out-of-service Inspections:	0			Vehicle Out-of-service Inspections:	1			Hazmat Out-of-service Inspections:				0	
Driver Out-of-service Rate:	0%			Vehicle Out-of-service Rate:	33%			Hazmat Out-of-service Rate:				0%	

Report executed at: 3/31/2025 3:50:51 PM

MCMIS snapshot date: 02/28/2025

For an explanation of FMCSA-reportable crashes see: <https://www.psp.fmcsa.dot.gov/psp/?redirectUrl=FAQ>

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.

Inspection Details												
Carrier Info				Driver Info				Inspection Info				
	Date	DOT #	Carrier Name	Driver Name	Driver Lic	State	Driver DOB	Rpt St	Report Number	Hazmat Insp	Insp Level	# of Viol
1	05/18/2022	3624929	HLC TRANSPORT LLC	CUELLAR-SANCHEZ, HAROL	514416524	NM	12/28/1987	NM	0550M3UHKG	N	1	3
Vehicle Violation: 393.48(a) Inoperative/defective brakes NON-OOS												
Vehicle Violation: 396.3(a)(1) A liquid fuel system with a dripping leak at any point OOS												
Vehicle Violation: 396.3(a)(1) Center Bearing (Carrier Bearing) Cracked / Loose / Broken / Missing OOS												
2	12/14/2022	2534297	LOVE FREIGHTWAYS INC	CUELLAR-SANCHEZ, HAROL	514416524	NM	12/28/1987	TX	6GV70AIJLC	N	2	0
3	10/06/2023	3111076	PHILLIP'S ROADWAY SERVICES LLC	CUELLAR SANCHEZ, HAROL	514416524	NM	12/28/1987	CO	PF10205731	N	3	0
4	11/01/2023	3111076	PHILLIP'S ROADWAY SERVICES LLC	CUELLAR SANCHEZ, HAROL	514416524	NM	12/28/1987	CO	1A26000190	N	3	0
5	11/02/2023	3111076	PHILLIP'S ROADWAY SERVICES LLC	CUELLAR-SANCHEZ, HAROL	514416524	NM	12/28/1987	CO	4C30000460	N	3	0
6	12/06/2023	2575446	CRAZY HORSE TRANSPORT LLC	CUELLAR-SANCHEZ, HAROL	514416524	NM	12/28/1987	OR	AADW003775	N	3	0
7	12/20/2023	2575446	CRAZY HORSE TRANSPORT LLC	CUELLARSANCHEZ, HAROL	514416524	NM	12/28/1988	WA	2063000050	N	3	0
8	12/16/2024	3907924	IMI TRUCKING	CUELLAR-SANCHEZ, HAROL	514416524	NM	12/28/1987	CA	ND72009081	N	1	2
Driver Violation: 395.24D-ELDPT HOS (ELD) - On request by an authorized safety official, a driver must produce and transfer from an ELD the driver's hours of service records in accordance with t NON-OOS												
Vehicle Violation: 393.45D-B Air Brake - Audible air leak at a proper connection NON-OOS												
Violation Summary												
Violation #		Description							# of Violations		# of Out-of-service Violations	
395.24D-ELDPT		HOS (ELD) - On request by an authorized safety official, a driver must produce and transfer from an ELD the driver's hours of service records in accordance with t							1		0	

Report executed at: 3/31/2025 3:50:51 PM

MCMIS snapshot date: 02/28/2025

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.

393.45D-B	Air Brake - Audible air leak at a proper connection	1	0
393.48(a)	Inoperative/defective brakes	1	0
396.3(a)(1)	A liquid fuel system with a dripping leak at any point	2	2

The summary counts and rates only include violations that were attributable to CUELLAR, HAROL.

Report executed at: 3/31/2025 3:50:51 PM

MCMIS snapshot date: 02/28/2025

For an explanation of FMCSA-reportable crashes see: <https://www.psp.fmcsa.dot.gov/psp/?redirectUrl=FAQ>

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.