

PSP Detailed Report

Federal Motor Carrier Safety Administration

Driver Information													
Last Name	First Name	License #	State										
LEONFUENTES	MARCOS	L515541664250	FL										
LEON	MARCOS	L515541664250	FL										
FUENTES	MARCOS	L515541664250	FL										

Crash Activity													
Crash Summary (Crashes listed represent a driver's involvement in FMCSA-reportable crashes, without any determination as to responsibility.)													
# of Crashes:	0	# of Crashes with Fatalities:	0	# of Crashes with Injuries:	0	# of Towaways:	0						
# Not preventable:	0	# of Fatalities:	0	# of Injuries:	0	# of Hazmat Releases:	0						
Crash Details (Crashes listed represent a driver's involvement in FMCSA-reportable crashes, without any determination as to responsibility.)													
	Date	DOT #	Carrier Name	Driver Name	Driver Lic	State	Driver DOB	Rpt St	Report Number	Location	# Fatalities	# of Injuries	

Inspection Activity (3 year history from MCMIS snapshot date)													
Inspection Summary													
Driver Summary				Vehicle Summary				Hazmat Summary					
Driver Inspections:		12		Vehicle Inspections:		4		Hazmat Inspections				0	
Driver Out-of-service Inspections:		1		Vehicle Out-of-service Inspections:		2		Hazmat Out-of-service Inspections:				0	
Driver Out-of-service Rate:		8%		Vehicle Out-of-service Rate:		50%		Hazmat Out-of-service Rate:				0%	

Report executed at: 3/19/2024 11:42:55 AM

MCMIS snapshot date: 02/23/2024

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.

For an explanation of FMCSA-reportable crashes see: <https://www.psp.fmcsa.dot.gov/psp/?redirectUrl=FAQ>

Inspection Details												
Carrier Info				Driver Info				Inspection Info				
	Date	DOT #	Carrier Name	Driver Name	Driver Lic	State	Driver DOB	Rpt St	Report Number	Hazmat Insp	Insp Level	# of Viol
1	03/23/2022	2861805	PEACE EXPRESS INC	LEON FUENTES, MARCOS	L515541664250	FL	11/25/1966	NE	00DH000467	N	3	1
Driver Violation: 392.2				Unlawfully parking and/or leaving vehicle in the roadway			NON-OOS					
2	04/12/2022	2861805	PEACE EXPRESS INC	LEON-FUENTES, MARCOS	L515541664250	FL	11/25/1966	NM	8096M2UQK4	N	2	1
Vehicle Violation: 396.5(a)				Hubs - No visible or measurable lubricant showing in the hub - outer wheel			OOS					
3	05/22/2022	2289631	TESLA TRANSPORT INC	LEON-FUENTES, MARCOS	L515541664250	FL	11/25/1966	NM	2438M3YHMC	N	3	0
4	09/08/2022	2956931	VITAL TRANS INC	LEON-FUENTES, MARCOS	L515541664250	FL	11/25/1966	WY	5304002054	N	1	2
Vehicle Violation: 393.95(a)				No/discharged/unsecured fire extinguisher			NON-OOS					
Vehicle Violation: 393.75(a)(3)				Tire-flat and/or audible air leak			OOS					
5	09/20/2022	2956931	VITAL TRANS INC	LEON-FUENTES, MARCOS	L515541664250	FL	11/25/1966	CA	UB36002618	N	3	2
Driver Violation: 392.2				Violation of Local Laws - Explain:			NON-OOS					
Driver Violation: 383.23(a)(2)				Operating a CMV without a CDL			OOS					
6	11/15/2022	2956931	VITAL TRANS INC	LEON-FUENTES, MARCOS	L515541664250	FL	11/25/1966	OK	T400161203	N	3	2
Driver Violation: 395.22(h)(2)				Driver failing to maintain ELD instruction sheet			NON-OOS					
Vehicle Violation: 396.17(c)				Operating a CMV without proof of a periodic inspection			NON-OOS					
7	03/16/2023	2956931	VITAL TRANS INC	LEON FUENTES, MARCOS	L515541664250	FL	11/25/1966	FL	1562002929	N	3	2
Driver Violation: 395.22(h)(4)				Driver failed to maintain supply of blank drivers records of duty status graph-grids			NON-OOS					
Driver Violation: 395.3(a)(2)				Driving beyond 14 hour duty period (Property carrying vehicle) - Nominal Violation			NON-OOS					
8	06/18/2023	2956931	VITAL TRANS INC	LEON-FUENTES, MARCOS	L515541664250	FL	11/25/1966	OR	AAYB007638	N	3	1
Driver Violation: 395.8				Record of Duty Status violation (general/form and manner)			NON-OOS					
9	09/28/2023	2956931	VITAL TRANS INC	LEON-FUENTES, MARCOS	L515541664250	FL	11/25/1966	WY	TCJS000041	N	3	2
Driver Violation: 392.2				Unlawfully parking and/or leaving vehicle in the roadway			NON-OOS					
Driver Violation: 392.22(a)				Failing to use hazard warning flashers			NON-OOS					
10	12/15/2023	2956931	VITAL TRANS INC	LEONFUENTES, MARCOS	L515541664250	FL	11/25/1966	MT	U215900118	N	2	0

Report executed at: 3/19/2024 11:42:55 AM

MCMIS snapshot date: 02/23/2024

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.

11	12/21/2023	2956931	VITAL TRANS INC	LEON-FUENTES, MARCOS	L515541664250	FL	11/25/1966	CA	UEFK003128	N	2	1
Driver Violation: 392.2			State/Local Laws - Speeding 6-10 miles per hour over the speed limit.				NON-OOS					
12	01/16/2024	2956931	VITAL TRANS INC	LEON-FUENTES, MARCOS	L515541664250	FL	11/25/1966	CO	1A22000169	N	3	0

Violation Summary

Violation #	Description	# of Violations	# of Out-of-service Violations
396.5(a)	Hubs - No visible or measurable lubricant showing in the hub - outer wheel	1	1
392.2	Violation of Local Laws - Explain:	4	0
383.23(a)(2)	Operating a CMV without a CDL	1	1
395.8	Record of Duty Status violation (general/form and manner)	1	0
392.22(a)	Failing to use hazard warning flashers	1	0
395.22(h)(4)	Driver failed to maintain supply of blank drivers records of duty status graph-grids	1	0
395.3(a)(2)	Driving beyond 14 hour duty period (Property carrying vehicle) - Nominal Violation	1	0
395.22(h)(2)	Driver failing to maintain ELD instruction sheet	1	0
396.17(c)	Operating a CMV without proof of a periodic inspection	1	0
393.95(a)	No/discharged/unsecured fire extinguisher	1	0
393.75(a)(3)	Tire-flat and/or audible air leak	1	1

The summary counts and rates only include violations that were attributable to LEONFUENTES, MARCOS.

Report executed at: 3/19/2024 11:42:55 AM

MCMIS snapshot date: 02/23/2024

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.

For an explanation of FMCSA-reportable crashes see: <https://www.psp.fmcsa.dot.gov/psp/?redirectUrl=FAQ>