

# PSP Detailed Report

Federal Motor Carrier Safety Administration

Driver Information													
Last Name	First Name	License #	State										
RODRIGUEZLEYVA	ENOLDO	35883079	TX										
RODRIGUEZ	ENOLDO	35883079	TX										
LEYVA	ENOLDO	35883079	TX										

Crash Activity													
Crash Summary (Crashes listed represent a driver's involvement in FMCSA-reportable crashes, without any determination as to responsibility.)													
# of Crashes:	0	# of Crashes with Fatalities:	0	# of Crashes with Injuries:	0	# of Towaways:	0						
# Not preventable:	0	# of Fatalities:	0	# of Injuries:	0	# of Hazmat Releases:	0						
Crash Details (Crashes listed represent a driver's involvement in FMCSA-reportable crashes, without any determination as to responsibility.)													
	Date	DOT #	Carrier Name	Driver Name	Driver Lic	State	Driver DOB	Rpt St	Report Number	Location	# Fatalities	# of Injuries	

Inspection Activity (3 year history from MCMIS snapshot date)													
Inspection Summary													
Driver Summary				Vehicle Summary				Hazmat Summary					
Driver Inspections:		1		Vehicle Inspections:		0		Hazmat Inspections				0	
Driver Out-of-service Inspections:		0		Vehicle Out-of-service Inspections:		0		Hazmat Out-of-service Inspections:				0	
Driver Out-of-service Rate:		0%		Vehicle Out-of-service Rate:		0%		Hazmat Out-of-service Rate:				0%	

Report executed at: 3/29/2024 1:25:42 PM

MCMIS snapshot date: 02/23/2024

For an explanation of FMCSA-reportable crashes see: <https://www.psp.fmcsa.dot.gov/psp/?redirectUrl=FAQ>

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.

Inspection Details												
Carrier Info				Driver Info				Inspection Info				
	Date	DOT #	Carrier Name	Driver Name	Driver Lic	State	Driver DOB	Rpt St	Report Number	Hazmat Insp	Insp Level	# of Viol
1	03/29/2022	2491124	ENOLDO RODRIGUEZ LEYVA	LEYVA, ENOLDO	35883079	TX	07/22/1970	NE	PK00005644	N	3	5
<div>Driver Violation: 392.2 Failure to obey traffic control device NON-OOS</div> <div>Driver Violation: 395.15(a)(2) Driver failed to use automatic on-board recording device when required by the motor carrier. NON-OOS</div> <div>Driver Violation: 395.24(d) ELD cannot transfer ELD records electronically NON-OOS</div> <div>Driver Violation: 395.22(h)(1) Driver failing to maintain ELD user's manual NON-OOS</div> <div>Driver Violation: 395.15(i)(5) Onboard recording device does not display required information NON-OOS</div>												
Violation Summary												
Violation #	Description								# of Violations	# of Out-of-service Violations		
392.2	Failure to obey traffic control device								1	0		
395.15(a)(2)	Driver failed to use automatic on-board recording device when required by the motor carrier.								1	0		
395.24(d)	ELD cannot transfer ELD records electronically								1	0		
395.22(h)(1)	Driver failing to maintain ELD user's manual								1	0		
395.15(i)(5)	Onboard recording device does not display required information								1	0		

The summary counts and rates only include violations that were attributable to RODRIGUEZLEYVA, ENOLDO.

Report executed at: 3/29/2024 1:25:42 PM

MCMIS snapshot date: 02/23/2024

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.

For an explanation of FMCSA-reportable crashes see: <https://www.psp.fmcsa.dot.gov/psp/?redirectUrl=FAQ>