PSP Detailed Report

Federal Motor Carrier Safety Administration

						Driv	/er In	nform	nation											
Last Name First Name							License #					State								
RODRIGUEZ GENARO						R3	362285	731220					FL							
	Crash Activity																			
Crash	Crash Summary (Crashes listed represent a driver's involvement in FMCSA-reportable crashes, without any determination as to responsibility.)																			
# of Crashes: 0						# of Crashes with Fatalities: 0				# of Crashes with Injuries: 0				0	0 # of Tow			vaways:	0	
# Not preventable: 0				0		# of Fatalities: 0				# of Inju			njuries:	0	0 # of Hazmat Re			eleases:	0	
Crash	Details (Cr	ashes listed r	epresent a d	iver's involve	ement i	in FMCSA-reportable cr	rashe	es, wit	thout any de	etermi	ination	as to	respoi	nsibility	.)					
	Date	DOT #	Carr	er Name		Driver Name		Drive	er Lic S	State	Driver	Driver DOB Rpt St Report Number Location # Fatalities					# of Inj	uries		
					lasas					0.000		4 -1 - 4								
-					inspe	ction Activity (3 year	r nist	tory 1		5 sna	apsno	ot date	e)							
Inspec	ction Summ	-																		
		Driver	Summary				Vehicl	le Surr	nmary							Hazmat Sum	mary			
Driver	Inspections:				12	Vehicle Inspections:					7 Hazmat Inspections						0			
Driver Out-of-service Inspections:						Vehicle Out-of-service Inspections:					4 Ha	4 Hazmat Out-of-service Inspections:						0		
Driver Out-of-service Rate:					0%	Vehicle Out-of-service Rate:					57% Hazmat Out-of-service Rate:						0%			
Inspe	ction Detail	s																		
Carrie	er Info				Drive	r Info								Inspect	tion In	fo				
	Date	DOT #	Carri	er Name		Driver Name			Driver Lic State		State	Drive	er DOB	Rpt St	Rep	ort Number	Hazmat Insp	Insp		# of Viol
1	05/06/202	1 3519641		ISLOGISTICS DRP	RODR	IGUEZ, GENARO		F	36228573122	20	FL	04/02	2/1973	GA	11	83000069	N	3	3	1
	Driver Violation: 395.26(b) Motor carrier failed to ensure that the ELD automatically recorded the required data elements. NON-OOS																			

Report executed at: 5/3/2024 2:12:50 PM

MCMIS snapshot date: 04/26/2024

2	06/12/2021	3519641	M & K TRANSLOGISTI CORP	ICS RO	DDRIGUEZ, GENARO	R362285731220	FL	04/02/1973	MO	W092000338	N	1	3	
	Vehicle \	/iolation:	393.45(d)	Brake Cor	nnections with Leaks - Connection to Po	wer Unit	NON-C	OS						
	Vehicle \	/iolation:	393.45(b)(2)	Brake Hos	ose or Tubing Chafing and/or Kinking Und	er Vehicle	NON-C	OOS						
	Vehicle \	/iolation:	393.9(a)	Inoperable	le Required Lamp		C	OS						
3	12/09/2021	3583845	M & K TRANSPORT GR CORP	OUP RO	DDRIGUEZ, GENARO	R362285731220	FL	04/02/1973	AZ	0319000803	N	2	4	
	Driver Vi	olation:			led to have on-board a CMV a sufficient s f duty status graph-grids.	upply of blank	NON-C	OOS						
	Vehicle \	/iolation:			fective ABS Malfunction Indicator Lamp for tured after 03/01/1998	or trailer	NON-C	OOS						
Vehicle Violation:		/iolation:	393.11	Truck-Trac sheeting o July 1997	actor upper body corner requirements for or reflex reflective material for vehicles m 7	NON-OOS								
	Driver Vi	olation:	395.8	Record of	f Duty Status violation (general/form and	manner)	NON-C	OS						
4	02/17/2022	3583845	M & K TRANSPORT GR CORP	OUP RO	DDRIGUEZ, GENARO	R362285731220	FL	04/02/1973	тх	68JE0XJJAG	N	2	3	
	Vehicle \	/iolation:	393.9(a)	Inoperable	le Required Lamp		C	OS						
	Vehicle \	/iolation:	393.9(a)	Inoperable	le Required Lamp		NON-C	OOS						
	Vehicle \	/iolation:	393.9(a)	a) Inoperable Required Lamp				NON-OOS						
5	12/09/2022	3583845	M & K TRANSPORT GR CORP	OUP RO	DDRIGUEZ, GENARO	R362285731220	FL	04/02/1973	FL	3305005316	N	2	1	
	Vehicle \	/iolation:	393.75(a)(3)	Tire-flat ar	and/or audible air leak		C	OOS						
6	12/18/2022	3583845	M & K TRANSPORT GR CORP	OUP RO	DDRIGUEZ, GENARO	R362285731220	FL	04/02/1973	LA	LANK001891	N	3	1	
	Driver Vi	olation:	395.24(d)	ELD cann	not transfer ELD records electronically		NON-C	OS						
7	04/05/2023	3583845	M & K TRANSPORT GR CORP	OUP RO	DDRIGUEZ, GENARO	R362285731220	FL	04/02/1973	LA	LALD008697	N	3	2	
	Driver Vi	olation:	392.22(a)	Failing to	use hazard warning flashers		NON-C	OOS						
	Driver Vi	olation:		Failure to place or improper placement of warning devices on the road surface			NON-OOS							
8	10/12/2023	2420847	AJ LOGISTICS TRANSP INC	ORT RO	DDRIGUEZ, GENARO	R362285731220	FL	04/02/1973	NC	0006584241	Ν	1	5	

Report executed at: 5/3/2024 2:12:50 PM

MCMIS snapshot date: 04/26/2024

	Vehicle V	violation:	393.75(a)	Flat tire or fabric exposed		(DOS					
	Vehicle V	violation:	393.48(a)	Inoperative/defective brakes		NON-0	DOS					
	Vehicle V	violation:	393.47(e)	Brake Out of Adjustment - Roto, Clamp (Short of Bolt	& Long), DD-3, or	NON-0	DOS					
	Vehicle \	violation:	396.3(a)(1)	BRAKES OUT OF SERVICE: The number of d equal to or greater than 20 percent of the servic vehicle or combination		C	DOS					
	Vehicle V	violation:	393.47(e)	Brake Out of Adjustment - Roto, Clamp (Short of Bolt	& Long), DD-3, or	NON-0	DOS					
9	01/19/2024	2260927	FIRST TRUCKING XTF	REME RODRIGUEZ, GENARO	R362285731220	FL	04/02/1973	NM	6290O0JM53	N	3	1
	Driver Vi	olation:	392.2	Failure to obey traffic control device		NON-0	DOS	-			-	
10	03/26/2024	2260927	FIRST TRUCKING XTF	REME RODRIGUEZ, GENARO ENRIQUE	R362285731220	FL	04/02/1973	MS	5020010526	N	2	1
	Driver Vi	olation:	395.24(d)	ELD cannot transfer ELD records electronically		NON-0	DOS					
11	03/30/2024	2260927	FIRST TRUCKING XTF	REME RODRIGUEZ, GENARO	R362285731220	FL	04/02/1973	GA	1424000186	N	3	0
		•			•							
12	04/16/2024	2260927	FIRST TRUCKING XTF	REME RODRIGUEZ, GENARO	R362285731220	FL	04/02/1973	KY	CV44780845	N	1	1
	Driver Vi	olation:	392.2	Violation of Local Laws - Explain:	•	NON-0	DOS					
Violati												
Violati	on Summary											
	olation #			Description					# of Violati	ons	# of Out-of- Violatio	
	olation #		to have on-board a CMV :	Description a sufficient supply of blank records of duty status	graph-grids.				# of Violati	i <mark>ons</mark> 1		ons
Vi	olation # g)(2)	Driver failed t			<u> </u>				# of Violati	ions 1 1		ons 0
V i 395.15(olation # g)(2)	Driver failed t No or Defecti	ive ABS Malfunction Indic	a sufficient supply of blank records of duty status	98	manufac	tured after July	1997	# of Violati	ions 1 1 1		ons 0 0
Vi 395.15(393.55(olation # g)(2)	Driver failed t No or Defecti Truck-Tractor	ive ABS Malfunction Indic	a sufficient supply of blank records of duty status ator Lamp for trailer manufactured after 03/01/19 rements for retroreflective sheeting or reflex refle	98	manufac	tured after July	1997	# of Violati	ions 1 1 1 1		ons 0 0 0
Vi 395.15(393.55(393.11	olation # g)(2) e)	Driver failed t No or Defecti Truck-Tractor Record of Du	ive ABS Malfunction Indic r upper body corner requi	a sufficient supply of blank records of duty status ator Lamp for trailer manufactured after 03/01/19 rements for retroreflective sheeting or reflex refle al/form and manner)	98	manufac	tured after July	1997	# of Violati	ions 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1		0 0 0 0 0
Vi 395.15(393.55(393.11 395.8	olation # g)(2) e) a)	Driver failed t No or Defecti Truck-Tractor Record of Du Failing to use	ive ABS Malfunction Indic r upper body corner requi ity Status violation (gener e hazard warning flashers	a sufficient supply of blank records of duty status ator Lamp for trailer manufactured after 03/01/19 rements for retroreflective sheeting or reflex refle al/form and manner)	98	manufac	tured after July	1997	# of Violati	ons 1 1 1 1 1 1 1		
Vi 395.15(393.55(393.11 395.8 392.22(a) b)	Driver failed t No or Defecti Truck-Tractor Record of Du Failing to use Failure to pla	ive ABS Malfunction Indic r upper body corner requi ity Status violation (gener e hazard warning flashers	a sufficient supply of blank records of duty status ator Lamp for trailer manufactured after 03/01/19 rements for retroreflective sheeting or reflex refle al/form and manner)	98	manufac	tured after July	1997	# of Violati	ons 1 1 1 1 1 1 1 1 1 4		0 0 0 0 0 0
395.15(393.55(393.11 395.8 392.22(392.22(a) b)	Driver failed t No or Defecti Truck-Tractor Record of Du Failing to use Failure to pla	ive ABS Malfunction Indic r upper body corner requi uty Status violation (gener a hazard warning flashers ace or improper placemen equired Lamp	a sufficient supply of blank records of duty status ator Lamp for trailer manufactured after 03/01/19 rements for retroreflective sheeting or reflex refle al/form and manner)	98	manufac	tured after July	1997	# of Violati	1 1 1 1 1 1 1		0 0 0 0 0 0 0 0
Vi 395.15(393.55(393.11 395.8 392.22(392.22(393.9(a	a) b) a)	Driver failed t No or Defecti Truck-Tractor Record of Du Failing to use Failure to pla Inoperable R Flat tire or fat	ive ABS Malfunction Indic r upper body corner requi uty Status violation (gener a hazard warning flashers ace or improper placemen equired Lamp	a sufficient supply of blank records of duty status ator Lamp for trailer manufactured after 03/01/19 rements for retroreflective sheeting or reflex refle al/form and manner)	98	manufac	tured after July	1997	# of Violati	1 1 1 1 1 1 1		ons 0 0 0 0 0 0 0 0 2
Vi 395.15(393.55(393.11 395.8 392.22(392.22(393.9(a 393.75(a) b) a) a) b) b) b) a)	Driver failed t No or Defecti Truck-Tractor Record of Du Failing to use Failure to pla Inoperable R Flat tire or fat Inoperative/d	ive ABS Malfunction Indic r upper body corner requi ity Status violation (gener a hazard warning flashers ice or improper placemen equired Lamp bric exposed lefective brakes	a sufficient supply of blank records of duty status ator Lamp for trailer manufactured after 03/01/19 rements for retroreflective sheeting or reflex refle al/form and manner)	98	manufac	tured after July	1997	# of Violati	1 1 1 1 1 1 1		0 1

Report executed at: 5/3/2024 2:12:50 PM

MCMIS snapshot date: 04/26/2024

392.2	Violation of Local Laws - Explain:	2	0
393.75(a)(3)	Tire-flat and/or audible air leak	1	1
395.26(b)	Motor carrier failed to ensure that the ELD automatically recorded the required data elements.	1	0
395.24(d)	ELD cannot transfer ELD records electronically	2	0
393.45(d)	Brake Connections with Leaks - Connection to Power Unit	1	0
393.45(b)(2)	Brake Hose or Tubing Chafing and/or Kinking Under Vehicle	1	0

The summary counts and rates only include violations that were attributable to RODRIGUEZ, GENARO.

Report executed at: 5/3/2024 2:12:50 PM MCMIS snapshot date: 04/26/2024