

# PSP Detailed Report

Federal Motor Carrier Safety Administration

Driver Information															
Last Name		First Name		License #			State								
GONZALEZ		ALEXIS		G524000671500			FL								
Crash Activity															
Crash Summary (Crashes listed represent a driver's involvement in FMCSA-reportable crashes, without any determination as to responsibility.)															
# of Crashes:		0		# of Crashes with Fatalities:		0		# of Crashes with Injuries:		0		# of Towaways:		0	
# Not preventable:		0		# of Fatalities:		0		# of Injuries:		0		# of Hazmat Releases:		0	
Crash Details (Crashes listed represent a driver's involvement in FMCSA-reportable crashes, without any determination as to responsibility.)															
	Date	DOT #	Carrier Name	Driver Name	Driver Lic	State	Driver DOB	Rpt St	Report Number	Location	# Fatalities	# of Injuries			
Inspection Activity (3 year history from MCMIS snapshot date)															
Inspection Summary															
Driver Summary				Vehicle Summary				Hazmat Summary							
Driver Inspections:		6		Vehicle Inspections:		4		Hazmat Inspections				0			
Driver Out-of-service Inspections:		0		Vehicle Out-of-service Inspections:		3		Hazmat Out-of-service Inspections:				0			
Driver Out-of-service Rate:		0%		Vehicle Out-of-service Rate:		75%		Hazmat Out-of-service Rate:				0%			
Inspection Details															
Carrier Info				Driver Info				Inspection Info							
	Date	DOT #	Carrier Name	Driver Name	Driver Lic	State	Driver DOB	Rpt St	Report Number	Hazmat Insp	Insp Level	# of Viol			
1	11/17/2021	2540798	MERCATOR GLOBAL LOGISTICS LLC	GONZALEZ, ALEXIS	G524000671500	FL	04/30/1967	OK	PE11182291	N	1	2			
Vehicle Violation:		393.78		Wipers - Inoperative / missing / damaged wipers.				NON-OOS							
Vehicle Violation:		393.45		Brake tubing and hose adequacy				OOS							

Report executed at: 5/27/2024 11:00:01 AM

MCMIS snapshot date: 04/26/2024

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.

For an explanation of FMCSA-reportable crashes see: <https://www.psp.fmcsa.dot.gov/psp/?redirectUrl=FAQ>

2	10/12/2022	2540798	MERCATOR GLOBAL LOGISTICS LLC	GONZALEZ, ALEXIS	G524000671500	FL	04/30/1967	AZ	0331000258	N	3	1
Co-Driver Violation: 395.8(e)(1) False report of drivers record of duty status NON-OOS - This violation does NOT apply to GONZALEZ, ALEXIS.												
3	11/17/2022	2582155	GLOBAL LOGISTICS FREIGHT LLC	GONZALEZ, ALEXIS	G524000671500	FL	04/30/1967	SC	L347000956	N	3	0
4	07/12/2023	3509638	NOVA FREIGHT LLC	GONZALEZ, ALEXIS	G524000671500	FL	04/30/1967	WY	PMRH000040	N	1	2
Vehicle Violation: 393.75(a)(3) Tire-flat and/or audible air leak OOS												
Vehicle Violation: 393.75(c) Tire-other tread depth less than 1/32 of inch measured in 2 adjacent major tread grooves 3 separate locations 8 inches apart NON-OOS												
5	09/04/2023	3509638	NOVA FREIGHT LLC	GONZALEZ, ALEXIS	G524000671500	FL	04/30/1967	TX	V231130933	N	2	0
6	10/16/2023	3509638	NOVA FREIGHT LLC	GONZALEZ, ALEXIS	G524000671500	FL	04/30/1967	OH	3245015759	N	1	3
Driver Violation: 395.20(b) The ELDs display screen cannot be viewed outside of the commercial motor vehicle. NON-OOS												
Vehicle Violation: 393.47(b) Mis-matched brake chambers on same axle NON-OOS												
Vehicle Violation: 392.9(a)(2) Failing to secure vehicle equipment OOS												
<b>Violation Summary</b>												
Violation #	Description								# of Violations	# of Out-of-service Violations		
393.78	Wipers - Inoperative / missing / damaged wipers.								1	0		
393.45	Brake tubing and hose adequacy								1	1		
393.75(a)(3)	Tire-flat and/or audible air leak								1	1		
393.75(c)	Tire-other tread depth less than 1/32 of inch measured in 2 adjacent major tread grooves 3 separate locations 8 inches apart								1	0		
395.20(b)	The ELDs display screen cannot be viewed outside of the commercial motor vehicle.								1	0		
393.47(b)	Mis-matched brake chambers on same axle								1	0		
392.9(a)(2)	Failing to secure vehicle equipment								1	1		

The summary counts and rates only include violations that were attributable to GONZALEZ, ALEXIS.

Report executed at: 5/27/2024 11:00:01 AM

MCMIS snapshot date: 04/26/2024

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.

For an explanation of FMCSA-reportable crashes see: <https://www.psp.fmcsa.dot.gov/psp/?redirectUrl=FAQ>