

# PSP Detailed Report

Federal Motor Carrier Safety Administration

Driver Information																			
Last Name	First Name			License #			State												
PADRONARROCHA	SERGIO			P365781634670			FL												
PADRON	SERGIO ALEJANDRO			P365781634670			FL												
AROCHA	SERGIO ALEJANDRO			P365781634670			FL												
Crash Activity																			
Crash Summary (Crashes listed represent a driver's involvement in FMCSA-reportable crashes, without any determination as to responsibility.)																			
# of Crashes:		0		# of Crashes with Fatalities:		0		# of Crashes with Injuries:		0		# of Towaways:		0					
# Not preventable:		0		# of Fatalities:		0		# of Injuries:		0		# of Hazmat Releases:		0					
Crash Details (Crashes listed represent a driver's involvement in FMCSA-reportable crashes, without any determination as to responsibility.)																			
Date	DOT #	Carrier Name	Driver Name	Driver Lic	State	Driver DOB	Rpt St	Report Number	Location	# Fatalities	# of Injuries								
Inspection Activity (3 year history from MCMIS snapshot date)																			
Inspection Summary																			
Driver Summary				Vehicle Summary				Hazmat Summary											
Driver Inspections:				5				Vehicle Inspections:				3				Hazmat Inspections:		0	
Driver Out-of-service Inspections:				0				Vehicle Out-of-service Inspections:				2				Hazmat Out-of-service Inspections:		0	
Driver Out-of-service Rate:				0%				Vehicle Out-of-service Rate:				67%				Hazmat Out-of-service Rate:		0%	

Report executed at: 6/5/2024 3:26:26 PM

MCMIS snapshot date: 04/26/2024

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.

For an explanation of FMCSA-reportable crashes see: <https://www.psp.fmcsa.dot.gov/psp/?redirectUrl=FAQ>

Inspection Details												
Carrier Info				Driver Info				Inspection Info				
	Date	DOT #	Carrier Name	Driver Name	Driver Lic	State	Driver DOB	Rpt St	Report Number	Hazmat Insp	Insp Level	# of Viol
1	06/29/2021	2341009	VELOX TRANSPORT SOLUTIONS LLC	PADRON, SERGIO	P365781634670	FL	12/27/1963	VA	7760000252	N	3	1
Driver Violation: 395.22(h)(4)				Driver failed to maintain supply of blank drivers records of duty status graph-grids			NON-OOS					
2	08/10/2022	2158062	TRANS AMERICAN EXPRESS INC	PADRON AROCHA, SERGIO	P365781634670	FL	12/27/1963	AL	1712001592	N	2	3
Vehicle Violation: 393.75(a)(3)				Tire-flat and/or audible air leak			OOS					
Vehicle Violation: 393.75(a)(3)				Tire-flat and/or audible air leak			OOS					
Vehicle Violation: 396.3(a)(1)				Inspection, repair and maintenance of parts and accessories			NON-OOS					
3	01/10/2023	2158062	TRANS AMERICAN EXPRESS INC	PADRON AROCHA, SERGIO	P365781634670	FL	12/27/1963	NM	2599N0AB3S	N	2	2
Vehicle Violation: 393.75(a)(3)				Tire-flat and/or audible air leak			OOS					
Vehicle Violation: 393.75(a)(3)				Tire-flat and/or audible air leak			OOS					
4	02/24/2023	2158062	TRANS AMERICAN EXPRESS INC	PADRON AROCHA, SERGIO	P365781634670	FL	12/27/1963	KS	HP92021817	N	3	2
Driver Violation: 395.22(h)(1)				Driver failing to maintain ELD user's manual			NON-OOS					
Driver Violation: 395.22(h)(4)				Driver failed to maintain supply of blank drivers records of duty status graph-grids			NON-OOS					
5	02/10/2024	2158062	TRANS AMERICAN EXPRESS INC	PADRON AROCHA, SERGIO	P365781634670	FL	12/27/1963	ID	3512003389	N	2	0
Violation Summary												
Violation #	Description								# of Violations	# of Out-of-service Violations		
395.22(h)(1)	Driver failing to maintain ELD user's manual								1	0		
395.22(h)(4)	Driver failed to maintain supply of blank drivers records of duty status graph-grids								2	0		
393.75(a)(3)	Tire-flat and/or audible air leak								4	4		
396.3(a)(1)	Inspection, repair and maintenance of parts and accessories								1	0		

The summary counts and rates only include violations that were attributable to PADRONARROCHA, SERGIO.

Report executed at: 6/5/2024 3:26:26 PM

MCMIS snapshot date: 04/26/2024

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.

For an explanation of FMCSA-reportable crashes see: <https://www.psp.fmcsa.dot.gov/psp/?redirectUrl=FAQ>