PSP Detailed Report

Federal Motor Carrier Safety Administration

						Drive	er Info	orm	ation											
Last Name First Name				rst Name L				License #				State								
TEJADA JOSUE				OSUE			P223	34247	743610					FL						
PACHE	COTEJADA			OSUE			P223	34247	743610					FL						
PACHE	CO			OSUE			P223	3424	743610					FL						
						Cr	ash A	Activ	vity											
Crash	Summary (C	rashes liste	d represent a o	lriver's invo	lvemer	nt in FMCSA-reportable	crash	ies, v	without any	deter	rminat	ion as	s to res	ponsibil	ity.)					
		#	of Crashes: 0			# of Crashes with Fata	lities:	0			# of	Crash	nes with I	njuries:	ies: 0			# of Towaways		
		# Not	preventable: 0			# of Fata	lities:	0	# of I			Injuries: 0 # of Hazı			mat Releases: 0		0			
Crash	Details (Cra	shes listed r	epresent a driv	er's involve	ment i	n FMCSA-reportable cra	ashes	, wit	hout any de	termi	inatior	n as to	o respor	nsibility	.)					
	Date	DOT #	Carrier	Name	Driver Name			Driver Lic State			Driver DOB Rpt St			pt St Report Number		Locatio	n #Fata	lities # o	f Injuri	es
					_															
-					Inspe	ction Activity (3 year	histo	ory f		S sna	apsho	ot dat	te)							
Inspe	ction Summa	-																		
		Driver	Summary			Vehicle Summary				_	Hazmat Summary									
Driver	Inspections:				14	Vehicle Inspections:			9 Hazmat In				at Inspections						0	
Driver	Out-of-service	Inspections:			1	1 Vehicle Out-of-service Inspections:				2 Hazmat O			Out-of-service Inspections:					0		
Driver Out-of-service Rate:					7%	7% Vehicle Out-of-service Rate:				22% Hazmat Or				Out-of-service Rate:					(0%
Inspe	ction Details																			
Carrier Info				Driver Info					Inspection Info											
Date DOT # Carr			Carrier	Name		Driver Name			Driver Lic	:	State	Drive	er DOB	Rpt St	Report	Number	Hazmat Insp	Insp Leve	l #o Vic	
1	10/28/2021	2470096	PAK AUTO TRA		PACHE	ECO TEJADA, JOSUE (co-	driver)	P	22342474361	0	FL	10/0)1/1974	СТ	0491	000158	N	2	3	

Report executed at: 7/2/2024 1:56:26 PM

MCMIS snapshot date: 05/31/2024

Driver Violation:		on:	395.8	Record of Duty Status violation (general/form and	NON-OOS - This violation does NOT apply to PACHECO TEJADA, JOSUE.									
	Vehicle Violation:		396.3(a)(1)	Tires (general)	NON-OOS - This violation does NOT apply to PACHECO TEJADA, JOSUE.									
Vehicle Violation:			393.75(c) Tire-other tread depth less than 1/32 of inch measured in 2 adjacent major tread grooves 3 separate locations 8 inches apart				NON-OOS - This violation does NOT apply to PACHECO TEJADA, JOSUE.							
2	12/16/2021 24	470096	PAK AUTO TRANSPORT LLC	ERS PACHECO TEJADA, JOSUE	P223424743610	FL	10/01/1974	NM	1355L9Q7VG	N	2	9		
	Vehicle Violat	tion:	390.21(a)	Not marked in accordance with regulations		NON-C	DOS							
	Vehicle Violat	tion:	393.95(a)	No/discharged/unsecured fire extinguisher		NON-C	DOS							
	Vehicle Violat	tion:		No or Defective ABS Malfunction Indicator Lamp manufactured after 03/01/1998	for trailer	NON-C	DOS							
	Vehicle Violat	tion:	393.9(a)	Inoperable Required Lamp		NON-C	DOS							
	Driver Violatio	on:		The driver failed to include name of co-driver for period.	NON-C	DOS								
	Driver Violatio	on:		Driver failed to record driver signature/certification for each 24 hour NON-OOS period.										
	Driver Violatio	on:	395.24(c)(2)(ii)	Driver failed to manually add the trailer number	NON-OOS									
	Driver Violatio	on:	395.24(c)(2)(iii)	Driver failed to manually add shipping document	NON-OOS									
Driver Violation:			392.2	2.2 Violation of Local Laws - Explain:										
3	01/16/2022 2	789894	365 LOGISTICS LLC	PACHECO TEJADA, JOSUE	P223424743610	FL	10/01/1974	WA	W428003800	N	1			
	Driver Violatio	on:	395.3(a)(2)	Driving beyond 14 hour duty period (Property car	rrying vehicle)	NON-C	DOS							
	Driver Violatio	on:	395.24(c)(1)(i)	Driver failed to make annotations when applicabl	e	NON-C	DOS							
Vehicle Violation:		tion:	393.78	Wipers - Inoperative / missing / damaged wipers		NON-C	DOS							
	Vehicle Violat	tion:	393.9(a)	Inoperable tail lamp	NON-OOS									
	Vehicle Violat	tion:	393.45(d)	Brake Connections with Leaks Under Vehicle	OOS									
	Vehicle Violat	tion:	393.9(a)	Inoperable tail lamp	NON-OOS									
	Vehicle Violat	tion:	393.47(a)	Inadequate brakes for safe stopping - Brake Lining condition										
Ļ	01/25/2022 2	789894	365 LOGISTICS LLC	PACHECO TEHADA, JOSUE	P223424743610	FL	10/01/1974	GA	1394000150	N	2	Т		
	Vehicle Violat	tion:	393.11 No or defective lighting devices or reflective material as required			NON-C	DOS					_		
Vehicle Violation: Vehicle Violation:		tion:	396.17(c)	Operating a CMV without proof of a periodic insp	NON-OOS									
		tion:	393.9(a)	Inoperable Required Lamp			NON-OOS							
Vehicle Violation: 39			393.11				NON-OOS							
5	01/28/2022 2	789894	365 LOGISTICS LLC	PACHECO TEJADA, JOSUE	P223424743610	FL	10/01/1974	MT	G655010191	N	3			
-														

Report executed at: 7/2/2024 1:56:26 PM

MCMIS snapshot date: 05/31/2024

7	11/29/2022 3296422	DULCE CORE LANDSCAPING CORP	PACHECO TEJADA, JOSUE	P223424743610	FL	10/01/1974	TN	TCIY003951	N	1	1				
	Driver Violation:	395.24(d) ELI	Cannot transfer ELD records electronically		NON-C	DOS					<u>.</u>				
8	02/22/2023 3296422	DULCE CORE LANDSCAPING CORP	TEJADA, JOSUE	P223424743610	FL	10/01/1974	IN	8285011258	N	1	4				
	Vehicle Violation:		V manufactured after 10/19/94 has an automa ustment system that fails to compensate for we		NON-C	DOS									
	Vehicle Violation:	393.47(e) Bra Bol	ke Out of Adjustment - Roto, Clamp (Short & L t	∟ong), DD-3, or	NON-C	DOS									
	Vehicle Violation:	393.47(e) Bra Bol	ke Out of Adjustment - Roto, Clamp (Short & L t	₋ong), DD-3, or	NON-C	DOS									
	Vehicle Violation:	393.47(e) Bra Bol	ke Out of Adjustment - Roto, Clamp (Short & L t	_ong), DD-3, or	NON-OOS										
9	03/30/2023 3296422	DULCE CORE LANDSCAPING CORP	PACHECO TEJADA, JOSUE (co-driver)	P223424743610	FL	10/01/1974	GA	1403000497	N	3	6				
	Driver Violation:		ver failed to certify the accuracy of the informat ELD	tion gathered by	NON-C	DOS - This viol	ation doe	s NOT apply to PACH	IECO TEJA	DA, JOSUE.					
	Driver Violation:	395.22(h)(1) Driv	ver failing to maintain ELD user's manual	NON-OOS - This violation does NOT apply to PACHECO TEJADA, JOSUE.											
	Driver Violation:	395.22(h)(2) Driv	22(h)(2) Driver failing to maintain ELD instruction sheet					NON-OOS - This violation does NOT apply to PACHECO TEJADA, JOSUE.							
	Driver Violation:		22(h)(3) Driver failed to maintain instruction sheet for ELD malfunction reporting requirements				NON-OOS - This violation does NOT apply to PACHECO TEJADA, JOSUE.								
	Driver Violation:		 Driver failed to maintain supply of blank drivers records of duty status graph-grids 				NON-OOS - This violation does NOT apply to PACHECO TEJADA, JOSUE.								
	Driver Violation:	392.82(a)(1) Usi	(a)(1) Using a hand-held mobile telephone while operating a CMV			NON-OOS - This violation does NOT apply to PACHECO TEJADA, JOSUE.									
10	04/18/2023 3296422	DULCE CORE LANDSCAPING CORP	PACHECO TEJADA, JOSUE	P223424743610	FL	10/01/1974	VA	6671001868	N	3	1				
	Driver Violation:	395.8(e)(1) Fal	se report of drivers record of duty status		C	DOS									
11	06/25/2023 3296422	DULCE CORE LANDSCAPING CORP	PACHECO TEJADA, JOSUE	P223424743610	FL	10/01/1974	UT	23TO000323	N	2	7				
	Vehicle Violation:	393.45(b)(2) Bra Uni	ke Hose or Tubing Chafing and/or Kinking - Co t	onnection to Power	C	DOS									
	Vehicle Violation:	393.201(a) Frame cracked / loose / sagging / broken			NON-OOS										
	Vehicle Violation:	393.48(a) Ino	393.48(a) Inoperative/defective brakes			NON-OOS									
	Vehicle Violation:	393.55(d)(3) No or Defective ABS Malfunction Indicator for towed vehicles on vehicles manufactured after February 2001			NON-OOS										
	Vehicle Violation:	396.9(d)(2) Failure to correct defects noted on previous inspection report			NON-OOS										
	Driver Violation:	395.32(b) Driver failed to assume or decline unassigned driving time			NON-OOS										
	Driver Violation:	395.8 Re	395.8 Record of Duty Status violation (general/form and manner)			NON-OOS									
12	10/09/2023 3296422	DULCE CORE LANDSCAPING CORP	PACHECO TEJADA, JOSUE	P223424743610	FL	10/01/1974	SC	G222009268	N	3	1				
	Driver Violation:	395.8(e)(1) Fal	se report of drivers record of duty status		NON-C	DOS									

Report executed at: 7/2/2024 1:56:26 PM

MCMIS snapshot date: 05/31/2024

13	11/06/2023	3296422	DULCE CORE LANDSCAPING CORP	PACHECO TEJADA, JOSUE	P223424743610	FL	10/01/1974	FL	9010000448	N	2	4	
	Driver Vi	olation:	392.2 Failur	e to obey traffic control device		NON-0	DOS						
	Vehicle V	/iolation:	396.17(c) Opera	ating a CMV without proof of a periodic insp	ection	NON-0	DOS						
	Vehicle \	/iolation:	393.60(c) Winds	shield - Damaged or Discolored		NON-0	DOS						
	Vehicle V	/iolation:	396.17(c) Opera	ating a CMV without proof of a periodic insp	ection	NON-0	DOS						
14	01/05/2024	3296422	DULCE CORE LANDSCAPING CORP	PACHECO TEJADA, JOSUE	P223424743610	FL	10/01/1974	VA	776000008	N	1	0	
Vielet													
	on Summary												
Vi	olation #			Description					# of Violation	ons	# of Out-of-service Violations		
390.21(a)	Not marked i	n accordance with regulations							1	0		
393.95(a)	No/discharge	ed/unsecured fire extinguisher							1	0		
393.55(e)	No or Defect	ive ABS Malfunction Indicator La	mp for trailer manufactured after 03/01/199	8					0			
393.9(a)	Inoperable R	equired Lamp							0			
395.8(d)(9)	The driver fa	iled to include name of co-driver	for each 24 hour period.						1		C	
395.8(f)	(7)	Driver failed	to record driver signature/certification	ation for each 24 hour period.						1		C	
395.24(c)(2)(ii)	Driver failed	to manually add the trailer numb	PL							C		
395.24(c)(2)(iii)	Driver failed	to manually add shipping docum	ent number						1		C	
392.2 Violation of Local Laws - Explain:										2		C	
393.53(b)	CMV manufa	ctured after 10/19/94 has an aut	omatic airbrake adjustment system that fails	s to compensate for wea	ar				1		C	
393.47(7(e) Brake Out of Adjustment - Roto, Clamp (Short & Long), DD-3, or Bolt							3					
395.24(d)	ELD cannot t	ransfer ELD records electronical	ly						1		C	
395.8(e	.8(e)(1) False report of drivers record of duty status								2		1		
396.17(7(c) Operating a CMV without proof of a periodic inspection							3		C			
393.60(c)	Windshield - Damaged or Discolored								1		C	
393.11		No or defective lighting devices or reflective material as required								2		C	
393.45(b)(2)	Brake Hose or Tubing Chafing and/or Kinking - Connection to Power Unit								1		1	
393.201	(a)	Frame cracked / loose / sagging / broken								1		C	
393.48(a)	Inoperative/defective brakes								1		C	
393.55(d)(3)	No or Defect	ive ABS Malfunction Indicator for	towed vehicles on vehicles manufactured a	after February 2001					1		C	
396.9(d)(2)	Failure to cor	rect defects noted on previous ir	spection report						1		C	

Report executed at: 7/2/2024 1:56:26 PM

MCMIS snapshot date: 05/31/2024

395.32(b)	Driver failed to assume or decline unassigned driving time	1	0
395.8	Record of Duty Status violation (general/form and manner)	1	0
395.3(a)(2)	Driving beyond 14 hour duty period (Property carrying vehicle)	1	0
395.24(c)(1)(i)	Driver failed to make annotations when applicable	1	0
393.78	Wipers - Inoperative / missing / damaged wipers.	1	0
393.45(d)	Brake Connections with Leaks Under Vehicle	1	1
393.47(a)	Inadequate brakes for safe stopping - Brake Lining condition	1	1

The summary counts and rates only include violations that were attributable to TEJADA, JOSUE.

Report executed at: 7/2/2024 1:56:26 PM MCMIS snapshot date: 05/31/2024