

PSP Detailed Report

Federal Motor Carrier Safety Administration

Driver Information													
Last Name	First Name	License #	State										
MELGAR	JUAN JOSE	42874235	TX										
BANEGASMELGAR	JUAN	42874235	TX										
BANEGAS	JUAN JOSE	42874235	TX										

Crash Activity													
Crash Summary (Crashes listed represent a driver's involvement in FMCSA-reportable crashes, without any determination as to responsibility.)													
# of Crashes:	0	# of Crashes with Fatalities:	0	# of Crashes with Injuries:	0	# of Towaways:	0						
# Not preventable:	0	# of Fatalities:	0	# of Injuries:	0	# of Hazmat Releases:	0						
Crash Details (Crashes listed represent a driver's involvement in FMCSA-reportable crashes, without any determination as to responsibility.)													
	Date	DOT #	Carrier Name	Driver Name	Driver Lic	State	Driver DOB	Rpt St	Report Number	Location	# Fatalities	# of Injuries	

Inspection Activity (3 year history from MCMIS snapshot date)													
Inspection Summary													
Driver Summary				Vehicle Summary				Hazmat Summary					
Driver Inspections:		2		Vehicle Inspections:		1		Hazmat Inspections				0	
Driver Out-of-service Inspections:		0		Vehicle Out-of-service Inspections:		1		Hazmat Out-of-service Inspections:				0	
Driver Out-of-service Rate:		0%		Vehicle Out-of-service Rate:		100%		Hazmat Out-of-service Rate:				0%	

Report executed at: 7/6/2024 12:40:39 PM

MCMIS snapshot date: 06/28/2024

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.

For an explanation of FMCSA-reportable crashes see: <https://www.psp.fmcsa.dot.gov/psp/?redirectUrl=FAQ>

Inspection Details												
Carrier Info				Driver Info				Inspection Info				
	Date	DOT #	Carrier Name	Driver Name	Driver Lic	State	Driver DOB	Rpt St	Report Number	Hazmat Insp	Insp Level	# of Viol
1	04/05/2024	2307400	U M G A LOGISTICS INC	BANEGAS MELGAR, JUAN	42874235	TX	06/12/1979	MO	W014000211	N	3	0
2	04/11/2024	2307400	U M G A LOGISTICS INC	BANEGAS MELGAR, JUAN	42874235	TX	06/12/1979	IA	000P142L9S	N	1	11
Vehicle Violation: 393.45(d) Brake connections with leaks or constrictions NON-OOS												
Vehicle Violation: 393.9(a) Inoperable tail lamp NON-OOS												
Vehicle Violation: 393.11 No or defective lighting devices or reflective material as required NON-OOS												
Vehicle Violation: 393.95(a) No/discharged/unsecured fire extinguisher NON-OOS												
Vehicle Violation: 393.75(c) Tire-other tread depth less than 2/32 of inch measured in a major tread groove NON-OOS												
Vehicle Violation: 396.3(a)(1) Brake - Leak from air chamber NON-OOS												
Vehicle Violation: 393.48(a) Inoperative/defective brakes NON-OOS												
Vehicle Violation: 393.47(e) Brake Out of Adjustment - Roto, Clamp (Short & Long), DD-3, or Bolt NON-OOS												
Vehicle Violation: 393.53(b) CMV manufactured after 10/19/94 has an automatic airbrake adjustment system that fails to compensate for wear NON-OOS												
Vehicle Violation: 396.3(a)(1) BRAKES OUT OF SERVICE: The number of defective brakes is equal to or greater than 20 percent of the service brakes on the vehicle or combination OOS												
Vehicle Violation: 396.17(c) Operating a CMV without proof of a periodic inspection NON-OOS												
Violation Summary												
Violation #		Description							# of Violations		# of Out-of-service Violations	
393.45(d)		Brake connections with leaks or constrictions							1		0	
393.9(a)		Inoperable tail lamp							1		0	
393.11		No or defective lighting devices or reflective material as required							1		0	
393.95(a)		No/discharged/unsecured fire extinguisher							1		0	
393.75(c)		Tire-other tread depth less than 2/32 of inch measured in a major tread groove							1		0	
396.3(a)(1)		Brake - Leak from air chamber							2		1	
393.48(a)		Inoperative/defective brakes							1		0	
393.47(e)		Brake Out of Adjustment - Roto, Clamp (Short & Long), DD-3, or Bolt							1		0	

Report executed at: 7/6/2024 12:40:39 PM

MCMIS snapshot date: 06/28/2024

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.

393.53(b)	CMV manufactured after 10/19/94 has an automatic airbrake adjustment system that fails to compensate for wear	1	0
396.17(c)	Operating a CMV without proof of a periodic inspection	1	0

The summary counts and rates only include violations that were attributable to MELGAR, JUAN JOSE.

Report executed at: 7/6/2024 12:40:39 PM

MCMIS snapshot date: 06/28/2024

For an explanation of FMCSA-reportable crashes see: <https://www.psp.fmcsa.dot.gov/psp/?redirectUrl=FAQ>

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.