

PSP Detailed Report

Federal Motor Carrier Safety Administration

Driver Information													
Last Name	First Name	License #	State										
RODASLOPEZ	GABRIEL	942221032	AR										
RODAS	GABRIEL	942221032	AR										
LOPEZRODAS	GABRIEL	942221032	AR										
LOPEZ	GABRIEL	942221032	AR										
Crash Activity													
Crash Summary (Crashes listed represent a driver's involvement in FMCSA-reportable crashes, without any determination as to responsibility.)													
# of Crashes:	0	# of Crashes with Fatalities:	0	# of Crashes with Injuries:	0	# of Towaways:	0						
# Not preventable:	0	# of Fatalities:	0	# of Injuries:	0	# of Hazmat Releases:	0						
Crash Details (Crashes listed represent a driver's involvement in FMCSA-reportable crashes, without any determination as to responsibility.)													
	Date	DOT #	Carrier Name	Driver Name	Driver Lic	State	Driver DOB	Rpt St	Report Number	Location	# Fatalities	# of Injuries	
Inspection Activity (3 year history from MCMIS snapshot date)													
Inspection Summary													
Driver Summary				Vehicle Summary				Hazmat Summary					
Driver Inspections:		6	Vehicle Inspections:		4	Hazmat Inspections		0					
Driver Out-of-service Inspections:		0	Vehicle Out-of-service Inspections:		2	Hazmat Out-of-service Inspections:		0					
Driver Out-of-service Rate:		0%	Vehicle Out-of-service Rate:		50%	Hazmat Out-of-service Rate:		0%					

Report executed at: 7/15/2024 12:08:21 PM

MCMIS snapshot date: 06/28/2024

For an explanation of FMCSA-reportable crashes see: <https://www.psp.fmcsa.dot.gov/psp/?redirectUrl=FAQ>

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.

Inspection Details												
Carrier Info				Driver Info				Inspection Info				
	Date	DOT #	Carrier Name	Driver Name	Driver Lic	State	Driver DOB	Rpt St	Report Number	Hazmat Insp	Insp Level	# of Viol
1	12/17/2021	65769	HIRSCHBACH MOTOR LINES INC	RODAS LOPEZ, GABRIEL	942221032	AR	05/26/1984	KS	HP93412067	N	3	0
2	09/08/2022	3218214	NIKI EXPRESS INC	RODAS LOPEZ, GABRIEL	942221032	AR	05/26/1984	TN	TEQM006692	N	1	2
Vehicle Violation: 393.75(a)(3)				Tire-flat and/or audible air leak			OOS					
Vehicle Violation: 393.45(d)				Brake connections with leaks or constrictions			OOS					
3	04/04/2023	3757116	EAS LOGISTICS LLC	RODAS LOPEZ, GABRIEL	942221032	AR	05/26/1984	SC	B366000623	N	2	3
Vehicle Violation: 393.95(a)				No/discharged/unsecured fire extinguisher			NON-OOS					
Vehicle Violation: 393.75(b)				Tire-front tread depth less than 4/32 of inch on a major tread groove			NON-OOS					
Vehicle Violation: 396.17(c)				Operating a CMV without proof of a periodic inspection			NON-OOS					
4	05/11/2023	3300306	HOOK N BOOK TOWING LLC	RODAS LOPEZ, GABRIEL	942221032	AR	05/26/1984	MO	W100000673	N	1	6
Vehicle Violation: 392.2				State or International Fuel Tax (IFTA) Violation			NON-OOS					
Vehicle Violation: 393.95(a)				No/discharged/unsecured fire extinguisher			NON-OOS					
Vehicle Violation: 376.11(d)(1)				Lease or Rental Agreement not on board leased or rented CMV			NON-OOS					
Vehicle Violation: 393.25(f)				Stop lamp violations			NON-OOS					
Vehicle Violation: 393.11				Upper Rear retroreflective sheeting or reflex reflecting material requirements for vehicles manufactured after December 1993			NON-OOS					
Vehicle Violation: 393.207(b)				Adjustable axle locking pins missing or not engaged			NON-OOS					
5	11/07/2023	2289209	MEIBORG INC	RODAS LOPEZ, GABRIEL	942221032	AR	05/26/1984	MI	PEIFM05884	N	2	6
Vehicle Violation: 393.9(a)				Inoperable Required Lamp			NON-OOS					
Vehicle Violation: 393.9(a)				Inoperable Required Lamp			NON-OOS					
Vehicle Violation: 393.9(a)				Inoperative Brake Lamps			OOS					
Vehicle Violation: 393.9(a)				Inoperable tail lamp			OOS					
Vehicle Violation: 393.9(a)				Inoperable Required Lamp			NON-OOS					
Vehicle Violation: 393.9(a)				Inoperable Required Lamp			NON-OOS					
6	01/30/2024	2431585	MAYLAND TRANSPORT LLC	RODAS LOPEZ, GABRIEL	942221032	AR	05/26/1984	TN	I037H80004	N	3	0

Report executed at: 7/15/2024 12:08:21 PM

MCMIS snapshot date: 06/28/2024

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.

Violation Summary			
Violation #	Description	# of Violations	# of Out-of-service Violations
393.75(a)(3)	Tire-flat and/or audible air leak	1	1
393.45(d)	Brake connections with leaks or constrictions	1	1
393.95(a)	No/discharged/unsecured fire extinguisher	2	0
393.75(b)	Tire-front tread depth less than 4/32 of inch on a major tread groove	1	0
396.17(c)	Operating a CMV without proof of a periodic inspection	1	0
392.2	State or International Fuel Tax (IFTA) Violation	1	0
376.11(d)(1)	Lease or Rental Agreement not on board leased or rented CMV	1	0
393.25(f)	Stop lamp violations	1	0
393.11	Upper Rear retroreflective sheeting or reflex reflecting material requirements for vehicles manufactured after December 1993	1	0
393.207(b)	Adjustable axle locking pins missing or not engaged	1	0
393.9(a)	Inoperable Required Lamp	6	2

The summary counts and rates only include violations that were attributable to RODASLOPEZ, GABRIEL.

Report executed at: 7/15/2024 12:08:21 PM

MCMIS snapshot date: 06/28/2024

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.

For an explanation of FMCSA-reportable crashes see: <https://www.psp.fmcsa.dot.gov/psp/?redirectUrl=FAQ>