

PSP Detailed Report

Federal Motor Carrier Safety Administration

Driver Information													
Last Name	First Name	License #	State										
JEANCHARLES	ERNSY	J526200803280	FL										
JEAN	ERNSY	J526200803280	FL										
CHARLES	ERNSY	J526200803280	FL										
Crash Activity													
Crash Summary (Crashes listed represent a driver's involvement in FMCSA-reportable crashes, without any determination as to responsibility.)													
# of Crashes:	0	# of Crashes with Fatalities:	0	# of Crashes with Injuries:	0	# of Towaways:	0						
# Not preventable:	0	# of Fatalities:	0	# of Injuries:	0	# of Hazmat Releases:	0						
Crash Details (Crashes listed represent a driver's involvement in FMCSA-reportable crashes, without any determination as to responsibility.)													
	Date	DOT #	Carrier Name	Driver Name	Driver Lic	State	Driver DOB	Rpt St	Report Number	Location	# Fatalities	# of Injuries	
Inspection Activity (3 year history from MCMIS snapshot date)													
Inspection Summary													
Driver Summary				Vehicle Summary				Hazmat Summary					
Driver Inspections:		3		Vehicle Inspections:		3		Hazmat Inspections				0	
Driver Out-of-service Inspections:		0		Vehicle Out-of-service Inspections:		0		Hazmat Out-of-service Inspections:				0	
Driver Out-of-service Rate:		0%		Vehicle Out-of-service Rate:		0%		Hazmat Out-of-service Rate:				0%	

Report executed at: 7/29/2024 3:31:59 PM

MCMIS snapshot date: 06/28/2024

For an explanation of FMCSA-reportable crashes see: <https://www.psp.fmcsa.dot.gov/psp/?redirectUrl=FAQ>

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.

Inspection Details												
Carrier Info				Driver Info				Inspection Info				
	Date	DOT #	Carrier Name	Driver Name	Driver Lic	State	Driver DOB	Rpt St	Report Number	Hazmat Insp	Insp Level	# of Viol
1	09/08/2021	1346846	MG LOGISTICS INC	ERNSY, JEAN	J526200803280	FL	09/08/1980	CA	ND6V002892	N	1	0
2	11/21/2021	1346846	MG LOGISTICS INC	JEAN CHARLES, ERNSY	J526200803280	FL	09/08/1980	CA	ND65004903	N	1	5
Vehicle Violation:				396.3(a)(1)	Inspection, repair and maintenance of parts and accessories		NON-OOS					
Vehicle Violation:				396.3(a)(1)	Inspection, repair and maintenance of parts and accessories		NON-OOS					
Vehicle Violation:				393.207(f)	Air suspension pressure loss		NON-OOS					
Vehicle Violation:				393.45(b)(2)	Brake Hose or Tubing Chafing and/or Kinking Under Vehicle		NON-OOS					
Vehicle Violation:				393.55(e)	No or Defective ABS Malfunction Indicator Lamp for trailer manufactured after 03/01/1998		NON-OOS					
3	10/20/2022	2979800	ZERO MAX INC	ERNSY, JEAN	J526200803280	FL	09/08/1980	KY	0S02800706	N	2	0
Violation Summary												
Violation #		Description							# of Violations		# of Out-of-service Violations	
396.3(a)(1)		Inspection, repair and maintenance of parts and accessories							2		0	
393.207(f)		Air suspension pressure loss							1		0	
393.45(b)(2)		Brake Hose or Tubing Chafing and/or Kinking Under Vehicle							1		0	
393.55(e)		No or Defective ABS Malfunction Indicator Lamp for trailer manufactured after 03/01/1998							1		0	

The summary counts and rates only include violations that were attributable to JEANCHARLES, ERNSY.

Report executed at: 7/29/2024 3:31:59 PM

MCMIS snapshot date: 06/28/2024

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.

For an explanation of FMCSA-reportable crashes see: <https://www.psp.fmcsa.dot.gov/psp/?redirectUrl=FAQ>