

PSP Detailed Report

Federal Motor Carrier Safety Administration

Driver Information															
Last Name		First Name		License #			State								
GARCIA		LUIS		G620526793050			FL								
Crash Activity															
Crash Summary (Crashes listed represent a driver's involvement in FMCSA-reportable crashes, without any determination as to responsibility.)															
# of Crashes:		0		# of Crashes with Fatalities:		0		# of Crashes with Injuries:		0		# of Towaways:		0	
# Not preventable:		0		# of Fatalities:		0		# of Injuries:		0		# of Hazmat Releases:		0	
Crash Details (Crashes listed represent a driver's involvement in FMCSA-reportable crashes, without any determination as to responsibility.)															
	Date	DOT #	Carrier Name	Driver Name	Driver Lic	State	Driver DOB	Rpt St	Report Number	Location	# Fatalities	# of Injuries			
Inspection Activity (3 year history from MCMIS snapshot date)															
Inspection Summary															
Driver Summary				Vehicle Summary				Hazmat Summary							
Driver Inspections:		3		Vehicle Inspections:		1		Hazmat Inspections				0			
Driver Out-of-service Inspections:		0		Vehicle Out-of-service Inspections:		1		Hazmat Out-of-service Inspections:				0			
Driver Out-of-service Rate:		0%		Vehicle Out-of-service Rate:		100%		Hazmat Out-of-service Rate:				0%			

Report executed at: 7/30/2024 11:20:03 AM

MCMIS snapshot date: 06/28/2024

For an explanation of FMCSA-reportable crashes see: <https://www.psp.fmcsa.dot.gov/psp/?redirectUrl=FAQ>

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.

Inspection Details												
Carrier Info				Driver Info				Inspection Info				
	Date	DOT #	Carrier Name	Driver Name	Driver Lic	State	Driver DOB	Rpt St	Report Number	Hazmat Insp	Insp Level	# of Viol
1	12/07/2023	2579406	CARGO RUNNER CO	GARCIA, LUIS	G620526793050	FL	08/25/1979	MN	0AEV000626	N	1	4
Driver Violation: 392.2 State/Local Laws - Excessive weight - 1-2500 lbs over on an axle/axle groups. NON-OOS												
Vehicle Violation: 393.209(d) Steering system components worn, welded, or missing OOS												
Vehicle Violation: 393.75(a)(3) Tire-flat and/or audible air leak OOS												
Vehicle Violation: 393.9(a) Inoperable Required Lamp NON-OOS												
2	04/22/2024	3482231	BENTOS INC	GARCIA, LUIS	G620526793050	FL	08/25/1979	CO	1330010301	N	3	0
3	05/09/2024	4094977	K&A INTERNATIONAL LLC	GARCIA, LUIS	G620526793050	FL	08/25/1979	MI	SAHIW01834	N	3	1
Driver Violation: 392.2 State/Local Laws - Speeding work/construction zone. NON-OOS												
Violation Summary												
Violation #		Description							# of Violations		# of Out-of-service Violations	
392.2		State/Local Laws - Excessive weight - 1-2500 lbs over on an axle/axle groups.							2		0	
393.209(d)		Steering system components worn, welded, or missing							1		1	
393.75(a)(3)		Tire-flat and/or audible air leak							1		1	
393.9(a)		Inoperable Required Lamp							1		0	

The summary counts and rates only include violations that were attributable to GARCIA, LUIS.

Report executed at: 7/30/2024 11:20:03 AM

MCMIS snapshot date: 06/28/2024

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.