

PSP Detailed Report

Federal Motor Carrier Safety Administration

Driver Information													
Last Name	First Name	License #	State										
RODRIGUEZPARRILLA	JOSE	R36242181170	IL										
RODRIGUEZ	JOSE ANTONIO	R36242181170	IL										
PARRILLA	JOSE ANTONIO	R36242181170	IL										

Crash Activity													
Crash Summary (Crashes listed represent a driver's involvement in FMCSA-reportable crashes, without any determination as to responsibility.)													
# of Crashes:	1	# of Crashes with Fatalities:	0	# of Crashes with Injuries:	1	# of Towaways:	1						
# Not preventable:	0	# of Fatalities:	0	# of Injuries:	1	# of Hazmat Releases:	0						
Crash Details (Crashes listed represent a driver's involvement in FMCSA-reportable crashes, without any determination as to responsibility.)													
	Date	DOT #	Carrier Name	Driver Name	Driver Lic	State	Driver DOB	Rpt St	Report Number	Location	# Fatalities	# of Injuries	
1	10/10/2023	3027572	J C MOVING INC	RODRIGUEZ PARRILLA, JOSE	R36242181170	IL	06/15/1981	WI	WI0000121112	CTH PP SB	0	1	

Inspection Activity (3 year history from MCMIS snapshot date)													
Inspection Summary													
Driver Summary				Vehicle Summary				Hazmat Summary					
Driver Inspections:		2		Vehicle Inspections:		2		Hazmat Inspections				0	
Driver Out-of-service Inspections:		1		Vehicle Out-of-service Inspections:		1		Hazmat Out-of-service Inspections:				0	
Driver Out-of-service Rate:		50%		Vehicle Out-of-service Rate:		50%		Hazmat Out-of-service Rate:				0%	

Report executed at: 8/14/2024 10:19:28 AM

MCMIS snapshot date: 07/26/2024

For an explanation of FMCSA-reportable crashes see: <https://www.psp.fmcsa.dot.gov/psp/?redirectUrl=FAQ>

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.

Inspection Details												
Carrier Info				Driver Info				Inspection Info				
	Date	DOT #	Carrier Name	Driver Name	Driver Lic	State	Driver DOB	Rpt St	Report Number	Hazmat Insp	Insp Level	# of Viol
1	12/13/2022	2424011	SMART TRANS LOGISTICS INC	RODRIGUEZ PARRILLA, JOSE	R36242181170	IL	06/15/1981	OH	3266010600	N	2	3
Vehicle Violation: 393.75(a)(1) Tire-ply or belt material exposed OOS Vehicle Violation: 393.75(a)(1) Tire-ply or belt material exposed OOS Vehicle Violation: 393.60(c) Windshield - Damaged or Discolored NON-OOS												
2	10/10/2023	3027572	J C MOVING INC	RODRIGUEZ PARRILLA, JOSE	R36242181170	IL	06/15/1981	WI	1736006700	N	2	2
Driver Violation: 392.2 Failure to yield right of way NON-OOS Driver Violation: 383.91(a) Operating a cmv with improper CDL group OOS												
Violation Summary												
Violation #	Description								# of Violations	# of Out-of-service Violations		
393.75(a)(1)	Tire-ply or belt material exposed								2	2		
393.60(c)	Windshield - Damaged or Discolored								1	0		
392.2	Failure to yield right of way								1	0		
383.91(a)	Operating a cmv with improper CDL group								1	1		

The summary counts and rates only include violations that were attributable to RODRIGUEZPARRILLA, JOSE.

Report executed at: 8/14/2024 10:19:28 AM

MCMIS snapshot date: 07/26/2024

For an explanation of FMCSA-reportable crashes see: <https://www.psp.fmcsa.dot.gov/psp/?redirectUrl=FAQ>

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.