

PSP Detailed Report

Federal Motor Carrier Safety Administration

Driver Information															
Last Name	First Name			License #			State								
LEYVAGONZALEZ	RAMON			L125721624520			FL								
LEYVA	RAMON ALBERTO			L125721624520			FL								
GONZALEZ	RAMON ALBERTO			L125721624520			FL								
Crash Activity															
Crash Summary (Crashes listed represent a driver's involvement in FMCSA-reportable crashes, without any determination as to responsibility.)															
# of Crashes:		0		# of Crashes with Fatalities:		0		# of Crashes with Injuries:		0		# of Towaways:		0	
# Not preventable:		0		# of Fatalities:		0		# of Injuries:		0		# of Hazmat Releases:		0	
Crash Details (Crashes listed represent a driver's involvement in FMCSA-reportable crashes, without any determination as to responsibility.)															
	Date	DOT #	Carrier Name	Driver Name	Driver Lic	State	Driver DOB	Rpt St	Report Number	Location	# Fatalities	# of Injuries			
Inspection Activity (3 year history from MCMIS snapshot date)															
Inspection Summary															
Driver Summary				Vehicle Summary				Hazmat Summary							
Driver Inspections:		1		Vehicle Inspections:		1		Hazmat Inspections				0			
Driver Out-of-service Inspections:		0		Vehicle Out-of-service Inspections:		0		Hazmat Out-of-service Inspections:				0			
Driver Out-of-service Rate:		0%		Vehicle Out-of-service Rate:		0%		Hazmat Out-of-service Rate:				0%			

Report executed at: 9/3/2024 10:23:03 AM

MCMIS snapshot date: 07/26/2024

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.

For an explanation of FMCSA-reportable crashes see: <https://www.psp.fmcsa.dot.gov/psp/?redirectUrl=FAQ>

Inspection Details												
Carrier Info				Driver Info				Inspection Info				
	Date	DOT #	Carrier Name	Driver Name	Driver Lic	State	Driver DOB	Rpt St	Report Number	Hazmat Insp	Insp Level	# of Viol
1	03/11/2024	1329089	PROFESSIONAL LOGISTICS INC	GONZALEZ, RAMON	L125721624520	FL	12/12/1962	OH	3246017121	N	2	2
<div> <div>Vehicle Violation: 392.2</div> <div>State vehicle registration or License Plate violation</div> <div>NON-OOS</div> </div> <div> <div>Vehicle Violation: 393.55(d)(3)</div> <div>No or Defective ABS Malfunction Indicator for towed vehicles on vehicles manufactured after February 2001</div> <div>NON-OOS</div> </div>												
Violation Summary												
Violation #	Description								# of Violations	# of Out-of-service Violations		
392.2	State vehicle registration or License Plate violation								1	0		
393.55(d)(3)	No or Defective ABS Malfunction Indicator for towed vehicles on vehicles manufactured after February 2001								1	0		

The summary counts and rates only include violations that were attributable to LEYVAGONZALEZ, RAMON.

Report executed at: 9/3/2024 10:23:03 AM

MCMIS snapshot date: 07/26/2024

For an explanation of FMCSA-reportable crashes see: <https://www.psp.fmcsa.dot.gov/psp/?redirectUrl=FAQ>

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.