

PSP Detailed Report

Federal Motor Carrier Safety Administration

Driver Information															
Last Name		First Name		License #		State									
SANTANAGONZALEZ		YUDEL		41883800		TX									
Crash Activity															
Crash Summary (Crashes listed represent a driver's involvement in FMCSA-reportable crashes, without any determination as to responsibility.)															
# of Crashes:		0		# of Crashes with Fatalities:		0		# of Crashes with Injuries:		0		# of Towaways:		0	
# Not preventable:		0		# of Fatalities:		0		# of Injuries:		0		# of Hazmat Releases:		0	
Crash Details (Crashes listed represent a driver's involvement in FMCSA-reportable crashes, without any determination as to responsibility.)															
	Date	DOT #	Carrier Name	Driver Name	Driver Lic	State	Driver DOB	Rpt St	Report Number	Location	# Fatalities	# of Injuries			
Inspection Activity (3 year history from MCMIS snapshot date)															
Inspection Summary															
Driver Summary				Vehicle Summary				Hazmat Summary							
Driver Inspections:		5		Vehicle Inspections:		4		Hazmat Inspections				0			
Driver Out-of-service Inspections:		1		Vehicle Out-of-service Inspections:		1		Hazmat Out-of-service Inspections:				0			
Driver Out-of-service Rate:		20%		Vehicle Out-of-service Rate:		25%		Hazmat Out-of-service Rate:				0%			
Inspection Details															
Carrier Info				Driver Info				Inspection Info							
	Date	DOT #	Carrier Name	Driver Name	Driver Lic	State	Driver DOB	Rpt St	Report Number	Hazmat Insp	Insp Level	# of Viol			
1	08/15/2022	3588701	J C Y TRANSPORTATION USA LLC	SANTANA GONZALEZ, YUDEL	41883800	TX	02/11/1985	TX	6DI99DFXBA	N	1	3			
Vehicle Violation:		390.21(a)		Not marked in accordance with regulations		NON-OOS									
Vehicle Violation:		393.78		Wipers - Inoperative / missing / damaged wipers.		NON-OOS									
Vehicle Violation:		392.9		Driver may not operate a CMV without proper load securement		NON-OOS									

Report executed at: 9/4/2024 3:43:55 PM

MCMIS snapshot date: 07/26/2024

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.

For an explanation of FMCSA-reportable crashes see: <https://www.psp.fmcsa.dot.gov/psp/?redirectUrl=FAQ>

2	11/09/2022	3588701	J C Y TRANSPORTATION USA LLC	SANTANA GONZALEZ, YUDEL	41883800	TX	02/11/1985	TX	6FW99DFPK2	N	1	4
Driver Violation:			395.8	Record of Duty Status violation (general/form and manner)			OOS					
Vehicle Violation:			396.17(c)	Operating a CMV without proof of a periodic inspection			NON-OOS					
Vehicle Violation:			390.21(a)	Not marked in accordance with regulations			NON-OOS					
Vehicle Violation:			392.2	State vehicle registration or License Plate violation			NON-OOS					
3	03/01/2023	3961781	BUSINESS CORPORATION LLC	SANTANA GONZALEZ, YUDEL	41883800	TX	02/11/1985	WA	W711009902	N	3	2
Driver Violation:			392.2	IRP Apportioned Tag or Registration Violation			NON-OOS					
Driver Violation:			392.2	Violation of Local Laws - Explain:			NON-OOS					
4	03/04/2024	3276712	CLAUDIA C TOLEDO BARBERENA	SANTANA GONZALEZ, YUDEL	41883800	TX	02/11/1985	TX	6T9A9DQA1W	N	1	7
Vehicle Violation:			393.47(e)	Brake Out of Adjustment - Roto, Clamp (Short & Long), DD-3, or Bolt			NON-OOS					
Vehicle Violation:			393.47(e)	Brake Out of Adjustment - Roto, Clamp (Short & Long), DD-3, or Bolt			NON-OOS					
Vehicle Violation:			396.3(a)(1)	BRAKES OUT OF SERVICE: The number of defective brakes is equal to or greater than 20 percent of the service brakes on the vehicle or combination			OOS					
Vehicle Violation:			393.9(a)	Inoperable head lamps			NON-OOS					
Vehicle Violation:			393.60(c)	Windshield - Damaged or Discolored			NON-OOS					
Vehicle Violation:			396.3(a)(1)	Inspection, repair and maintenance of parts and accessories			NON-OOS					
Vehicle Violation:			396.5(b)	Hubs - Oil and/or Grease Leaking from hub - inner wheel			OOS					
5	04/12/2024	3196493	E-7 LOGISTICS LLC	SANTANA GONZALEZ, YUDEL	41883800	TX	02/11/1985	TX	V241387318	N	2	1
Vehicle Violation:			393.9(a)	Inoperable Required Lamp			NON-OOS					
Violation Summary												
Violation #		Description							# of Violations		# of Out-of-service Violations	
393.9(a)		Inoperable Required Lamp							2		0	
392.2		IRP Apportioned Tag or Registration Violation							3		0	
390.21(a)		Not marked in accordance with regulations							2		0	
393.78		Wipers - Inoperative / missing / damaged wipers.							1		0	
392.9		Driver may not operate a CMV without proper load securement							1		0	
393.47(e)		Brake Out of Adjustment - Roto, Clamp (Short & Long), DD-3, or Bolt							2		0	
396.3(a)(1)		BRAKES OUT OF SERVICE: The number of defective brakes is equal to or greater than 20 percent of the service brakes on the vehicle or combination							2		1	
393.60(c)		Windshield - Damaged or Discolored							1		0	

Report executed at: 9/4/2024 3:43:55 PM

MCMIS snapshot date: 07/26/2024

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.

396.5(b)	Hubs - Oil and/or Grease Leaking from hub - inner wheel	1	1
395.8	Record of Duty Status violation (general/form and manner)	1	1
396.17(c)	Operating a CMV without proof of a periodic inspection	1	0

The summary counts and rates only include violations that were attributable to SANTANAGONZALEZ, YUDEL.

Report executed at: 9/4/2024 3:43:55 PM

MCMIS snapshot date: 07/26/2024

For an explanation of FMCSA-reportable crashes see: <https://www.psp.fmcsa.dot.gov/psp/?redirectUrl=FAQ>

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.