

PSP Detailed Report

Federal Motor Carrier Safety Administration

Driver Information															
Last Name		First Name		License #			State								
MICHAUD		JOHN		M230479853730			FL								
Crash Activity															
Crash Summary (Crashes listed represent a driver's involvement in FMCSA-reportable crashes, without any determination as to responsibility.)															
# of Crashes:		0		# of Crashes with Fatalities:		0		# of Crashes with Injuries:		0		# of Towaways:		0	
# Not preventable:		0		# of Fatalities:		0		# of Injuries:		0		# of Hazmat Releases:		0	
Crash Details (Crashes listed represent a driver's involvement in FMCSA-reportable crashes, without any determination as to responsibility.)															
	Date	DOT #	Carrier Name	Driver Name	Driver Lic	State	Driver DOB	Rpt St	Report Number	Location	# Fatalities	# of Injuries			
Inspection Activity (3 year history from MCMIS snapshot date)															
Inspection Summary															
Driver Summary				Vehicle Summary				Hazmat Summary							
Driver Inspections:		1		Vehicle Inspections:		1		Hazmat Inspections				0			
Driver Out-of-service Inspections:		0		Vehicle Out-of-service Inspections:		0		Hazmat Out-of-service Inspections:				0			
Driver Out-of-service Rate:		0%		Vehicle Out-of-service Rate:		0%		Hazmat Out-of-service Rate:				0%			
Inspection Details															
Carrier Info				Driver Info				Inspection Info							
	Date	DOT #	Carrier Name	Driver Name	Driver Lic	State	Driver DOB	Rpt St	Report Number	Hazmat Insp	Insp Level	# of Viol			
1	10/05/2022	3158621	JB 1 TRANSPORT LLC	MICHAUD, JOHN	M230479853730	FL	10/13/1985	MO	W236007805	N	2	1			
Vehicle Violation:		393.60(d)		Windshield / Windows - Tinting permits less than 70% of light transmittance.				NON-OOS							

Report executed at: 9/17/2024 11:42:50 AM

MCMIS snapshot date: 08/30/2024

For an explanation of FMCSA-reportable crashes see: <https://www.psp.fmcsa.dot.gov/psp/?redirectUrl=FAQ>

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.

Violation Summary			
Violation #	Description	# of Violations	# of Out-of-service Violations
393.60(d)	Windshield / Windows - Tinting permits less than 70% of light transmittance.	1	0

The summary counts and rates only include violations that were attributable to MICHAUD, JOHN.

Report executed at: 9/17/2024 11:42:50 AM

MCMIS snapshot date: 08/30/2024

For an explanation of FMCSA-reportable crashes see: <https://www.psp.fmcsa.dot.gov/psp/?redirectUrl=FAQ>

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.