

PSP Detailed Report

Federal Motor Carrier Safety Administration

Driver Information															
Last Name		First Name		License #			State								
JOHNSON		PATRICK		04447422			TX								
Crash Activity															
Crash Summary (Crashes listed represent a driver's involvement in FMCSA-reportable crashes, without any determination as to responsibility.)															
# of Crashes:		0		# of Crashes with Fatalities:		0		# of Crashes with Injuries:		0		# of Towaways:		0	
# Not preventable:		0		# of Fatalities:		0		# of Injuries:		0		# of Hazmat Releases:		0	
Crash Details (Crashes listed represent a driver's involvement in FMCSA-reportable crashes, without any determination as to responsibility.)															
	Date	DOT #	Carrier Name	Driver Name	Driver Lic	State	Driver DOB	Rpt St	Report Number	Location	# Fatalities	# of Injuries			
Inspection Activity (3 year history from MCMIS snapshot date)															
Inspection Summary															
Driver Summary				Vehicle Summary				Hazmat Summary							
Driver Inspections:		3		Vehicle Inspections:		2		Hazmat Inspections				0			
Driver Out-of-service Inspections:		0		Vehicle Out-of-service Inspections:		1		Hazmat Out-of-service Inspections:				0			
Driver Out-of-service Rate:		0%		Vehicle Out-of-service Rate:		50%		Hazmat Out-of-service Rate:				0%			
Inspection Details															
Carrier Info				Driver Info				Inspection Info							
	Date	DOT #	Carrier Name	Driver Name	Driver Lic	State	Driver DOB	Rpt St	Report Number	Hazmat Insp	Insp Level	# of Viol			
1	11/23/2021	3354211	MODESTO LOGISTICS LLC	JOHNSON, PATRICK	04447422	TX	06/15/1971	TN	TCMJ002416	N	1	2			
Vehicle Violation:		393.60(c)		Windshield - Damaged or Discolored			NON-OOS								
Vehicle Violation:		393.9(a)		Inoperative turn signal			OOS								

Report executed at: 9/24/2024 5:33:03 PM

MCMIS snapshot date: 08/30/2024

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.

For an explanation of FMCSA-reportable crashes see: <https://www.psp.fmcsa.dot.gov/psp/?redirectUrl=FAQ>

2	06/14/2022	3354211	MODESTO LOGISTICS LLC	JOHNSON, PATRICK	04447422	TX	06/15/1971	MI	NEWCJ00572	N	1	2
Vehicle Violation:		393.11	Truck-Tractor lower rear mud flaps retroreflective sheeting / reflex reflective material requirements for vehicles manufactured after July 1997			NON-OOS						
Vehicle Violation:		393.48(a)	Inoperative/defective brakes			NON-OOS						
3	03/10/2023	2904384	M7 TRANSPORTATION LLC	JOHNSON, PATRICK	04447422	TX	06/15/1971	NM	5061N1XJPC	N	3	0

Violation Summary												
Violation #	Description								# of Violations	# of Out-of-service Violations		
393.60(c)	Windshield - Damaged or Discolored								1	0		
393.9(a)	Inoperative turn signal								1	1		
393.11	Truck-Tractor lower rear mud flaps retroreflective sheeting / reflex reflective material requirements for vehicles manufactured after July 1997								1	0		
393.48(a)	Inoperative/defective brakes								1	0		

The summary counts and rates only include violations that were attributable to JOHNSON, PATRICK.

Report executed at: 9/24/2024 5:33:03 PM

MCMIS snapshot date: 08/30/2024

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.

For an explanation of FMCSA-reportable crashes see: <https://www.psp.fmcsa.dot.gov/psp/?redirectUrl=FAQ>