

# PSP Detailed Report

Federal Motor Carrier Safety Administration

Driver Information															
Last Name		First Name		License #			State								
LOZADA		JOSE		L230439724160			FL								
Crash Activity															
Crash Summary (Crashes listed represent a driver's involvement in FMCSA-reportable crashes, without any determination as to responsibility.)															
# of Crashes:		0		# of Crashes with Fatalities:		0		# of Crashes with Injuries:		0		# of Towaways:		0	
# Not preventable:		0		# of Fatalities:		0		# of Injuries:		0		# of Hazmat Releases:		0	
Crash Details (Crashes listed represent a driver's involvement in FMCSA-reportable crashes, without any determination as to responsibility.)															
	Date	DOT #	Carrier Name	Driver Name	Driver Lic	State	Driver DOB	Rpt St	Report Number	Location	# Fatalities	# of Injuries			
Inspection Activity (3 year history from MCMIS snapshot date)															
Inspection Summary															
Driver Summary				Vehicle Summary				Hazmat Summary							
Driver Inspections:		2		Vehicle Inspections:		2		Hazmat Inspections				0			
Driver Out-of-service Inspections:		2		Vehicle Out-of-service Inspections:		2		Hazmat Out-of-service Inspections:				0			
Driver Out-of-service Rate:		100%		Vehicle Out-of-service Rate:		100%		Hazmat Out-of-service Rate:				0%			

Report executed at: 10/3/2024 9:47:59 AM

MCMIS snapshot date: 08/30/2024

For an explanation of FMCSA-reportable crashes see: <https://www.psp.fmcsa.dot.gov/psp/?redirectUrl=FAQ>

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.

Inspection Details												
Carrier Info				Driver Info				Inspection Info				
	Date	DOT #	Carrier Name	Driver Name	Driver Lic	State	Driver DOB	Rpt St	Report Number	Hazmat Insp	Insp Level	# of Viol
1	06/11/2022	3333949	VJ TRANSPORT SERVICE LLC	LOZADA, JOSE	L230439724160	FL	11/16/1972	TX	6BPH0XLKKB	N	2	4
Driver Violation:		395.8(a)(1)	ELD - No record of duty status (ELD Required)				OOS					
Vehicle Violation:		396.17(c)	Operating a CMV without proof of a periodic inspection				NON-OOS					
Vehicle Violation:		393.30	Improper battery installation				NON-OOS					
Vehicle Violation:		393.128	No/improper securement of vehicles				OOS					
2	01/05/2023	3333949	VJ TRANSPORT SERVICE LLC	LOZADA, JOSE	L230439724160	FL	11/16/1972	TX	6HHB0VLKJ4	N	2	6
Vehicle Violation:		396.3(a)(1)	BRAKES OUT OF SERVICE: The number of defective brakes is equal to or greater than 20 percent of the service brakes on the vehicle or combination				OOS					
Vehicle Violation:		393.53(b)	CMV manufactured after 10/19/94 has an automatic airbrake adjustment system that fails to compensate for wear				NON-OOS					
Vehicle Violation:		393.47(e)	Brake Out of Adjustment - Roto, Clamp (Short & Long), DD-3, or Bolt				NON-OOS					
Vehicle Violation:		393.47(e)	Brake Out of Adjustment - Roto, Clamp (Short & Long), DD-3, or Bolt				NON-OOS					
Driver Violation:		391.45(b)	Expired medical examiner's certificate				NON-OOS					
Driver Violation:		383.23(a)(2)	Operating a CMV without a CDL				OOS					
Violation Summary												
Violation #		Description							# of Violations		# of Out-of-service Violations	
396.3(a)(1)		BRAKES OUT OF SERVICE: The number of defective brakes is equal to or greater than 20 percent of the service brakes on the vehicle or combination							1		1	
393.53(b)		CMV manufactured after 10/19/94 has an automatic airbrake adjustment system that fails to compensate for wear							1		0	
393.47(e)		Brake Out of Adjustment - Roto, Clamp (Short & Long), DD-3, or Bolt							2		0	
391.45(b)		Expired medical examiner's certificate							1		0	
383.23(a)(2)		Operating a CMV without a CDL							1		1	
395.8(a)(1)		ELD - No record of duty status (ELD Required)							1		1	
396.17(c)		Operating a CMV without proof of a periodic inspection							1		0	
393.30		Improper battery installation							1		0	
393.128		No/improper securement of vehicles							1		1	

Report executed at: 10/3/2024 9:47:59 AM

MCMIS snapshot date: 08/30/2024

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.

The summary counts and rates only include violations that were attributable to LOZADA, JOSE.

Report executed at: 10/3/2024 9:47:59 AM

MCMIS snapshot date: 08/30/2024

For an explanation of FMCSA-reportable crashes see: <https://www.psp.fmcsa.dot.gov/psp/?redirectUrl=FAQ>

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.