

PSP Detailed Report

Federal Motor Carrier Safety Administration

Driver Information															
Last Name		First Name		License #			State								
JEFFERSON		SHAWN		42365806			TX								
Crash Activity															
Crash Summary (Crashes listed represent a driver's involvement in FMCSA-reportable crashes, without any determination as to responsibility.)															
# of Crashes:		1		# of Crashes with Fatalities:		0		# of Crashes with Injuries:		1		# of Towaways:		1	
# Not preventable:		1		# of Fatalities:		0		# of Injuries:		1		# of Hazmat Releases:		0	
Crash Details (Crashes listed represent a driver's involvement in FMCSA-reportable crashes, without any determination as to responsibility.)															
	Date	DOT #	Carrier Name	Driver Name	Driver Lic	State	Driver DOB	Rpt St	Report Number	Location	# Fatalities	# of Injuries			
1	09/30/2021	1243338	P&S TRANSPORTATION LLC	JEFFERSON, SHAWN	42365806	TX	05/18/1987	TX	TX64Y7HQE1C X	W 600 COURT ST	0	1			
➔ ROW 1 REVIEWED - NOT PREVENTABLE - FMCSA REVIEWED THIS CRASH AND DETERMINED THAT IT WAS NOT PREVENTABLE.															
Inspection Activity (3 year history from MCMIS snapshot date)															
Inspection Summary															
Driver Summary				Vehicle Summary				Hazmat Summary							
Driver Inspections:		1		Vehicle Inspections:		1		Hazmat Inspections				0			
Driver Out-of-service Inspections:		0		Vehicle Out-of-service Inspections:		1		Hazmat Out-of-service Inspections:				0			
Driver Out-of-service Rate:		0%		Vehicle Out-of-service Rate:		100%		Hazmat Out-of-service Rate:				0%			

Report executed at: 10/23/2024 11:46:50 AM

MCMIS snapshot date: 09/27/2024

For an explanation of FMCSA-reportable crashes see: <https://www.psp.fmcsa.dot.gov/psp/?redirectUrl=FAQ>

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.

Inspection Details												
Carrier Info				Driver Info				Inspection Info				
	Date	DOT #	Carrier Name	Driver Name	Driver Lic	State	Driver DOB	Rpt St	Report Number	Hazmat Insp	Insp Level	# of Viol
1	03/17/2022	1243338	P&S TRANSPORTATION	JEFFERSON, SHAWN	42365806	TX	05/18/1987	TX	69B99DIRY4	N	2	4
<div>Vehicle Violation: 392.2 State vehicle registration or License Plate violation NON-OOS</div> <div>Vehicle Violation: 393.110(b) Insufficient tiedowns to prevent forward movement for load not blocked by headerboard, bulkhead, or other cargo. OOS</div> <div>Vehicle Violation: 393.104(b) Damaged securement system/tiedowns OOS</div> <div>Vehicle Violation: 393.104(f)(4) No edge protection for tiedowns NON-OOS</div>												
Violation Summary												
Violation #	Description								# of Violations	# of Out-of-service Violations		
392.2	State vehicle registration or License Plate violation								1	0		
393.110(b)	Insufficient tiedowns to prevent forward movement for load not blocked by headerboard, bulkhead, or other cargo.								1	1		
393.104(b)	Damaged securement system/tiedowns								1	1		
393.104(f)(4)	No edge protection for tiedowns								1	0		

The summary counts and rates only include violations that were attributable to JEFFERSON, SHAWN.

Report executed at: 10/23/2024 11:46:50 AM

MCMIS snapshot date: 09/27/2024

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.

For an explanation of FMCSA-reportable crashes see: <https://www.psp.fmcsa.dot.gov/psp/?redirectUrl=FAQ>