

# PSP Detailed Report

Federal Motor Carrier Safety Administration

Driver Information													
Last Name	First Name	License #	State										
PEREZGONZALEZ	JOSE	P625434633000	FL										
PEREZ	JOSE OSCAR	P625434633000	FL										
GONZALEZ	JOSE OSCAR	P625434633000	FL										

Crash Activity													
Crash Summary (Crashes listed represent a driver's involvement in FMCSA-reportable crashes, without any determination as to responsibility.)													
# of Crashes:	0	# of Crashes with Fatalities:	0	# of Crashes with Injuries:	0	# of Towaways:	0						
# Not preventable:	0	# of Fatalities:	0	# of Injuries:	0	# of Hazmat Releases:	0						
Crash Details (Crashes listed represent a driver's involvement in FMCSA-reportable crashes, without any determination as to responsibility.)													
	Date	DOT #	Carrier Name	Driver Name	Driver Lic	State	Driver DOB	Rpt St	Report Number	Location	# Fatalities	# of Injuries	

Inspection Activity (3 year history from MCMIS snapshot date)													
Inspection Summary													
Driver Summary				Vehicle Summary				Hazmat Summary					
Driver Inspections:		3		Vehicle Inspections:		1		Hazmat Inspections				0	
Driver Out-of-service Inspections:		1		Vehicle Out-of-service Inspections:		0		Hazmat Out-of-service Inspections:				0	
Driver Out-of-service Rate:		33%		Vehicle Out-of-service Rate:		0%		Hazmat Out-of-service Rate:				0%	

Report executed at: 10/7/2024 10:21:30 AM

MCMIS snapshot date: 09/27/2024

For an explanation of FMCSA-reportable crashes see: <https://www.psp.fmcsa.dot.gov/psp/?redirectUrl=FAQ>

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.

Inspection Details												
Carrier Info				Driver Info				Inspection Info				
	Date	DOT #	Carrier Name	Driver Name	Driver Lic	State	Driver DOB	Rpt St	Report Number	Hazmat Insp	Insp Level	# of Viol
1	05/19/2022	3041569	AMG EXPRESS CARGO INC	PEREZ, JOSE	P625434633000	FL	08/20/1963	TX	6B2D0AJDQ5	N	1	3
Vehicle Violation: 396.5(b) Oil and/or grease leak NON-OOS Vehicle Violation: 393.45(b)(2) Brake Hose or Tubing Chafing and/or Kinking Under Vehicle NON-OOS Vehicle Violation: 393.45(b)(2) Brake Hose or Tubing Chafing and/or Kinking Under Vehicle NON-OOS												
2	01/21/2023	1213613	ROLAND TRANSPORT INC	PEREZ GONZALEZ, JOSE	P625434633000	FL	08/20/1963	AR	560C006556	N	3	0
3	04/26/2023	1213613	ROLAND TRANSPORT INC	PEREZ GONZALEZ, JOSE	P625434633000	FL	08/20/1963	OR	AADW003526	N	3	2
Driver Violation: 395.8(a)(1) ELD - No record of duty status (ELD Required) OOS Driver Violation: 395.8(e)(1) False report of drivers record of duty status NON-OOS												
Violation Summary												
Violation #	Description								# of Violations	# of Out-of-service Violations		
395.8(a)(1)	ELD - No record of duty status (ELD Required)								1	1		
395.8(e)(1)	False report of drivers record of duty status								1	0		
396.5(b)	Oil and/or grease leak								1	0		
393.45(b)(2)	Brake Hose or Tubing Chafing and/or Kinking Under Vehicle								2	0		

The summary counts and rates only include violations that were attributable to PEREZGONZALEZ, JOSE.

Report executed at: 10/7/2024 10:21:30 AM

MCMIS snapshot date: 09/27/2024

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.

For an explanation of FMCSA-reportable crashes see: <https://www.psp.fmcsa.dot.gov/psp/?redirectUrl=FAQ>