## **PSP Detailed Report**

**Federal Motor Carrier Safety Administration** 

	Driver Information																	
Last Name First Name			е			License #				State								
ARENCIBIA ADONIS						A652000782290					FL							
	Crash Activity																	
Crash	Crash Summary (Crashes listed represent a driver's involvement in FMCSA-reportable crashes, without any determination as to responsibility.)																	
# (Out to 1)									ys: 0									
				0	# of Fataliti			0				# of I	njuries:	0	# of Hazmat Releases:			
Crash Details (Crashes listed represent a driver's involvement in FMCSA-reportable crashes, without any determination as to responsibility.)													0					
Crasii																		
	Date	DOI#	Carri	er Name		Driver Name	Di	river Lic	State	Drive	er DOB	Kpt St	Report Number Location		Location	# Fata	lities   # of	injuries
	Inspection Activity (3 year history from MCMIS snapshot date)																	
Inspec	Inspection Summary																	
	Driver Summary Vehicle Summary Hazmat Summary																	
Driver Inspections:				2	Vehicle Inspections:					1 Ha	1 Hazmat Inspections 0							
Driver Out-of-service Inspections:					Vehicle Out-of-service Inspections:						0 Hazmat Out-of-service Inspections: 0							
Driver Out-of-service Rate:					Vehicle Out-of-service Rate:					· · · · · · · · · · · · · · · · · · ·						0%		
				0 76	0% Vehicle Out-of-service Rate.					0%								
	Inspection Details																	
				Driver	ver Info					Inspection Info								
	Date	DOT#	Carrie	r Name		Driver Name		Driver	Lic	State	Driver	r DOB	Rpt St	Report	Number	Hazmat Insp	Insp Level	# of Viol
1	11/22/2021 2089174 AREL TRUCKING INC ARE		ARENO	CIBIA, ADONIS A65200		A6520007	782290	FL	06/29	06/29/1978 MS		6610007244		N	2	1		
	Vehicle Violation: 396.3(a)(1) Inspection, repair and maintenance of parts and accessories NON-OOS																	
2	2 08/15/2024 3021325 PAM INTERNATIONAL INC A			ARENO	CIBIA, ADONIS		A652000782290		FL	06/29	/1978	AL JSBH008729		008729	N	3	0	

Report executed at: 10/24/2024 5:57:13 PM

MCMIS snapshot date: 09/27/2024

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.

Violation Summary									
Violation #	Description	# of Violations	# of Out-of-service Violations						
396.3(a)(1)	Inspection, repair and maintenance of parts and accessories	1	0						

The summary counts and rates only include violations that were attributable to ARENCIBIA, ADONIS.

Report executed at: 10/24/2024 5:57:13 PM

MCMIS snapshot date: 09/27/2024

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.