

# PSP Detailed Report

Federal Motor Carrier Safety Administration

Driver Information															
Last Name		First Name		License #		State									
MACHADOVASQUEZ		FELIPE		M231006861760		FL									
MACHADO		ANDRES FELIPE		M231006861760		FL									
Crash Activity															
Crash Summary (Crashes listed represent a driver's involvement in FMCSA-reportable crashes, without any determination as to responsibility.)															
# of Crashes:		0		# of Crashes with Fatalities:		0		# of Crashes with Injuries:		0		# of Towaways:		0	
# Not preventable:		0		# of Fatalities:		0		# of Injuries:		0		# of Hazmat Releases:		0	
Crash Details (Crashes listed represent a driver's involvement in FMCSA-reportable crashes, without any determination as to responsibility.)															
	Date	DOT #	Carrier Name	Driver Name	Driver Lic	State	Driver DOB	Rpt St	Report Number	Location	# Fatalities	# of Injuries			
Inspection Activity (3 year history from MCMIS snapshot date)															
Inspection Summary															
Driver Summary				Vehicle Summary				Hazmat Summary							
Driver Inspections:		1		Vehicle Inspections:		1		Hazmat Inspections				0			
Driver Out-of-service Inspections:		0		Vehicle Out-of-service Inspections:		1		Hazmat Out-of-service Inspections:				0			
Driver Out-of-service Rate:		0%		Vehicle Out-of-service Rate:		100%		Hazmat Out-of-service Rate:				0%			

Report executed at: 11/20/2024 11:28:26 AM

MCMIS snapshot date: 10/25/2024

For an explanation of FMCSA-reportable crashes see: <https://www.psp.fmcsa.dot.gov/psp/?redirectUrl=FAQ>

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.

Inspection Details												
Carrier Info				Driver Info				Inspection Info				
	Date	DOT #	Carrier Name	Driver Name	Driver Lic	State	Driver DOB	Rpt St	Report Number	Hazmat Insp	Insp Level	# of Viol
1	08/10/2022	1048682	GOLDEN SUNRISE TRANSPORT INC	MACHADO, FELIPE	M231006861760	FL	05/16/1986	FL	3660006046	N	2	6
<div>Vehicle Violation: 393.78 Wipers - Inoperative / missing / damaged wipers NON-OOS</div> <div>Vehicle Violation: 396.17(c) Operating a CMV without proof of a periodic inspection NON-OOS</div> <div>Vehicle Violation: 393.9(a) Inoperable Required Lamp NON-OOS</div> <div>Vehicle Violation: 393.9(a) Inoperative turn signal OOS</div> <div>Vehicle Violation: 396.17(c) Operating a CMV without proof of a periodic inspection NON-OOS</div> <div>Vehicle Violation: 393.30 Improper battery installation NON-OOS</div>												
Violation Summary												
Violation #	Description								# of Violations	# of Out-of-service Violations		
393.78	Wipers - Inoperative / missing / damaged wipers								1	0		
396.17(c)	Operating a CMV without proof of a periodic inspection								2	0		
393.9(a)	Inoperable Required Lamp								2	1		
393.30	Improper battery installation								1	0		

The summary counts and rates only include violations that were attributable to MACHADOVASQUEZ, FELIPE.

Report executed at: 11/20/2024 11:28:26 AM

MCMIS snapshot date: 10/25/2024

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.

For an explanation of FMCSA-reportable crashes see: <https://www.psp.fmcsa.dot.gov/psp/?redirectUrl=FAQ>