PSP Detailed Report

Federal Motor Carrier Safety Administration

							Drive	er lı	nform	ation											
Last Name First					First Name				License #					State							
RICHARDSON FOREST						049146667						GA									
	Crash Activity														<u> </u>						
Crash	Crash Summary (Crashes listed represent a driver's involvement in FMCSA-reportable crashes, without any determination as to responsibility.)																				
# of Crashes:					0 # of Crashes with Fatalit				s: 0	0 # of Crashes with					njuries:	0	# of Towaways:				0
# Not preventable:					# of Fatali				s: 0					# of I	njuries:	0	# of Hazmat Releases:			eases:	0
Crash	Crash Details (Crashes listed represent a driver's involvement in FMCSA-reportable crashes, without any determination as to responsibility.)																				
Date DOT # Carrie				ier Nar	Name Driver Name				Drive	Driver Lic State Drive			r DOB	Rpt St	t Report Number Loo			on # Fatalities		# of Injuries	
Inspection Activity (2 year hist									tory from MCMIS snapshot date)												
Inches	Inspection Activity (3 year history from MCMIS snapshot date)																				
Inspec	Inspection Summary																				
	Driver Summary Vehicle Summary Hazmat Summary																				
Driver Inspections:						3	3 Vehicle Inspections:						1 Hazmat Inspections							0	
Driver Out-of-service Inspections:						0 Vehicle Out-of-service Inspections:							0 Hazmat Out-of-service Inspections:								0
Driver Out-of-service Rate:						0%	Vehicle Out-of-service Rat					0% H	azmat O	Out-of-service Rate: 09						0%	
Inspec	Inspection Details																				
Carrier Info						Driver Info								Inspect	Inspection Info						
	Date	DOT #	Carri	Carrier Name		Driver Name				Driver Lic	:	State	State Driver DOB		Rpt St	Repor	t Number	Hazmat Insp	Insp Le		# of Viol
1	03/01/2022	1925066	JK LOG	ISTICS	TICS LLC RICH		ARDSON, FOREST			049146667	7	GA 10/1		4/1970	GA	0370	0003730	N	3		2
	Driver Violation: 392.2 Miscellaneous Traffic Law Violation										NON-OOS										
	Driver Violation: 392.2 State vehicle registration or License Plate violation									NON-OOS											

Report executed at: 1/3/2025 1:07:55 PM

MCMIS snapshot date: 12/27/2024

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.

2	01/21/2023	3880859	KTC MAX INC		FOREST, RICHARDSON	049146667	GA	10/14/1970	AZ	0292004515	N	2	4
	Vehicle Violation:		392.2 Wheel (Mud) Flaps missing or defective				NON-C	DOS					
Driver Violation:		olation:	395.8(f)(1) Driver		ivers record of duty status not current			DOS					
Vehicle Violation:		/iolation:	393.9(a) Inoperative turn signal				NON-C	DOS					
Driver Violation:		olation:	395.8 Record of Duty Status violation (general/form and manner)				NON-C	DOS					
3	09/11/2024	4 3283188 LEADER FREIGH SYSTEMS INC		Г	RICHARDSON, FOREST	049146667	GA	GA 10/14/1970 IL		4180980301	N	3	0
Violati	Violation Summary												
v	iolation #	Description									# of Violations # of Out- Viol		
392.2	.2 Wheel (Mud) Flaps missing or defective									3			
395.8(f))(1)	Drivers record of duty status not current										1 0	
393.9(a	ı)	Inoperative turn signal										1	
395.8		Record of Duty Status violation (general/form and manner)											0

The summary counts and rates only include violations that were attributable to RICHARDSON, FOREST.

Report executed at: 1/3/2025 1:07:55 PM MCMIS snapshot date: 12/27/2024

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.