

# PSP Detailed Report

Federal Motor Carrier Safety Administration

Driver Information															
Last Name		First Name		License #		State									
TOLENTINO		JOEY		H01108071		HI									
Crash Activity															
Crash Summary (Crashes listed represent a driver's involvement in FMCSA-reportable crashes, without any determination as to responsibility.)															
# of Crashes:		0		# of Crashes with Fatalities:		0		# of Crashes with Injuries:		0		# of Towaways:		0	
# Not preventable:		0		# of Fatalities:		0		# of Injuries:		0		# of Hazmat Releases:		0	
Crash Details (Crashes listed represent a driver's involvement in FMCSA-reportable crashes, without any determination as to responsibility.)															
	Date	DOT #	Carrier Name	Driver Name	Driver Lic	State	Driver DOB	Rpt St	Report Number	Location	# Fatalities	# of Injuries			
Inspection Activity (3 year history from MCMIS snapshot date)															
Inspection Summary															
Driver Summary				Vehicle Summary				Hazmat Summary							
Driver Inspections:		6		Vehicle Inspections:		4		Hazmat Inspections				0			
Driver Out-of-service Inspections:		0		Vehicle Out-of-service Inspections:		2		Hazmat Out-of-service Inspections:				0			
Driver Out-of-service Rate:		0%		Vehicle Out-of-service Rate:		50%		Hazmat Out-of-service Rate:				0%			
Inspection Details															
Carrier Info				Driver Info				Inspection Info							
	Date	DOT #	Carrier Name	Driver Name	Driver Lic	State	Driver DOB	Rpt St	Report Number	Hazmat Insp	Insp Level	# of Viol			
1	02/02/2023	3741789	NESTA INTERNATIONAL	TOLENTINO, JOEY	H01108071	HI	02/23/1990	TX	6I9D0XCNA3	N	2	1			
Vehicle Violation:		393.45(b)(2)		Brake Hose or Tubing Chafing and/or Kinking Under Vehicle				NON-OOS							

Report executed at: 12/24/2024 2:16:01 PM

MCMIS snapshot date: 11/29/2024

For an explanation of FMCSA-reportable crashes see: <https://www.psp.fmcsa.dot.gov/psp/?redirectUrl=FAQ>

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.

2	02/06/2023	3741789	NESTA INTERNATIONAL LLC	TOLENTINO, JOEY	H01108071	HI	02/23/1990	OH	0814000178	N	1	2
Driver Violation:		392.2	State/Local Laws - Speeding 6-10 miles per hour over the speed limit		NON-OOS							
Vehicle Violation:		393.9(a)	Inoperable Required Lamp		OOS							
3	04/11/2023	3741789	NESTA INTERNATIONAL LLC	TOLENTINO, JOEY	H01108071	HI	02/23/1990	MO	W158002305	N	2	1
Driver Violation:		395.8	Record of Duty Status violation (general/form and manner)		NON-OOS							
4	04/28/2023	3741789	NESTA INTERNATIONAL LLC	TOLENTINO, JOEY	H01108071	HI	02/23/1990	IN	9646000015	N	3	1
Driver Violation:		392.2	State/Local Laws - Speeding 6-10 miles per hour over the speed limit		NON-OOS							
5	07/17/2023	3119644	CNB LOGISTICS LLC	TOLENTINO, JOEY	H01108071	HI	02/23/1990	HI	00CK001763	N	3	3
Driver Violation:		392.16(a)	Failing to use seat belt while operating a CMV		NON-OOS							
Vehicle Violation:		392.2	State vehicle registration or License Plate violation		NON-OOS							
Vehicle Violation:		392.2	Violation of Local Laws - Explain		NON-OOS							
6	08/25/2023	1402201	MCB INC	TOLENTINO, JOEY	H01108071	HI	02/23/1990	HI	CU42000129	N	1	5
Vehicle Violation:		396.3(a)(1)	Brake - Leak from air chamber		NON-OOS							
Vehicle Violation:		396.3(a)(1)	Brake system pressure loss		OOS							
Vehicle Violation:		393.95(a)	No/discharged/unsecured fire extinguisher		NON-OOS							
Vehicle Violation:		393.9(a)	Inoperable Required Lamp		NON-OOS							
Vehicle Violation:		393.45(d)	Brake connections with leaks or constrictions		NON-OOS							

#### Violation Summary

Violation #	Description	# of Violations	# of Out-of-service Violations
392.16(a)	Failing to use seat belt while operating a CMV	1	0
392.2	State vehicle registration or License Plate violation	4	0
393.9(a)	Inoperable Required Lamp	2	1
396.3(a)(1)	Brake - Leak from air chamber	2	1
393.95(a)	No/discharged/unsecured fire extinguisher	1	0
393.45(d)	Brake connections with leaks or constrictions	1	0
393.45(b)(2)	Brake Hose or Tubing Chafing and/or Kinking Under Vehicle	1	0
395.8	Record of Duty Status violation (general/form and manner)	1	0

The summary counts and rates only include violations that were attributable to TOLENTINO, JOEY.

Report executed at: 12/24/2024 2:16:01 PM

MCMIS snapshot date: 11/29/2024

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.

For an explanation of FMCSA-reportable crashes see: <https://www.psp.fmcsa.dot.gov/psp/?redirectUrl=FAQ>