PSP Detailed Report

Federal Motor Carrier Safety Administration

		Drive	er Info	orma	ation										
Last Name	License #						State								
DURANNAVEIRA		D230295512000						FL							
DURAN	ANGEL LUIS			D230295512000						FL					
NAVEIRA		D230295512000						FL							
Crash Activity															
Crash Summary (Crashes listed represent a driver's involvement in FMCSA-reportable crashes, without any determination as to responsibility.)															
# of Crashes:	0 # of Crashes with Fatalit			0			# of Crash	es with Ir	njuries:	0	0 # of To			0	
# Not preventable:	0	# of Fatal	ities:	0				# of Ir	njuries:	0	# of Hazmat Re			0	
Crash Details (Crashes listed represent a driver's involvement in FMCSA-reportable crashes, without any determination as to responsibility.)															
Date DOT # Carrie	r Name	Driver Name	Driver Lic St			State	Driver DOB	Rpt St	Report	Number	Location	# Fatalities	# of Inj	uries	
Inspection Activity (3 year history from MCMIS snapshot date)															
Inspection Summary															
Driver Summary	Vehicle Summary					Hazmat Summary									
Driver Inspections:	Vehicle Inspections:					2 H	2 Hazmat Inspections						0		
Driver Out-of-service Inspections:	Vehicle Out-of-service Inspections:					0 H	Hazmat Out-of-service Inspections:								
Driver Out-of-service Rate:	0%	Vehicle Out-of-service Rate:				0% H	Hazmat Out-of-service Rate: 0%						0%		

Report executed at: 5/19/2025 9:32:44 AM

MCMIS snapshot date: 04/25/2025

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.

Inspec	tion Details														
Carrier Info				Driver Info	Driver Info					Inspection Info					
	Date	DOT #	Carrier Name	Driver Name	Driver Lic	State	Driver DOB	Rpt St	Report Number	Hazmat Insp	Insp Level	# of Viol			
1	12/09/2024	821903	H AND H LIQUID SLUDGE DISPOSAL INC	DURAN NAVEIRA, ANGEL	D230295512000	FL	10/15/1983	FL	3857003624	N	2	4			
Vehicle Violation: 393.11B-CSSRR REFL			393.11B-CSSRR RE	SPICUITY SYSTEMS - TRAILERS, SIDE RETRO LECTIVE SHEETING INADEQUATE ON VEHICLE NON-OOS UFACTURED ON OR AFTER DECEMBER 1, 1993											
Vehicle Violation: 393.11A1-CSLRR RETR		SPICUITY SYSTEMS - TRUCK TRACTOR, LOWER REAR RO REFLECTIVE SHEETING MISSING ON VEHICLE NON-OOS UFACTURED ON OR AFTER JULY 1, 1997													
Vehicle Violation: 393.11A1-CSURR RETR		SPICUITY SYSTEMS - TRUCK TRACTOR, UPPER REAR RO REFLECTIVE SHEETING MISSING ON VEHICLE NON-OC UFACTURED ON OR AFTER JULY 1, 1997			NON-OOS										
	Vehicle \	e Violation: 393.9A-LBL LIGH		ITING - BACKUP LAMP INOPERATIVE			DOS								
2	03/13/2025	2828543	ZIGI FREIGHT INC	DURAN NAVEIRA, ANGEL	D230295512000	FL	10/15/1983	SD	5290002591	N	2	1			
	Driver Vi	olation:	392.60A-D DF	IVER - UNAUTHORIZED PASSENGER(S) O											
Violati	on Summary	,													
Violation #		Description					# of Violat	ions	# of Out-of-service Violations						
392.60	λ-D	DRIVER - UNAUTHORIZED PASSENGER(S) ON-BOARD A CMV								1		0			
393.11B-CSSRR CONSPICUITY SYSTEMS - TRAILERS, SIDI DECEMBER 1, 1993				E RETRO REFLECTIVE SHEETING INADEQUATE ON VEHICLE MANUFACTURED ON OR AFTER						1 0					
393.11A1-CSLRR CONSPICUITY SYSTEMS - TRUCK TRACTO OR AFTER JULY 1, 1997				CTOR, LOWER REAR RETRO REFLECTIVE	N	1		0							
393.11A1-CSURR CONSPICUITY SYSTEMS - TRUCK TRACT OR AFTER JULY 1, 1997				TOR, UPPER REAR RETRO REFLECTIVE	N	1		0							
393.9A-LBL LIGHTING - BACKUP LAMP INOPERATIVE				1								0			

The summary counts and rates only include violations that were attributable to DURANNAVEIRA, ANGEL.

Report executed at: 5/19/2025 9:32:44 AM

MCMIS snapshot date: 04/25/2025

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.