## **PSP** Detailed Report

Federal Motor Carrier Safety Administration

						Driv	ver Ir	nform	ation										
Last	Name			Fire	st Name		Lic	License #					State						
ROD	RIGUEZAGUA	DO		NC	EL GIRALDO		50	50977917					ТХ						
ROD	RIGUEZAGUA	DO		NC	NOEL				R362627701720					FL					
ROD	RIGUEZ			NC	EL GIRALDO		50	0977917	7			ТХ							
RODRIGUEZ RODRIGUEZ AGUADO AGUADO Crash Summary (Crashes listed represent a # of Crashes: # Not preventable: Crash Details (Crashes listed represent a d					EL GIRALDO		R	R362627701720					FL						
AGU	ADO			NC	EL GIRALDO		50	0977917	7				тх						
AGUADO					EL GIRALDO		R	3626277	701720				FL						
						C	rash	n Activ	/ity										
Cra	Crash Summary (Crashes listed represent a driver's involvement in FMCSA-reportable crashes, without any determination as to responsibility.)																		
		#	# of Crashes:	2		# of Crashes with Fata	alities	s: 0			# of Cras	hes with I	njuries	s: 1		# of To	waways: 2		
		# Not	preventable:	0		alities	s: 0	0 <b># of</b>					Injuries: 1 # of Hazmat Re						
Cra	sh Details (C	rashes listed r	epresent a d	rive	r's involvement	in FMCSA-reportable c	rashe	es, witl	hout any	deter	mination as t	o respor	nsibilit	ity.)					
	Date	DOT #	Carr	Carrier Name		Driver Name		Driver Lic		Stat	e Driver DOE	B Rpt St	Report Number		er Locati	on # Fatalities	ities # of Injuries		
1	06/29/2020	2505119	2505119 NIS EXPRESS INC RODRIGUEZ AGUADO, NOEL		R	R362627701720 FL			05/12/1970	OH	OH0205105449		19 IR 7	1 0	1				
2	07/03/2022	7/03/2022 3156752 TRUCK FL		ORI	DA CORP RO	RODRIGUEZ AGUADO, Noel		R362627701720		FL	05/12/1970	СТ	CT2200284053		3 91-N	1 0	0 0		
			• •		Inspe	ection Activity (3 year	r his	tory f	rom MC	MIS	snapshot da	te)							
Insp	ection Sum	nary																	
Inspection Summary Driver Summary						Vehic	le Sum	mary						Hazmat Su	mmary				
Driver Inspections:					2	2 Vehicle Inspections:					0	Hazmat Inspections							
Driv	er Out-of-servi	ce Inspections:			1	1 Vehicle Out-of-service Inspections:					0	Hazmat Out-of-service Inspections:							
Driv	er Out-of-servi	ce Rate:			50%	Vehicle Out-of-service Rate:					0%	Hazmat Out-of-service Rate: 0%							

Report executed at: 1/24/2025 6:08:11 PM

MCMIS snapshot date: 12/27/2024

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.

Inspec	tion Details													
Carrier Info				Driver Info					Inspection Info					
	Date	DOT #	Carrier Name	Driver Name	Driver Lic	State	Driver DOB	Rpt St	Report Number	Hazmat Insp	Insp Level	# of Viol		
1	12/27/2021	3156752	TRUCK FLORIDA CORP	RODRIGUEZ AGUADO, NOEL	R362627701720	FL	05/12/1970	со	PF05408544	N	3	1		
	Driver Vi	olation:	395.8(e)(1) False	report of drivers record of duty status OOS										
2	11/21/2022	3638018	ELIO AP TRANSPORT LLC	RODRIGUEZ AGUADO, NOEL	R362627701720	FL	05/12/1970	NC	0006476814	N	3	0		
Violatio	on Summary													
Violation #				# of Violati	# of Violations		# of Out-of-service Violations							
395.8(e)(1)		False report o	f drivers record of duty status		1		1							

The summary counts and rates only include violations that were attributable to RODRIGUEZAGUADO, NOEL GIRALDO.

Report executed at: 1/24/2025 6:08:11 PM MCMIS snapshot date: 12/27/2024

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.