

# PSP Detailed Report

Federal Motor Carrier Safety Administration

Driver Information													
Last Name	First Name	License #	State										
RIVAS	YOELME	H655960783480	FL										
HERNANDEZRIVAS	YOELME	H655960783480	FL										
HERNANDEZ	YOELME	H655960783480	FL										

Crash Activity													
Crash Summary (Crashes listed represent a driver's involvement in FMCSA-reportable crashes, without any determination as to responsibility.)													
# of Crashes:	0	# of Crashes with Fatalities:	0	# of Crashes with Injuries:	0	# of Towaways:	0						
# Not preventable:	0	# of Fatalities:	0	# of Injuries:	0	# of Hazmat Releases:	0						
Crash Details (Crashes listed represent a driver's involvement in FMCSA-reportable crashes, without any determination as to responsibility.)													
	Date	DOT #	Carrier Name	Driver Name	Driver Lic	State	Driver DOB	Rpt St	Report Number	Location	# Fatalities	# of Injuries	

Inspection Activity (3 year history from MCMIS snapshot date)													
Inspection Summary													
Driver Summary				Vehicle Summary				Hazmat Summary					
Driver Inspections:		2		Vehicle Inspections:		2		Hazmat Inspections				0	
Driver Out-of-service Inspections:		0		Vehicle Out-of-service Inspections:		0		Hazmat Out-of-service Inspections:				0	
Driver Out-of-service Rate:		0%		Vehicle Out-of-service Rate:		0%		Hazmat Out-of-service Rate:				0%	

Report executed at: 2/20/2025 2:28:28 PM

MCMIS snapshot date: 01/31/2025

For an explanation of FMCSA-reportable crashes see: <https://www.psp.fmcsa.dot.gov/psp/?redirectUrl=FAQ>

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.

Inspection Details												
Carrier Info				Driver Info				Inspection Info				
	Date	DOT #	Carrier Name	Driver Name	Driver Lic	State	Driver DOB	Rpt St	Report Number	Hazmat Insp	Insp Level	# of Viol
1	08/09/2023	3471406	DY EXPRESS CORP	HERNANDEZ RIVAS, YOELME	H655960783480	FL	09/28/1978	TX	6NHI9DIA58	N	2	5
<div>Vehicle Violation: 392.2 State vehicle registration or License Plate violation NON-OOS</div> <div>Vehicle Violation: 393.9(a) Inoperative turn signal NON-OOS</div> <div>Vehicle Violation: 393.11 Truck-Tractor upper body corner requirements for retroreflective sheeting or reflex reflective material for vehicles manufactured after July 1997 NON-OOS</div> <div>Vehicle Violation: 393.11 Truck-Tractor lower rear mud flaps retroreflective sheeting / reflex reflective material requirements for vehicles manufactured after July 1997 NON-OOS</div> <div>Vehicle Violation: 393.9(a) Inoperable Required Lamp NON-OOS</div>												
2	05/30/2024	1437731	STAR TRANSPORTATION PA INC	HERNANDEZ RIVAS, YOELME	H655960783480	FL	09/28/1978	WA	X847000213	N	2	0
Violation Summary												
Violation #	Description								# of Violations	# of Out-of-service Violations		
392.2	State vehicle registration or License Plate violation								1	0		
393.9(a)	Inoperative turn signal								2	0		
393.11	Truck-Tractor upper body corner requirements for retroreflective sheeting or reflex reflective material for vehicles manufactured after July 1997								2	0		

The summary counts and rates only include violations that were attributable to RIVAS, YOELME.

Report executed at: 2/20/2025 2:28:28 PM

MCMIS snapshot date: 01/31/2025

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.

For an explanation of FMCSA-reportable crashes see: <https://www.psp.fmcsa.dot.gov/psp/?redirectUrl=FAQ>