

PSP Detailed Report

Federal Motor Carrier Safety Administration

Driver Information															
Last Name		First Name		License #			State								
DIAZ		VICTOR		47739421			TX								
Crash Activity															
Crash Summary (Crashes listed represent a driver's involvement in FMCSA-reportable crashes, without any determination as to responsibility.)															
# of Crashes:		0		# of Crashes with Fatalities:		0		# of Crashes with Injuries:		0		# of Towaways:		0	
# Not preventable:		0		# of Fatalities:		0		# of Injuries:		0		# of Hazmat Releases:		0	
Crash Details (Crashes listed represent a driver's involvement in FMCSA-reportable crashes, without any determination as to responsibility.)															
	Date	DOT #	Carrier Name	Driver Name	Driver Lic	State	Driver DOB	Rpt St	Report Number	Location	# Fatalities	# of Injuries			
Inspection Activity (3 year history from MCMIS snapshot date)															
Inspection Summary															
Driver Summary				Vehicle Summary				Hazmat Summary							
Driver Inspections:		8		Vehicle Inspections:		7		Hazmat Inspections				0			
Driver Out-of-service Inspections:		2		Vehicle Out-of-service Inspections:		4		Hazmat Out-of-service Inspections:				0			
Driver Out-of-service Rate:		25%		Vehicle Out-of-service Rate:		57%		Hazmat Out-of-service Rate:				0%			
Inspection Details															
Carrier Info				Driver Info				Inspection Info							
	Date	DOT #	Carrier Name	Driver Name	Driver Lic	State	Driver DOB	Rpt St	Report Number	Hazmat Insp	Insp Level	# of Viol			
1	06/30/2022	3788046	JOLKADOT TRANSPORT LLC	DIAZ, VICTOR	47739421	TX	10/14/1989	LA	LADR007057	N	2	1			
Vehicle Violation:		392.2		Dimension Violation (Width / Height / Length)			NON-OOS								

Report executed at: 4/10/2025 9:01:34 AM

MCMIS snapshot date: 02/28/2025

For an explanation of FMCSA-reportable crashes see: <https://www.psp.fmcsa.dot.gov/psp/?redirectUrl=FAQ>

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.

2	09/01/2022	3788046	JOLKADOT TRANSPORT LLC	DIAZ, VICTOR	47739421	TX	10/14/1989	WY	WSDD000259	N	2	4
Vehicle Violation: 393.205(c) Wheel fasteners loose and/or missing NON-OOS Vehicle Violation: 393.45(b)(2) Brake Hose or Tubing Chafing and/or Kinking - Connection to Power Unit NON-OOS Vehicle Violation: 392.2 Dimension Violation (Width / Height / Length) NON-OOS Driver Violation: 392.2 Failure to obey traffic control device NON-OOS												
3	09/03/2022	3788046	JOLKADOT TRANSPORT LLC	DIAZ, VICTOR	47739421	TX	10/14/1989	IN	7301003088	N	2	5
Vehicle Violation: 392.2 IRP Apportioned Tag or Registration Violation NON-OOS Vehicle Violation: 392.2 Dimension Violation (Width / Height / Length) NON-OOS Vehicle Violation: 392.2 Dimension Violation (Width / Height / Length) NON-OOS Vehicle Violation: 393.25(f) Stop lamp violations NON-OOS Vehicle Violation: 393.9(a) Inoperative turn signal OOS												
4	09/04/2022	3788046	JOLKADOT TRANSPORT LLC	DIAZ, VICTOR	47739421	TX	10/14/1989	IN	7306003662	N	2	13
Vehicle Violation: 393.75(a)(3) Tire-flat and/or audible air leak OOS Vehicle Violation: 392.2 State or International Fuel Tax (IFTA) Violation NON-OOS Vehicle Violation: 392.2 IRP Apportioned Tag or Registration Violation NON-OOS Vehicle Violation: 393.9(a) Inoperable Required Lamp NON-OOS Vehicle Violation: 392.2 Dimension Violation (Width / Height / Length) NON-OOS Vehicle Violation: 392.2 Dimension Violation (Width / Height / Length) NON-OOS Vehicle Violation: 392.2 Dimension Violation (Width / Height / Length) NON-OOS Vehicle Violation: 393.11 Truck-Tractor lower rear mud flaps retroreflective sheeting / reflex reflective material requirements for vehicles manufactured after July 1997 NON-OOS Vehicle Violation: 393.11 Truck-Tractor upper body corner requirements for retroreflective sheeting or reflex reflective material for vehicles manufactured after July 1997 NON-OOS Vehicle Violation: 392.2 IRP Apportioned Tag or Registration Violation NON-OOS Driver Violation: 395.22(h)(3) Driver failed to maintain instruction sheet for ELD malfunction reporting requirements NON-OOS Driver Violation: 395.22(h)(2) Driver failing to maintain ELD instruction sheet NON-OOS Vehicle Violation: 393.205(c) Wheel fasteners loose and/or missing NON-OOS												
5	10/04/2022	3788046	JOLKADOT TRANSPORT LLC	DIAZ, VICTOR	47739421	TX	10/14/1989	WA	W318005548	N	2	10

Report executed at: 4/10/2025 9:01:34 AM

MCMIS snapshot date: 02/28/2025

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.

For an explanation of FMCSA-reportable crashes see: <https://www.psp.fmcsa.dot.gov/psp/?redirectUrl=FAQ>

<div>Vehicle Violation: 393.106(d) Insufficient aggregate working load limit OOS</div> <div>Vehicle Violation: 393.75(a)(1) Tire-ply or belt material exposed OOS</div> <div>Vehicle Violation: 393.75(g) Weight carried exceeds tire load limit OOS</div> <div>Vehicle Violation: 393.207(f) Air suspension pressure loss OOS</div> <div>Vehicle Violation: 393.100(b) Leaking/spilling/blowing/falling cargo OOS</div> <div>Vehicle Violation: 392.2 Violation of Local Laws - Explain NON-OOS</div> <div>Driver Violation: 392.2 State/Local Laws - Excessive weight - 2501-5000 lbs over on an axle/axle groups NON-OOS</div> <div>Driver Violation: 392.2 Dimension Violation (Width / Height / Length) NON-OOS</div> <div>Driver Violation: 395.22(g) Portable ELD not mounted in a fixed position and visible to driver NON-OOS</div> <div>Driver Violation: 395.8(e)(1) False report of drivers record of duty status OOS</div>												
6	10/26/2022	3788046	JOLKADOT TRANSPORT LLC	DIAZ, VICTOR	47739421	TX	10/14/1989	UT	23HK000023	N	2	4
<div>Driver Violation: 395.8(e)(1) False report of drivers record of duty status OOS</div> <div>Driver Violation: 395.34(a)(1) Failing to note malfunction that requires use of paper log NON-OOS</div> <div>Vehicle Violation: 393.9(a) Inoperable Required Lamp NON-OOS</div> <div>Vehicle Violation: 393.9(a) Inoperable tail lamp NON-OOS</div>												
7	11/01/2022	3788046	JOLKADOT TRANSPORT LLC	DIAZ, VICTOR	47739421	TX	10/14/1989	TX	6FO89DMPRX	N	2	13

Report executed at: 4/10/2025 9:01:34 AM

MCMIS snapshot date: 02/28/2025

For an explanation of FMCSA-reportable crashes see: <https://www.psp.fmcsa.dot.gov/psp/?redirectUrl=FAQ>

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.

Vehicle Violation:	393.45(a)	Air Brake tubing improperly joined or spliced	OOS
Vehicle Violation:	393.106(c)(1)	No means to prevent cargo from rolling	OOS
Driver Violation:	999.	Speeding	NON-OOS
Vehicle Violation:	393.11	Truck-Tractor upper body corner requirements for retroreflective sheeting or reflex reflective material for vehicles manufactured after July 1997	NON-OOS
Vehicle Violation:	393.11	Truck-Tractor lower rear mud flaps retroreflective sheeting / reflex reflective material requirements for vehicles manufactured after July 1997	NON-OOS
Vehicle Violation:	393.9(a)	Inoperable Required Lamp	NON-OOS
Vehicle Violation:	393.9(a)	Inoperable Required Lamp	NON-OOS
Vehicle Violation:	393.19	Inoperative/Defective Hazard Warning Lamp	NON-OOS
Vehicle Violation:	393.9(a)	Inoperative turn signal	NON-OOS
Driver Violation:	395.3(a)(3)(ii)	Driving beyond 8 hour driving limit since the end of the last on duty, off duty, or sleeper period of at least 30 minutes	NON-OOS
Vehicle Violation:	393.55(e)	No or Defective ABS Malfunction Indicator Lamp for trailer manufactured after 03/01/1998	NON-OOS
Vehicle Violation:	393.104(b)	Damaged securement system/tiedowns	NON-OOS
Vehicle Violation:	393.9(a)	Inoperative Brake Lamps	NON-OOS

8	07/29/2024	4260431	JOLTZ LLC	DIAZ, VICTOR	47739421	TX	10/14/1989	SD	5860001665	N	3	0
---	------------	---------	-----------	--------------	----------	----	------------	----	------------	---	---	---

Violation Summary

Violation #	Description	# of Violations	# of Out-of-service Violations
393.45(a)	Air Brake tubing improperly joined or spliced	1	1
393.106(c)(1)	No means to prevent cargo from rolling	1	1
999.	Speeding	1	0
393.11	Truck-Tractor upper body corner requirements for retroreflective sheeting or reflex reflective material for vehicles manufactured after July 1997	4	0
393.9(a)	Inoperable Required Lamp	8	1
393.19	Inoperative/Defective Hazard Warning Lamp	1	0
395.3(a)(3)(ii)	Driving beyond 8 hour driving limit since the end of the last on duty, off duty, or sleeper period of at least 30 minutes	1	0
393.55(e)	No or Defective ABS Malfunction Indicator Lamp for trailer manufactured after 03/01/1998	1	0
393.104(b)	Damaged securement system/tiedowns	1	0
393.75(a)(3)	Tire-flat and/or audible air leak	1	1
392.2	State or International Fuel Tax (IFTA) Violation	15	0

Report executed at: 4/10/2025 9:01:34 AM

MCMIS snapshot date: 02/28/2025

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.

395.22(h)(3)	Driver failed to maintain instruction sheet for ELD malfunction reporting requirements	1	0
395.22(h)(2)	Driver failing to maintain ELD instruction sheet	1	0
393.205(c)	Wheel fasteners loose and/or missing	2	0
393.106(d)	Insufficient aggregate working load limit	1	1
393.75(a)(1)	Tire-ply or belt material exposed	1	1
393.75(g)	Weight carried exceeds tire load limit	1	1
393.207(f)	Air suspension pressure loss	1	1
393.100(b)	Leaking/spilling/blowing/falling cargo	1	1
395.22(g)	Portable ELD not mounted in a fixed position and visible to driver	1	0
395.8(e)(1)	False report of drivers record of duty status	2	2
393.25(f)	Stop lamp violations	1	0
393.45(b)(2)	Brake Hose or Tubing Chafing and/or Kinking - Connection to Power Unit	1	0
395.34(a)(1)	Failing to note malfunction that requires use of paper log	1	0

The summary counts and rates only include violations that were attributable to DIAZ, VICTOR.

Report executed at: 4/10/2025 9:01:34 AM

MCMIS snapshot date: 02/28/2025

For an explanation of FMCSA-reportable crashes see: <https://www.psp.fmcsa.dot.gov/psp/?redirectUrl=FAQ>

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.