

# PSP Detailed Report

Federal Motor Carrier Safety Administration

Driver Information															
Last Name		First Name		License #			State								
JAUREGUI		HECTOR		D6153267			CA								
Crash Activity															
Crash Summary (Crashes listed represent a driver's involvement in FMCSA-reportable crashes, without any determination as to responsibility.)															
# of Crashes:		0		# of Crashes with Fatalities:		0		# of Crashes with Injuries:		0		# of Towaways:		0	
# Not preventable:		0		# of Fatalities:		0		# of Injuries:		0		# of Hazmat Releases:		0	
Crash Details (Crashes listed represent a driver's involvement in FMCSA-reportable crashes, without any determination as to responsibility.)															
	Date	DOT #	Carrier Name	Driver Name	Driver Lic	State	Driver DOB	Rpt St	Report Number	Location	# Fatalities	# of Injuries			
Inspection Activity (3 year history from MCMIS snapshot date)															
Inspection Summary															
Driver Summary				Vehicle Summary				Hazmat Summary							
Driver Inspections:		8		Vehicle Inspections:		5		Hazmat Inspections				0			
Driver Out-of-service Inspections:		0		Vehicle Out-of-service Inspections:		2		Hazmat Out-of-service Inspections:				0			
Driver Out-of-service Rate:		0%		Vehicle Out-of-service Rate:		40%		Hazmat Out-of-service Rate:				0%			
Inspection Details															
Carrier Info				Driver Info					Inspection Info						
	Date	DOT #	Carrier Name	Driver Name	Driver Lic	State	Driver DOB	Rpt St	Report Number	Hazmat Insp	Insp Level	# of Viol			
1	03/15/2024	3989686	TEZ JET INC	JAUREGUI, HECTOR	D6153267	CA	06/02/1986	ND	FT58000417	N	2	0			

Report executed at: 4/17/2025 9:24:49 AM

MCMIS snapshot date: 02/28/2025

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.

For an explanation of FMCSA-reportable crashes see: <https://www.psp.fmcsa.dot.gov/psp/?redirectUrl=FAQ>

2	06/05/2024	3470394	DAN CARGO LOGISTICS INC	JAUREGUI, HECTOR	D6153267	CA	06/02/1986	CO	0761920156	N	3	0
3	08/13/2024	3946085	GTFV TRANSPORT INC	JAUREGUI, HECTOR	D6153267	CA	06/02/1986	CA	UC0D001617	N	2	2
Vehicle Violation: 392.2 State vehicle registration or License Plate violation NON-OOS Vehicle Violation: 392.2 Dimension Violation (Width / Height / Length) NON-OOS												
4	10/24/2024	3946085	GTFV TRANSPORT INC	JAUREGUI, HECTOR	D6153267	CA	06/02/1986	CA	UCSK000362	N	1	0
5	10/24/2024	3946085	GTFV TRANSPORT INC	JAUREGUI, HECTOR	D6153267	CA	06/02/1986	CA	NCU6004001	N	1	2
Vehicle Violation: 392.2-SLLED State/Local Laws - Excessive dimension (width/height/length) NON-OOS Vehicle Violation: 393.75A3-TAOL Tires - All others, leaking or inflation less than 50% of the maximum inflation pressure on tire not equipped with ATIS OOS												
6	10/25/2024	3946085	GTFV TRANSPORT INC	JAUREGUI, HECTOR	D6153267	CA	06/02/1986	OR	AS39890031	N	3	0
Driver Violation: 392.2-SLLED State/Local Laws - Excessive dimension (width/height/length) NON-OOS												
7	01/27/2025	3946085	GTFV TRANSPORT INC	JAUREGUI, HECTOR	D6153267	CA	06/02/1986	PA	XL00074396	N	3	0
8	02/13/2025	3946085	GTFV TRANSPORTATION INC	JAUREGUI, HECTOR	D6153267	CA	06/02/1986	MI	STRAL03589	N	2	5
Vehicle Violation: 393.207F-SDAS Suspension - Deflated air suspension OOS Vehicle Violation: 393.207F-SDAS Suspension - Deflated air suspension OOS Vehicle Violation: 393.207F-SDAS Suspension - Deflated air suspension OOS Vehicle Violation: 393.207F-SDAS Suspension - Deflated air suspension OOS Driver Violation: 392.2-SLLEWA3 State/Local Laws - Excessive weight - More than 5000 lbs over on an axle/axle groups NON-OOS												
<b>Violation Summary</b>												
Violation #	Description								# of Violations	# of Out-of-service Violations		
392.2	State vehicle registration or License Plate violation								2	0		
392.2-SLLED	State/Local Laws - Excessive dimension (width/height/length)								2	0		
393.207F-SDAS	Suspension - Deflated air suspension								4	4		
392.2-SLLEWA3	State/Local Laws - Excessive weight - More than 5000 lbs over on an axle/axle groups								1	0		
393.75A3-TAOL	Tires - All others, leaking or inflation less than 50% of the maximum inflation pressure on tire not equipped with ATIS								1	1		

The summary counts and rates only include violations that were attributable to JAUREGUI, HECTOR.

Report executed at: 4/17/2025 9:24:49 AM

MCMIS snapshot date: 02/28/2025

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.