

PSP Detailed Report

Federal Motor Carrier Safety Administration

Driver Information															
Last Name		First Name		License #			State								
HERNANDEZ		RAGGIEL		42797651			TX								
Crash Activity															
Crash Summary (Crashes listed represent a driver's involvement in FMCSA-reportable crashes, without any determination as to responsibility.)															
# of Crashes:		0		# of Crashes with Fatalities:		0		# of Crashes with Injuries:		0		# of Towaways:		0	
# Not preventable:		0		# of Fatalities:		0		# of Injuries:		0		# of Hazmat Releases:		0	
Crash Details (Crashes listed represent a driver's involvement in FMCSA-reportable crashes, without any determination as to responsibility.)															
	Date	DOT #	Carrier Name	Driver Name	Driver Lic	State	Driver DOB	Rpt St	Report Number	Location	# Fatalities	# of Injuries			
Inspection Activity (3 year history from MCMIS snapshot date)															
Inspection Summary															
Driver Summary				Vehicle Summary				Hazmat Summary							
Driver Inspections:		2		Vehicle Inspections:		2		Hazmat Inspections				0			
Driver Out-of-service Inspections:		0		Vehicle Out-of-service Inspections:		0		Hazmat Out-of-service Inspections:				0			
Driver Out-of-service Rate:		0%		Vehicle Out-of-service Rate:		0%		Hazmat Out-of-service Rate:				0%			
Inspection Details															
Carrier Info				Driver Info				Inspection Info							
	Date	DOT #	Carrier Name	Driver Name	Driver Lic	State	Driver DOB	Rpt St	Report Number	Hazmat Insp	Insp Level	# of Viol			
1	07/13/2022	2475440	ALL TIME LOGISTICS INC	HERNANDEZ, RAGGIEL	42797651	TX	10/01/1989	TN	EED0027311	N	1	1			
Vehicle Violation:		392.2		DIMENSION VIOLATION (WIDTH / HEIGHT / LENGTH)			NON-OOS								

Report executed at: 4/22/2025 10:18:37 AM

MCMIS snapshot date: 03/28/2025

For an explanation of FMCSA-reportable crashes see: <https://www.psp.fmcsa.dot.gov/psp/?redirectUrl=FAQ>

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.

2	10/17/2024	2595939	PB ENERGY LOGISTICS LLC	HERNANDEZ, RAGGIEL	42797651	TX	10/01/1989	TX	V241608648	N	2	6
Driver Violation:	395.8F01	DRIVERS RECORD OF DUTY STATUS NOT CURRENT			NON-OOS							
Vehicle Violation:	393.9	INOPERABLE REQUIRED LAMP			NON-OOS							
Vehicle Violation:	393.9	INOPERABLE REQUIRED LAMP			NON-OOS							
Vehicle Violation:	393.60C	WINDSHIELD - DAMAGED OR DISCOLORED			NON-OOS							
Vehicle Violation:	393.55D2	CMV MANUFACTURED ON/AFTER 3/1/2001 NOT EQUIPPED WITH ABS MALFUNCTION CIRCUIT / LAMP FROM TOWED VEHICLE IN CAB			NON-OOS							
Vehicle Violation:	393.45DLUV	BRAKE CONNECTIONS WITH LEAKS UNDER VEHICLE			NON-OOS							

Violation Summary

Violation #	Description	# of Violations	# of Out-of-service Violations
395.8F01	DRIVERS RECORD OF DUTY STATUS NOT CURRENT	1	0
393.9	INOPERABLE REQUIRED LAMP	2	0
393.60C	WINDSHIELD - DAMAGED OR DISCOLORED	1	0
393.55D2	CMV MANUFACTURED ON/AFTER 3/1/2001 NOT EQUIPPED WITH ABS MALFUNCTION CIRCUIT / LAMP FROM TOWED VEHICLE IN CAB	1	0
393.45DLUV	BRAKE CONNECTIONS WITH LEAKS UNDER VEHICLE	1	0
392.2	DIMENSION VIOLATION (WIDTH / HEIGHT / LENGTH)	1	0

The summary counts and rates only include violations that were attributable to HERNANDEZ, RAGGIEL.

Report executed at: 4/22/2025 10:18:37 AM

MCMIS snapshot date: 03/28/2025

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.

For an explanation of FMCSA-reportable crashes see: <https://www.psp.fmcsa.dot.gov/psp/?redirectUrl=FAQ>