

PSP Detailed Report

Federal Motor Carrier Safety Administration

Driver Information													
Last Name	First Name	License #	State										
GOMEZVEGA	JOSE	G521421683740	FL										
GOMEZ	JOSE ANTONIO	G521421683740	FL										
VEGA	JOSE ANTONIO	G521421683740	FL										

Crash Activity													
Crash Summary (Crashes listed represent a driver's involvement in FMCSA-reportable crashes, without any determination as to responsibility.)													
# of Crashes:	0	# of Crashes with Fatalities:	0	# of Crashes with Injuries:	0	# of Towaways:	0						
# Not preventable:	0	# of Fatalities:	0	# of Injuries:	0	# of Hazmat Releases:	0						
Crash Details (Crashes listed represent a driver's involvement in FMCSA-reportable crashes, without any determination as to responsibility.)													
	Date	DOT #	Carrier Name	Driver Name	Driver Lic	State	Driver DOB	Rpt St	Report Number	Location	# Fatalities	# of Injuries	

Inspection Activity (3 year history from MCMIS snapshot date)													
Inspection Summary													
Driver Summary				Vehicle Summary				Hazmat Summary					
Driver Inspections:		3		Vehicle Inspections:		3		Hazmat Inspections				0	
Driver Out-of-service Inspections:		1		Vehicle Out-of-service Inspections:		1		Hazmat Out-of-service Inspections:				0	
Driver Out-of-service Rate:		33%		Vehicle Out-of-service Rate:		33%		Hazmat Out-of-service Rate:				0%	

Report executed at: 4/28/2025 9:23:28 AM

MCMIS snapshot date: 03/28/2025

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.

For an explanation of FMCSA-reportable crashes see: <https://www.psp.fmcsa.dot.gov/psp/?redirectUrl=FAQ>

Inspection Details												
Carrier Info				Driver Info				Inspection Info				
	Date	DOT #	Carrier Name	Driver Name	Driver Lic	State	Driver DOB	Rpt St	Report Number	Hazmat Insp	Insp Level	# of Viol
1	04/25/2023	1284430	NORTH AMERICAN TRANSPORT SERVICES LLC	GOMEZ VEGA, JOSE	G521421683740	FL	10/14/1968	PA	F602311514	N	2	2
<div>Vehicle Violation: 393.55(d)(3) NO OR DEFECTIVE ABS MALFUNCTION INDICATOR FOR TOWED VEHICLES ON VEHICLES MANUFACTURED AFTER FEBRUARY 2001 NON-OOS</div> <div>Vehicle Violation: 393.45(d) BRAKE CONNECTIONS WITH LEAKS UNDER VEHICLE NON-OOS</div>												

Report executed at: 4/28/2025 9:23:28 AM

MCMIS snapshot date: 03/28/2025

For an explanation of FMCSA-reportable crashes see: <https://www.psp.fmcsa.dot.gov/psp/?redirectUrl=FAQ>

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.

2	10/31/2024	2635806	A M BEST TRANSPORTATION INC	GOMEZ VEGA, JOSE	G521421683740	FL	10/14/1968	MO	W147000201	N	1	19
<div>Vehicle Violation: 393.9A-LCL LIGHTING - CLEARANCE LAMP(S) INOPERATIVE NON-OOS</div> <div>Vehicle Violation: 393.45D-B AIR BRAKE - AUDIBLE AIR LEAK AT A PROPER CONNECTION NON-OOS</div> <div>Driver Violation: 395.8A1-HOSP HOS (PROPERTY) - FAILING TO HAVE A RECORD OF DUTY STATUS USING THE METHOD PRESCRIBED OOS</div> <div>Vehicle Violation: 393.95F EMERGENCY EQUIPMENT - STOPPED VEHICLE WARNING DEVICES MISSING OR IMPROPER NON-OOS</div> <div>Vehicle Violation: 396.3A1-BOS BRAKE - DEFECTIVE BRAKE(S) ARE EQUAL TO OR GREATER THAN 20% OF THE SERVICE BRAKES ON THE VEHICLE/COMBINATION OOS</div> <div>Vehicle Violation: 393.48A-BIBD DRUM BRAKE - INOPERATIVE OTHER THAN A STEERING AXLE NON-OOS</div> <div>Vehicle Violation: 393.48A-BIBD DRUM BRAKE - INOPERATIVE OTHER THAN A STEERING AXLE NON-OOS</div> <div>Vehicle Violation: 393.48A-BIBD DRUM BRAKE - INOPERATIVE OTHER THAN A STEERING AXLE NON-OOS</div> <div>Vehicle Violation: 393.48A-BIBD DRUM BRAKE - INOPERATIVE OTHER THAN A STEERING AXLE NON-OOS</div> <div>Vehicle Violation: 393.43A-TPV AIR BRAKE - INOPERABLE OR MISSING TRACTOR PROTECTION VALVE OOS</div> <div>Vehicle Violation: 393.45B2-B-AIR AIR BRAKE - HOSE/TUBING DAMAGED OR NOT SECURED NON-OOS</div> <div>Vehicle Violation: 393.48A-BIBD DRUM BRAKE - INOPERATIVE OTHER THAN A STEERING AXLE NON-OOS</div> <div>Driver Violation: 395.30B1-ELDDFR HOS (ELD) - DRIVER FAILING TO REVIEW RECORDS AND CERTIFY THE ACCURACY OF THE INFORMATION. NON-OOS</div> <div>Driver Violation: 395.24 HOS (ELD) - ELD FORM AND MANNER NON-OOS</div> <div>Vehicle Violation: 390.21TE2IV-D DRIVER - OPERATE A RENTED CMV WITHOUT RENTAL AGREEMENT ON-BOARD VEHICLE NON-OOS</div> <div>Vehicle Violation: 393.48A-BMBCBD DRUM BRAKE - MISSING/BROKEN COMPONENT(S) NON-OOS</div> <div>Vehicle Violation: 393.9A-LIL LIGHTING - IDENTIFICATION LAMP(S) INOPERATIVE NON-OOS</div> <div>Vehicle Violation: 396.3A1-BACL AIR BRAKE - AIR COMPRESSOR MOUNTING BOLTS LOOSE. OOS</div> <div>Vehicle Violation: 392.2-SLLIRP STATE/LOCAL LAWS - IRP APPORTIONED TAG OR REGISTRATION VIOLATION NON-OOS</div>												
3	01/11/2025	2635806	A M BEST TRANSPORTATION INC	GOMEZ VEGA, JOSE	G521421683740	FL	10/14/1968	NM	9328P0BFPQ	N	2	0

Violation Summary

Violation #	Description	# of Violations	# of Out-of-service Violations
393.55(d)(3)	NO OR DEFECTIVE ABS MALFUNCTION INDICATOR FOR TOWED VEHICLES ON VEHICLES MANUFACTURED AFTER FEBRUARY 2001	1	0
393.45(d)	BRAKE CONNECTIONS WITH LEAKS UNDER VEHICLE	1	0
393.9A-LCL	LIGHTING - CLEARANCE LAMP(S) INOPERATIVE	1	0

Report executed at: 4/28/2025 9:23:28 AM

MCMIS snapshot date: 03/28/2025

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.

393.45D-B	AIR BRAKE - AUDIBLE AIR LEAK AT A PROPER CONNECTION	1	0
395.8A1-HOSP	HOS (PROPERTY) - FAILING TO HAVE A RECORD OF DUTY STATUS USING THE METHOD PRESCRIBED	1	1
393.95F	EMERGENCY EQUIPMENT - STOPPED VEHICLE WARNING DEVICES MISSING OR IMPROPER	1	0
396.3A1-BOS	BRAKE - DEFECTIVE BRAKE(S) ARE EQUAL TO OR GREATER THAN 20% OF THE SERVICE BRAKES ON THE VEHICLE/COMBINATION	1	1
393.48A-BIBD	DRUM BRAKE - INOPERATIVE OTHER THAN A STEERING AXLE	5	0
393.43A-TPV	AIR BRAKE - INOPERABLE OR MISSING TRACTOR PROTECTION VALVE	1	1
393.45B2-B-AIR	AIR BRAKE - HOSE/TUBING DAMAGED OR NOT SECURED	1	0
395.30B1-ELDDFR	HOS (ELD) - DRIVER FAILING TO REVIEW RECORDS AND CERTIFY THE ACCURACY OF THE INFORMATION.	1	0
395.24	HOS (ELD) - ELD FORM AND MANNER	1	0
390.21TE2IV-D	DRIVER - OPERATE A RENTED CMV WITHOUT RENTAL AGREEMENT ON-BOARD VEHICLE	1	0
393.48A-BMBCBD	DRUM BRAKE - MISSING/BROKEN COMPONENT(S)	1	0
393.9A-LIL	LIGHTING - IDENTIFICATION LAMP(S) INOPERATIVE	1	0
396.3A1-BACL	AIR BRAKE - AIR COMPRESSOR MOUNTING BOLTS LOOSE.	1	1
392.2-SLLIRP	STATE/LOCAL LAWS - IRP APPORTIONED TAG OR REGISTRATION VIOLATION	1	0

The summary counts and rates only include violations that were attributable to GOMEZVEGA, JOSE.

Report executed at: 4/28/2025 9:23:28 AM

MCMIS snapshot date: 03/28/2025

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.

For an explanation of FMCSA-reportable crashes see: <https://www.psp.fmcsa.dot.gov/psp/?redirectUrl=FAQ>