

PSP Detailed Report

Federal Motor Carrier Safety Administration

Driver Information													
Last Name	First Name	License #	State										
TAYLOR	LETERRENCE	801212776	MS										
Crash Activity													
Crash Summary (Crashes listed represent a driver's involvement in FMCSA-reportable crashes, without any determination as to responsibility.)													
# of Crashes:	0	# of Crashes with Fatalities:	0	# of Crashes with Injuries:	0	# of Towaways:	0						
# Not preventable:	0	# of Fatalities:	0	# of Injuries:	0	# of Hazmat Releases:	0						
Crash Details (Crashes listed represent a driver's involvement in FMCSA-reportable crashes, without any determination as to responsibility.)													
	Date	DOT #	Carrier Name	Driver Name	Driver Lic	State	Driver DOB	Rpt St	Report Number	Location	# Fatalities	# of Injuries	
Inspection Activity (3 year history from MCMIS snapshot date)													
Inspection Summary													
Driver Summary				Vehicle Summary				Hazmat Summary					
Driver Inspections:		6	Vehicle Inspections:		2	Hazmat Inspections		0					
Driver Out-of-service Inspections:		0	Vehicle Out-of-service Inspections:		1	Hazmat Out-of-service Inspections:		0					
Driver Out-of-service Rate:		0%	Vehicle Out-of-service Rate:		50%	Hazmat Out-of-service Rate:		0%					
Inspection Details													
Carrier Info				Driver Info				Inspection Info					
	Date	DOT #	Carrier Name	Driver Name	Driver Lic	State	Driver DOB	Rpt St	Report Number	Hazmat Insp	Insp Level	# of Viol	
1	09/20/2022	3001683	ARTIRA TRANSPORTATION INC	TAYLOR, LETERRENCE	801212776	MS	07/10/1989	WV	4715000906	N	2	1	
Vehicle Violation:		393.75(a)(3)		TIRE-FLAT AND/OR AUDIBLE AIR LEAK				OOS					

Report executed at: 5/2/2025 1:07:30 PM

MCMIS snapshot date: 04/25/2025

For an explanation of FMCSA-reportable crashes see: <https://www.psp.fmcsa.dot.gov/psp/?redirectUrl=FAQ>

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.

2	10/25/2022	3001683	ARTIRA TRANSPOTATION INC	TAYLOR, LETERRENCE	801212776	MS	07/10/1989	WA	W439000286	N	2	1
Driver Violation: 392.2 FAILURE TO OBEY TRAFFIC CONTROL DEVICE NON-OOS												
3	12/07/2022	2075148	ASAP TRANS CORP	TAYLOR, LETERRENCE	801212776	MS	07/10/1989	KY	0S14501388	N	3	0
4	01/06/2023	2075148	ASAP TRANS CORP	TAYLOR, LETERRENCE	801212776	MS	07/10/1989	WV	4747001095	N	3	1
Driver Violation: 392.2 FAILURE TO OBEY TRAFFIC CONTROL DEVICE NON-OOS												
5	05/14/2024	2908503	DHESI HOT SHOT INC	TAYLOR, LETERRENCE	801212776	MS	07/10/1989	NE	T390001125	N	3	2
Vehicle Violation: 392.2 STATE VEHICLE REGISTRATION OR LICENSE PLATE VIOLATION NON-OOS												
Vehicle Violation: 396.17(c) OPERATING A CMV WITHOUT PROOF OF A PERIODIC INSPECTION NON-OOS												
6	09/17/2024	2908503	DHESI HOT SHOT INC	TAYLOR, LETERRENCE	801212776	MS	07/10/1989	AL	RHCV002755	N	3	0
Violation Summary												
Violation #	Description								# of Violations	# of Out-of-service Violations		
392.2	FAILURE TO OBEY TRAFFIC CONTROL DEVICE								3	0		
396.17(c)	OPERATING A CMV WITHOUT PROOF OF A PERIODIC INSPECTION								1	0		
393.75(a)(3)	TIRE-FLAT AND/OR AUDIBLE AIR LEAK								1	1		

The summary counts and rates only include violations that were attributable to TAYLOR, LETERRENCE.

Report executed at: 5/2/2025 1:07:30 PM

MCMIS snapshot date: 04/25/2025

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.

For an explanation of FMCSA-reportable crashes see: <https://www.psp.fmcsa.dot.gov/psp/?redirectUrl=FAQ>