PSP Detailed Report

Federal Motor Carrier Safety Administration

						Driv	er In	form	nation											
Last Name First Nam					irst Name			License #						State						
TURNER REGINALD					D				38556522					ТХ						
				•		C	rash	Acti	ivity				I							
Crash	Summary (C	rashes liste	ed represent a	a driver's inv	olveme	nt in FMCSA-reportable	e cras	hes,	without a	ny dete	rminati	on as to	o resp	onsibil	ity.)					
# of Crashes: 0						# of Crashes with Fat	alities:	0			# of Crashes with Injuries: 0 # of Towaw						ways:	0		
				0		# of Fat	alities:	0					# of In	ijuries:	0		# of Haz	mat Rele	eases:	0
Crast	Details (Cra	shes listed	represent a d	river's involv	ement i	in FMCSA-reportable c	rashes	s, wi	ithout any	determ	ination	as to re	espon	sibility	.)					
	Date	DOT #	Carri	er Name		Driver Name		Drive	er Lic	State	Driver	DOB F	Rpt St	Report	Number	Locatio	n #Fata	alities #	‡ of Inju	uries
					Inspe	ction Activity (3 year	r histe	ory	from MC	MIS sr	apsho	t date)								
Inspe	Inspection Summary																			
	Driver Summary Vehicle Summary Hazmat Summary																			
Driver Inspections:					2	Vehicle Inspections:		1					Hazmat Inspections						1	
Driver	Out-of-service	Inspections:			0	Vehicle Out-of-service In	spection	ons:				1 Hazr	mat Ou	t-of-ser	vice Insp	ections:				0
Driver Out-of-service Rate:					0%	Vehicle Out-of-service Ra	100% Hazr					Hazmat Out-of-service Rate:							0%	
Inspe	ction Details																			
Carrier Info					Driver Info							I	Inspection Info							
	Date DOT # Car		Carri	er Name		Driver Name		Driver Lic		ic	State Drive		DOB Rpt St Report		Number	Hazmat Insp	Insp Le		# of Viol	
1	09/05/2022	76600	QUALITY	CARRIERS	,						07/28/1	978	ТΧ	6E3B	DXNRCJ	Y	2		3	
	Vehicle	Vehicle Violation: 107.620(b) NO COPY OF US DOT HAZARDOUS MATERIALS NON-OOS REGISTRATION NUMBER																		
	Vehicle	Violation:	393.75(a)(3)	TIR	E-FLAT A	ND/OR AUDIBLE AIR LEAF	<				0	OS								
	Vehicle	Violation:	393.75(c)		TIRE-OTHER TREAD DEPTH LESS THAN 2/32 OF INCH NON-OOS MEASURED IN A MAJOR TREAD GROOVE NON-OOS															

Report executed at: 5/26/2025 12:06:02 PM

MCMIS snapshot date: 04/25/2025

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.

2	12/29/2022		REGINALD VANN	VANN, REGINALD	38556522	ТХ	07/28/1978	IN	9210000407	N	3	1	
	Driver Violation: 392.2 STATE/LOCAL LAWS - SPEEDING 6-10 MILES PER HOUR OVER NON-OOS												
Violati	Violation Summary												
Vi	Violation # Description										# of Out-of-service Violations		
392.2		STATE/LOCA		1		0							
107.620	(b)	NO COPY OF US DOT HAZARDOUS MATERIALS REGISTRATION NUMBER								1		0	
393.75(a)(3)	TIRE-FLAT AND/OR AUDIBLE AIR LEAK								1		1	
393.75(c)	TIRE-OTHER TREAD DEPTH LESS THAN 2/32 OF INCH MEASURED IN A MAJOR TREAD GROOVE								1		0	

The summary counts and rates only include violations that were attributable to TURNER, REGINALD.

Report executed at: 5/26/2025 12:06:02 PM MCMIS snapshot date: 04/25/2025

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.