

PSP Detailed Report

Federal Motor Carrier Safety Administration

Driver Information															
Last Name		First Name		License #			State								
CASTRO		JOSE		C22613672			KY								
Crash Activity															
Crash Summary (Crashes listed represent a driver's involvement in FMCSA-reportable crashes, without any determination as to responsibility.)															
# of Crashes:		0		# of Crashes with Fatalities:		0		# of Crashes with Injuries:		0		# of Towaways:		0	
# Not preventable:		0		# of Fatalities:		0		# of Injuries:		0		# of Hazmat Releases:		0	
Crash Details (Crashes listed represent a driver's involvement in FMCSA-reportable crashes, without any determination as to responsibility.)															
	Date	DOT #	Carrier Name	Driver Name	Driver Lic	State	Driver DOB	Rpt St	Report Number	Location	# Fatalities	# of Injuries			
Inspection Activity (3 year history from MCMIS snapshot date)															
Inspection Summary															
Driver Summary				Vehicle Summary				Hazmat Summary							
Driver Inspections:		2		Vehicle Inspections:		1		Hazmat Inspections				0			
Driver Out-of-service Inspections:		0		Vehicle Out-of-service Inspections:		0		Hazmat Out-of-service Inspections:				0			
Driver Out-of-service Rate:		0%		Vehicle Out-of-service Rate:		0%		Hazmat Out-of-service Rate:				0%			
Inspection Details															
Carrier Info				Driver Info				Inspection Info							
	Date	DOT #	Carrier Name	Driver Name	Driver Lic	State	Driver DOB	Rpt St	Report Number	Hazmat Insp	Insp Level	# of Viol			
1	03/01/2023	3842554	CARDONA'S LOGISTICS MP LLC	CASTRO, JOSE	C22613672	KY	10/20/1980	TN	TFEY000088	N	1	1			
Vehicle Violation:		393.47(d)		ALL BRAKES - INSUFFICIENT BRAKE LINING THICKNESS			NON-OOS								

Report executed at: 5/30/2025 11:09:48 AM

MCMIS snapshot date: 04/25/2025

For an explanation of FMCSA-reportable crashes see: <https://www.psp.fmcsa.dot.gov/psp/?redirectUrl=FAQ>

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.

2	11/30/2023	2841686	AYALA TRANSPORT LLC	CASTRO, JOSE	C22613672	KY	10/20/1980	IL	4069010606	N	3	0
Violation Summary												
Violation #	Description								# of Violations	# of Out-of-service Violations		
393.47(d)	ALL BRAKES - INSUFFICIENT BRAKE LINING THICKNESS								1	0		

The summary counts and rates only include violations that were attributable to CASTRO, JOSE.

Report executed at: 5/30/2025 11:09:48 AM

MCMIS snapshot date: 04/25/2025

For an explanation of FMCSA-reportable crashes see: <https://www.psp.fmcsa.dot.gov/psp/?redirectUrl=FAQ>

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.